

Project Name:

Kirkpatrick Dam

Owner:

Department of

Environmental Protection

Mead & Hunt

Marty Kemps, PE (FL)

Representatives: Jim Botz, PE

Date:

August 2 and 3, 2021

The following findings are a summary of Mead & Hunt's inspection. Detailed information regarding the inspection will be provided in the inspection report which will also contain the requested Condition Assessment, recommendations, additional photos, final dive report, and repair / maintenance information.

Dive Inspection

Volkert, Inc. performed a dive inspection of the project on August 2 and 3, 2021. The following is a summary of their findings.

- A. No significant areas of deterioration were noted by the divers that require immediate repairs.
- B. Wood debris was present along the upstream side of the spillway. As a result, the divers were unable to inspect the upstream face of the ogee and upstream apron.
- C. The downstream apron was undermined with approximately 18-inches of the downstream sheet piling cut-off wall exposed. Material has also eroded beneath the apron, through the pick-holes located throughout the sheet pile cut-off wall.
- D. The debris barrier cables and connecting hardware below the waterline are no longer supported by the timber pile clusters.
- E. Hardware securing the gate seals are corroded.

Inspection

The following is a summary of the observations made by Mead & Hunt during our inspection.

Spillway


- A. No immediate dam safety concerns with regards to the spillway were observed during the inspection.
- B. With the debris barrier system in dis-repair, heavy woody debris exists immediately upstream of the spillway. This debris significantly reduces the discharge capacity of the spillway.

- C. The walking path over the culverts that collect seepage from the left¹ along the left side, downstream side of the spillway is undermined. Although not a dam safety concern, if this undermined section settles, it would be a tripping hazard.
- D. Gate seals leak.
- E. The support frame of the hydraulic cylinders, gates, and connecting hardware for the gates contained areas of rust with slight to moderate corroding.


Embankments

- A. No sinkholes, low spots, or signs of slope instability were observed at both the left and right embankments. The embankments were well vegetated and maintained.
- B. Minor rutting and bare spots were observed at select, small areas along the embankments.
- C. Some palm trees were noted at the toe of the embankment which will require removal.
- D. Each embankment contained seepage along the downstream toe. This seepage is collected in a trench and discharged to the river.


¹ The project structures are referred to in this memo as left and right looking downstream.




Photograph No. 1: View of downstream end of spillway




Photograph No.2: Spillway piers




Photograph No. 3: Diver inspecting Gate 1



Photograph No. 4: Debris upstream of gates



Photograph No. 5: Corrosion of gate hoist supports



Photograph No. 6: Downstream view of gate



Photograph No. 7: Upstream slope of left embankment




Photograph No.8: Downstream slope of left embankment



Photograph No. 9: Upstream slope of right embankment



Photograph No. 10: Downstream slope of right embankment



2021 Inspection Report

Kirkpatrick Dam

Ocklawaha River Putman County, Florida

Report prepared for

Florida Department of Environmental Protection #

Report prepared by



November 2021



This item has been digitally signed and sealed by Martin Kemps, PE on 11/10/2021.

Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.

Table of Contents

				Page
1.	Gene	eral		1
2.	Proje	ect Des	cription	1
3.	Field	Inspec	tion	2
	3.1	Field I	nspection Observations	3
		3.1.1	Spillway	3
		3.1.2	Left Embankment	5
		3.1.3	Right Embankment	6
4.	Surv	eillance	and Monitoring	6
5.	Opin	ion of F	Probable Cost and Timeline	7
6.	Drawdown Impacts			9
7.	References10			10

Appendices

- A Project Drawings
- B Photographs
- C Dive Inspection Report
- D Condition Assessment Report For Florida Dams and Impoundments

1. General

The Kirkpatrick Dam (Project) is owned, operated, and maintained by the Florida Department of Environmental Protection (FDEP). Mead & Hunt, Inc. (Mead & Hunt) performed the inspection of the Kirkpatrick Dam on August 2 and 3, 2021. A dive inspection was also performed as part of the inspection on August 2 and 3, 2021. This report provides a summary of the inspection and recommendations for long-term monitoring along with a cost estimate for repairs.

The conclusions and recommendations herein are based on the engineer's opinion and are made independently of the FDEP, its employees, and its representatives. The conclusions regarding the condition and safety of the dam and related facilities are not guaranteed but do represent our best judgment.

This report was prepared by Martin Kemps, PE and reviewed by Jim Botz, PE.

2. Project Description

The Kirkpatrick Dam was designed by the U.S. Army Corps of Engineers (USACE) as part of the Cross Florida Barge Canal system. The dam is currently listed as "Low Hazard Potential" in the National Inventory of Dams (FL00156), meaning failure of mis-operation results in no probable loss of human life and low economic and/or environmental losses.

The Kirkpatrick Dam consists of three primary water-retaining structures – a left embankment¹, a vertical lift gate spillway, and a right embankment. The embankments are homogenous and consist of clean sand, silty sand, and clayey sand. The crest is 30 feet wide with a top elevation of 28.0. The downstream section consists of 4(H):1(V) downstream slopes. The downstream slopes contain a rip rap revetment to elevation² 19.3 which is underlain by a two-stage filter system. The upstream slopes consist of 4(H):1(V) slopes to elevation 25.0, 10(H):1(V) slopes to elevation 13.0, and a 3(H):1(V) slope that ties back into the existing ground surface.

The spillway consists of a reinforced ogee weir with a top elevation of 6.0 and four vertical lift gates (numbered from 1 – 4, from left to right). The upstream cut-off consists of reinforced concrete to elevation -21.0 with a steel sheetpile extending down to elevation -35.0. Four 15-foot-high by 40-foot-wide vertical lift gates which are operated with hydraulic rams that are situated on an overhead operating platform. The forebay and tailrace walls consist of sheetpile with a whaler. The forebay walls extend down to elevation -15.5 to -33.5, with a top elevation ranging from elevation 28.0 to 8.9. The tailrace walls extend to a bottom elevation -20.5 to -31.0 with a top elevation 16.0 to 0.5. The downstream apron consists of a 30-inch-thick reinforced concrete slab supported by timber pile, with a sheet pile cut-off wall at the downstream end.

Upstream of the spillway there is a debris barrier system which consists of cables supported by 17 timber dolphins. A concrete walking path which crosses the culverts that collect seepage from the left embankment is located along the left side of the spillway. Rodman Road crosses over the concrete weir, downstream of the spillway gates. Select project drawings of the Project for reference are included in Appendix A.

1

¹ Left and right are referred to in this report relative to an observer facing downstream.

² Elevations in this report are referenced to NGVD 29.

3. Field Inspection

The field inspection of the Project was performed on August 2 and 3, 2021. The following individuals participated in the visual inspection:

John DeHoff – FDEP
Jim Botz, PE – Mead & Hunt, Inc.
Marty Kemps, PE – Mead & Hunt, Inc.

At the time of the inspection, the weather was overcast to heavy rains with temperature of 75°F to 86°F. The reservoir was at approximate elevation 19.6. The conditions allowed for a visual assessment of all the Project's water-retaining structures. No condition that requires immediate action were noted during the field inspection.

Visual observations of the Project's water-retaining structures were made during the field inspection to note the following conditions:

- · Cracking of concrete
- Deterioration of concrete
- Joint movement or offsets
- Misalignment
- Movement
- Settlement
- Excessive debris

- Deformation of gate members
- Leakage
- Seepage
- Erosion
- Debris
- Instrumentation
- Offsets

The field inspection started along the spillway, then along the crest and upstream slope of the left embankment and back across the downstream slope. The spillway was inspected from the roadway downstream, followed by the crest and downstream slope of the right embankment and back across the upstream slope of the right embankment. Photographs taken during the inspection and referenced below can be found in Appendix B.

An underwater dive inspection was performed by Volkert, Inc. (Volkert) on August 2 and 3, 2021. A copy of the underwater inspection report can be found in Appendix C.

The condition of Project components was evaluated relative to the following definitions.

Excellent Appearance is essentially equivalent to post-construction condition. Feature or system

functions as intended and without problems. Maintenance needs are less than or

equivalent to design intent.

Good Appearance has minor deterioration such as concrete shrinkage cracks or damage to

coatings over less than 5 percent of area, which would be expected for a structure or system of similar age and exposure. Feature or system reliably functions as intended.

Maintenance needs are essentially equivalent to design intent.

Fair

Appearance has deterioration such as concrete cracking, spalling, joint offsets, or metal corrosion over more than 25 percent of area, which is indicative of age, weathering, or wear. Feature or system accommodates design loadings and functions as intended; however, operation may periodically require minor manipulation. Maintenance needs are evident and likely greater than design intent.

Poor

Appearance has significant deterioration that could be indicative of reduced structural integrity and ability to accommodate design loadings. Feature or system often does not function as intended and requires repair or replacement. Maintenance needs are frequent and far exceed the design intent.

Unsatisfactory The feature or system is no longer able to perform its function as intended and poses a threat to the safe operation of the facility. Immediate attention is required to remedy the condition.

A Condition Assessment Report For Florida Dams and Impoundments form was also completed and is included in Appendix D.

3.1 **Field Inspection Observations**

Spillway

The spillway appeared in good condition overall. Debris consisting of logs and vegetation were located upstream of the spillway (see Photograph Nos. 1, 2, and 3). These logs extended to the bottom of the reservoir and prevented the divers from inspecting the upstream portion of the ogee below elevation 4.0, manatee barrier at Gate Nos. 1-3, and the entire left forebay wall. The divers noted minor spalling (1/2-inch deep) with no exposed rebar along the upstream side of the concrete weir where visible.

The upstream debris (boat) barrier is in disrepair with failed cables and connecting hardware. The anchor piles themselves appeared to be in relatively good condition. This debris could clog the spillway bays reducing the discharge capacity of the Project. If discharge capacity is restricted, the reservoir could surcharge and overtop the embankments during a heavy rain event. In addition the logs may prevent the vertical lift gates from opening or closing as intended. It is recommended that the debris in front of the spillway be removed to maintain discharge capacity and ensure proper gate operation.

2021-REC-1 Remove the logs, vegetation, and other debris from in front of the spillway by July 2022.

2021-REC-2 Revise the upstream debris barrier design and repair barrier so that logs do not accumulate in front of the gates by December 2023.

Some light spalling (see Photograph No. 4) was noted on the right side of the left pier at Gate No. 1. A vertical crack with spalling (see Photograph No. 5) was also noted along the right side of the left pier at Gate No. 1. These spalls appear to be the same size when compared to the 2015 and 2019 inspection reports. The divers noted some light spalling along the upstream side of the concrete weir where visible.

The upstream sheetpile forebay walls had light surface rust on the pile caps but appeared to be straight, with no signs of buckling and in good condition (see Photograph Nos. 6 and 7). Where the divers could access the upstream forebay walls, only light corrosion was noted.

The concrete operating platform where the hoists for the gates are located, the concrete was in good condition (see Photograph Nos. 8 and 9) with hairline cracks. Rust and corrosion were noted on the frames that support the hydraulic cylinders Nos. 2 through 4 (see Photograph Nos. 10 and 11). The housing for the hydraulic cylinders also contained rust (see Photograph No. 12), with the exception of the hydraulic operating system for Gate No. 1, which was replaced in 2019.

2021-REC-3 The hydraulic cylinders and support framing for Gate Nos. 2-4 should be cleaned (sandblasted) and re-coated by end of December 2023 to extend service life.

The vertical lift gates appeared to be in fair condition. The horizontal structural members collect debris and water which increases the rate of corrosion (see Photograph No. 13). Vegetation was also observed to be growing from within the horizontal members (see Photograph No. 14). To document the amount of corrosion and overall condition of the gates, a detailed, hands-on inspection which includes climbing the gates along with taking thickness measurements should be performed and the results reviewed by a qualified hydraulic steel structural engineer.

2021-REC-4 Debris and vegetation should be removed from the horizontal members of the gates along with cleaning of the gate members so a detailed, hands-on inspection of the gates can be performed, including taking thickness measurements of gate members. The findings should be reviewed by a qualified hydraulic steel structural engineer by December 2023.

Each of the gates are operated by its own electrically driven hydraulic ram operating system. A standby generator is available to operate the gates and is tested at least yearly by a vendor.

The downstream sheetpile tailrace walls had light surface rust on the pile caps but appeared to be straight, no signs of buckling and in good condition (see Photograph Nos. 15 and 16). The divers also only noted light corrosion below the waterline. The sealant was missing along the vertical construction joint at the concrete abutment walls. The divers could see a PVC waterstop located between the joints, which the plans also show. Since the joint isn't subject to freeze-thaw conditions and there is a waterstop present, no action is required other than continue routine inspections for deteriorating joint conditions.

The downstream portion of the concrete ogee weir was in good condition, with minor scaling of the concrete. The downstream apron continued to show some undermining (**Figure 1**) beneath the downstream edge but has not changed significantly when compared to the 2015 readings. The undermining extended a distance of 3'-8" upstream beyond the sheet piling and a maximum of 27-inches beneath the concrete, downstream of the sheet piling.



Figure 1. Location of undermining

2021-REC-5 The void beneath the downstream edge of the apron should be grouted and rip rap placed to prevent future undermining by the end of 2024.

3.1.2 Left Embankment

Overall the left embankment was in good condition. No signs of settlement, slope instability, cracking or wet areas were observed. No cracks or depressions were observed along the crest which consists of asphaltic concrete. The upstream and downstream slopes had adequate cover of grass (see Photograph Nos. 17 and 18) with the exception of a relatively small section located just above the rip rap (see Photograph No. 19) which had only sparse vegetation. Overall the grass was well-maintained. The rip rap along the upstream slope along the edge of the reservoir had adequate cover and was in excellent condition. A small palm tree was growing near the rip rap along the upstream slope which should be removed (see Photograph No. 20).

2021-REC-6 The palm tree located along the rip rap of the upstream slope of the left embankment should be removed by July 2022.

Seepage was observed within the rip rap revetment along the downstream toe. Heavy vegetation (see Photograph No. 21) was noted along the upstream slope of revetment. The downstream slope of the revetment did not contain heavy vegetation. This heavy vegetation should be killed or removed to allow seepage water to flow more freely and to improve visibility of the ditch for inspections.

2021-REC-7 The heavy vegetation along the downstream revetment of the left embankment that collects seepage should be killed or removed by July 2022.

Although not a dam safety concern, the concrete walking path over the culverts that collect seepage from the left embankment is undermined, which if settles, could be a tripping hazard. The grouted rip rap slopes adjacent to the spillway tailrace walls appeared in good condition (see Photograph No. 22). We understand that the hollow areas beneath the rip rap that were identified in the 2019 GPI Inspection Report have not been repaired. The grout cover is still intact and has not cracked or settled into the underlying voids.

3.1.3 Right Embankment

Overall the right embankment was in good condition. No signs of settlement, slope instability, cracking or wet areas were observed. No cracks or depressions were observed along the crest which consists of asphaltic concrete. The rip rap along the upstream slope along the edge of the reservoir had adequate cover and was in good condition. The upstream and downstream slopes had adequate cover of grass (see Photograph Nos. 23 and 24). Heavier vegetation was located on the downstream slope by the spillway (Photograph No. 25). We understand that this vegetation has grown this year and will be cut during the FDEP's annual maintenance activities. Heavy vegetation and a small palm tree were growing in the rip rap along the downstream of the rip rap revetment which should be removed (see Photograph No. 26).

2021-REC-8 The palm tree along with the heavy vegetation located along the upstream side of the rip rap revetment on the right embankment should be removed by July 2022.

The rip rap along both the upstream slope and downstream revetment had adequate cover and was in excellent condition. Seepage was observed within the rip rap revetment along the downstream toe which flows into the Ocklawaha River.

4. Surveillance and Monitoring

The only monitoring currently performed is from operator observations during weekly site visits and viewing staff gages to monitor headwater and tailwater elevations. The Project currently does not have any active instrumentation such as monitoring wells, piezometers, survey control points, or seepage monitoring systems.

Since the Project is low-hazard and is in fairly good condition, the only recommendation we have regarding instrumentation is to monitor survey control points on the spillway piers. Permanent benchmarks not located on the spillway would need to be installed along with control points on each of the four piers. Readings should be taken annually for the first three years to establish a baseline, then every five years. The data should be plotted and reviewed after each survey to determine if any movement or adverse trends are developing that would compromise the safety of the dam.

2021-REC-9 Establish an elevation and alignment survey program for the spillway piers. Take readings yearly for three years, then every five years. The data should be plotted and reviewed after each survey for excessive movement or any spurious trends that may be developing. The first baseline survey should be completed by December 2022.

5. Opinion of Probable Cost and Timeline

The cost estimate is considered a Class 4 estimate based upon the Association for the Advancement of Cost Engineering (AACE) International Cost Estimate Classification System – As Applied in Engineering, Procurement, and Construction for the Hydropower Industry. A summary of the Class 5 estimate is shown in Table 5-1 for reference:

Table 5-1. AACE Cost Estimate Matrix

COST ESTIMATE CLASSIFICATION MATRIX FOR THE HYDROPOWER INDUSTRY

	Primary Characteristic	Secondary Characteristic			
ESTIMATE CLASS	MATURITY LEVEL OF PROJECT DEFINITION DELIVERABLES I xpressed as 5 of complete definition	END USAGE Typical purpose of Cylinate	METHODOLOGY type at estin ating method	EXPECTED ACCURACY RANGE Typical variation in low and high ranges ¹⁵	
Class 5	0% to 2%	Concept screening	Capacity factored, parametric models, judgment, or analogy		
Class 4	1% to 15%	Study or feasibility	Equipment factored or parametric models	L: -15% to -30% H: +20% to +50%	
Closs 3	10% to 40%	Budget authorization or control	Semi-detailed unit costs with assembly level line items	L: -10% to -20% H: +10% to +30%	
Class 2	30% to 75%	Control or bid/tender	Detailed unit cost with forced detailed take-off	L: -5% to -15% H: +5% to +20%	
Class 1	65% to 100%	Check estimate or bid/tender	Detailed unit cost with detailed take-of!	L: -3% to -10% H: +3% to +15%	

Notes: [a] The state of technology, availability of applicable reference cost data, and many other risks affect the range markedly. The +/ value represents typical percentage variation of artifal costs from the cost estimate after application or contingency (typically at a 50% level of confidence) for given scope.

The following table is a summary of costs with regards to Mead & Hunt's 2021 recommendations with a 20-30% contingency included.

Table 5-2. Maintenance, Cost, and Timeline Estimation

KIRKPATRICK MAINTENANCE AND REPAIR ITEMS				
Mead & Hunt's 2021 Inspection Report				
Recommendation	Estimated Cost*	Recommended Completion Date	Remarks	
Remove the logs, vegetation, and other debris from in front of the spillway, (2021-REC-1)	\$280,000	July 2023	Includes 20% contingency Assumes reservoir drawndown to elevation 6.0 Assumes disposal at nearby original borrow pit for dam	
Revise the upstream debris barrier design and repair barrier so that logs do not accumulate in front of the gates. (2021-REC-2)	\$635,000	December 2022	Includes 20% contingency Assumes reservoir drawndown to elevation 6.0 Repair will utilize existing pile clusters Includes engineering	

The hydraulic cylinders and support framing for Gate Nos. 2-4 should be cleaned (sandblasted) and re-coated. (2021-REC-3)	\$160,000	July 2023	 Assumes re-coating in-place with on-site containment Zinc primer, epoxy intermediate, and polyurethane topcoat
Debris and vegetation should be removed from the horizontal members of the gates along with cleaning of the gate members so a detailed, hands-on inspection of the gates can be performed, including taking thickness measurements of gate members. The findings should be reviewed by a qualified hydraulic steel structural engineer by December 2023. (2021-REC-4)	\$38,000	December 2023	 Inspection includes physically climbing the gates Includes engineering review
The void beneath the downstream edge of the apron should be grouted and rip rap placed to prevent future undermining. (2021-REC-5)	\$220,000	December 2024	Assumes grout pumped from land Barge to place rip rap Includes engineering
The palm tree located along the rip rap of the upstream slope of the left embankment should be removed. (2021-REC-6 and 2021-REC-8)	N/A	July 2022	Assumes trees will be removed by operating personnel
The heavy vegetation along the downstream revetment of the left embankment that collects seepage should be killed or removed by July 2022. (2021-REC-7)	\$5,000	July 2022	Assumes about a half-acre of clearing
Establish an elevation and alignment survey for the spillway piers. Take readings yearly for three years, then every five years. The data should be plotted and reviewed after each survey for excessive movement or any spurious trends that may be developing. (2021-REC-7)	\$4,000 initial survey / \$1,400 per year afterwards	Begin December 2022	Assumes operators review yearly data

^{*} Information presented on this sheet represents our opinion of probable project costs in 2021 dollars and is based upon limited engineering. Unit and lump sum prices are based on costs for similar projects, discussions with contractors, vendor quotes, FDOT, engineering judgement, and/or published data. Actual bids and total project cost will vary based on contractor's perceived risk, site access, market conditions, availability of materials, etc. No warranties concerning the accuracy of costs presented herein are expressed or implied.

Besides the maintained and repaired items mentioned above in Table 4-2, GPI also recommended in their 2019 inspection report that the gate seals and the rip rap slopes adjacent to the spillway be grouted to fill voids. The prices (in 2019 dollars) appear reasonable but need to account for inflation of about 2-3% per year. We recommend that these additional items be completed by December 2023.

The estimated schedules to perform repairs assumes the conditions described do not become significantly worse. If operators observe these areas becoming significantly more deteriorated, a qualified consultant should be notified to discuss a revised timeline of repair / maintenance items.

6. Drawdown Impacts

We understand the FDEP is considering lowering the reservoir pool from the normal elevation of 20.0 feet. The reservoir elevations which are being considered are elevation 18.0, 16.0, and 14.0 feet NGVD 29. The following is a summary of the recommendations provided in Section 4.0 with commentary if the reservoir levels are permanently lowered.

Table 5-1. Drawdown vs Impact on Repairs


Table 5-1. Drawdown vs impact on Repairs			
KIRKPATRICK MAINTENANCE AND REPAIR ITEMS VS LOWERED HEADWATER ELEVATION			
RECOMMENDATION	IMPACT OF LOWERED RESERVOIR POOL		
Remove the logs, vegetation, and other debris from in front of the spillway. (2021-REC-1)	Upstream debris would be able to clog the spillway bays reducing the discharge capacity of the Project, regardless of pool level. If discharge capacity is restricted, the reservoir could surcharge and overtop the embankments during a heavy rain event. The large logs may also prevent the vertical lift gates from opening or closing as intended. The debris should be removed in front of the spillway as discussed in Section 4 regardless of the reservoir elevation.		
Revise the upstream debris barrier design and repair barrier so that logs do not accumulate in front of the gates, (2021-REC-2)	To prevent debris from accumulating and reducing spillway capacity along with interfering with gate operations, the upstream debris barrier should be repaired with the schedule discussed in Section 4 regardless of reservation elevation.		
The hydraulic cylinders and support framing for Gate Nos. 2-4 should be cleaned (sandblasted) and re-coated. (2021-REC-3)	The gates would need to continue to operate regardless of pool level. To prolong the useful life of the gate operating system, the framing and cylinders should be re-coated as recommended in Section 4.		
Debris and vegetation should be removed from the horizontal members of the gates along with cleaning of the gate members so a detailed, hands-on inspection of the gates can be performed, including taking thickness measurements of gate members. The findings should be reviewed by a qualified hydraulic steel structural engineer by December 2023. (2021-REC-4)	The gates would need to continue to operate regardless of pool level. To help provide long-term reliability the gate should be cleaned and inspected per the schedule discussed in Section 4.		
The void beneath the downstream edge of the apron should be grouted and rip rap placed to prevent future undermining. (2021-REC-5)	If the pool is lowered, discharge through the gates would still be required, at any pool level. To prevent the downstream apron from undermining, the schedule to repair the apron discussed in Section 4 would need to be maintained.		


KIRKPATRICK MAINTENANCE AND REPAIR ITEMS VS LOWERED HEADWATER ELEVATION		
RECOMMENDATION	IMPACT OF LOWERED RESERVOIR POOL	
The palm tree located along the rip rap of the upstream slope of the left embankment should be removed. (2021-REC-6 and 2021-REC-8)	The palm trees should be removed per the schedule discussed in Section 4 to reduce seepage paths that may be created by the root system, regardless of pool level elevation.	
The heavy vegetation along the downstream revetment of the left embankment that collects seepage should be killed or removed by July 2022. (2021-REC-7)	To maintain flow and to allow for visual inspections regardless of pool level, the vegetation along the left downstream revetment should be removed per the schedule discussed in Section 4.	
Establish an elevation and alignment survey for the spillway piers. Take readings yearly for three years, then every five years. The data should be plotted and reviewed after each survey for excessive movement or any spurious trends that may be developing. (2021-REC-7)	The recommendation to survey the spillway piers could be removed if the pool was lowered to elevation 18 or lower. The likelihood of the structure moving with a reduced hydrostatic loading condition is low.	

7. References


- AACE International Recommended Practice No. 69R-12, Cost Estimate Classification System As Applied in Engineering, Procurement, and Construction for the Hydropower Industry, January 25, 2013.
- Amec Foster Wheeler Environmental & Infrastructure, Inc., Kirkpatrick Dam & Buckman Lock Geotechnical Inspection Report, July 2017.
- Greenman-Pedersen, Inc., Report of Findings Inspection of Kirkpatrick Dam, October 2019.
- U.S. Army Engineer District, Jacksonville Corps of Engineers, *Cross Florida Barge Canal Plans Rodman Dam and Spillway*, January 1966.
- URS Corporation Southern, Kirkpatrick Dam and Spillway Condition Assessment, September 2015.

Appendix A. Project Drawings






Appendix B. Photographs




Photograph 1 – Upstream vegetation and logs looking left




Photograph 2 – Up-close view of log debris




Photograph 3 - Debris immediately upstream of gate




Photograph 4 – Light spalling at left pier of Gate No. 1




Photograph 5 - Vertical spalling at left pier of Gate No. 1




Photograph 6 - Left forebay wall




Photograph 7 - Right forebay wall




Photograph 8 - View of operating platform looking northwest




Photograph 9 - View of operating platform looking southeast




Photograph 10 - Rust and corrosion on framing that supports the hydraulic cylinders




Photograph 11 - Rust and corrosion on top of framing that supports the hydraulic cylinders




Photograph 12 - Rust on hydraulic cylinder housing




Photograph 13 - Typical vertical lift gate with corrosion along horizontal members



Photograph 14 – Vegetation growing in vertical structural members



Photograph 15 - Left tailrace wall



Photograph 16 - Hairline cracks and efflorescence on tainter gate piers



Photograph 17 - Upstream face of left embankment



Photograph 18 - Downstream face of left embankment




Photograph 19 - Sparse vegetation along upstream slope of left embankment



Photograph 20 – Palm tree on upstream slope that should be removed



Photograph 21 – Heavy vegetation along the rip rap revetment of the left embankment



Photograph 22 - Grouted rip rap along the downstream side of the left embankment, adjacent to spillway



Photograph 23 – Upstream slope of right embankment



Photograph 24 – Downstream slope of right embankment



Photograph 25 - Vegetation along the downstream side of the right embankment



Photograph 26 - Palm tree located on the downstream slope of the right embankment

Appendix C. Dive Inspection Report

Underwater Inspection Report

TAYLOR ENGINEERING, INC.

NBI Structure ID. (8): Kirkpatrick Dam

Underwater Date (93): 08/02/21 and 08/03/21

Structure/Roadway Identification:

District (2):

County (3):

Feature Intersected (6):

Facility Carried (7):

Putnam N/A

Kirkpatrick Dam

Underwater Inspection Details: Special Crew Hours:

Max. Depth:

Signature:

Type of Dive Insp.:

Level II (SCUBA)

Type of Boat Used: N/A

Water Type/Marine Growth:

Fresh - Algae

Inspection Personnel:

Field Personnel: Hoogland, Keith S. Title SUCBI P.E./C.B.I. No.:

00341/Lead

Duty: Dive

Mauer, Jarred M.

AUBI

Dive

Marston, Douglas W.

AUBIT

Tend

SCOPE:

Divers inspected the spillway upstream and downstream, retaining walls, abutments, piers and gates upstream, stilling basin and wingwalls downstream including connections and joints in the walls and floor.

CONTROL STRUCTURE:

Weir

Upstream

The concrete surfaces have typical scale (loss of aggregate) up to 1/2in. deep, with no exposed rebar.

Downstream

The concrete surfaces have typical scale (loss of matrix) up to 1-1/2in. deep, with no exposed rebar-

East Abutment (including joints)

There is typical scale (loss of aggregate) up to 1/4in. deep, with no exposed rebar.

Downstream

There is typical scale (loss of matrix) up to 1/2in. deep, with no exposed rebar.

Piers 1 through 3

Upstream

There is typical scale (loss of aggregate) up to 1/2in. deep, with no exposed rebar.

Downstream

There is typical scale (loss of matrix) up to 1/2in. deep, with no exposed rebar.

Structure ID: Kirkpatrick Dam

District: 03 Inspection Date: 08/02/21

CONTROL STRUCTURE (CONTINUED):

West Abutment (including joints)

Upstream

There is typical scale (loss of aggregate) up to 1/4in. deep, with no exposed rebar.

Downstream

There is typical scale (loss of matrix) up to 1/4in. deep, with no exposed rebar.

STILLING BASIN:

West Stilling Abutment

Both joints (walls) are missing joint sealant and can be probed 8in. to water stop, with no leakage.

East Stilling Abutment

Both joints (walls) are missing joint sealant and can be probed 8in. to water stop, with no leakage.

Downstream Apron

Along the end sill, starting 15ft. from the east end, the downstream apron floor is undercut, 100ft. L x 27in. H, extending back 12in. to 18in. to a steel sheet pile wall. There are fifteen lifting holes in the steel sheet pile located just below the concrete floor. The holes are up to 2in. diameter and can be probed 3ft. 8in., no water flow was observed through the lifting holes.

Top of End sill to groundline (south side), End sill is 5ft. high:

Location	2015	2021
West end	14in.	18in.
Floor Seam 3	6ft.	4ft. 5in.
Floor Seam 2	6ft. 6in.	6ft. 6in.
Fioor Seam 1	5ft. 6in.	6ft.
East end	18in.	18in.

There is rock rubble lining the wingwall and along the end seal and light rock rubble toward the center.

WINGWALLS:

Upstream

The steel sheet piles have random areas of light corrosion.

Downstream

The steel sheet piles have random areas of light corrosion.

Divers could not access the NE wingwall due to numerous logs accumulated in the area.

VOLKERT, INC.

Structure ID: Kirkpatrick Dam

District: 03 Inspection Date: 08/02/21

GATES 1 THROUGH 4

There are four lift gates, each lift gate has four manatee barriers in front of them.

Divers could only access the west manatee barrier at Gate 4 from the north side, all others were blocked by numerous logs.

Upstream

The bolts holding the side seal and brackets on all four gates have severe corrosion with up to 100% section loss.

All gates, the single seal bracket holding the seals have moderate corrosion/light pitting.

All gates, the side seal bolts have severe deterioration from the fifth bolt, several bolts are deteriorated to flush with the bracket surface.

On the side seal brackets where they are attached to the gate on Gate 1 on the east side has one loose and one missing bolt. Gate 3 on the east side has one missing bolt.

The bolts holding the bottom seal bracket on all four gates are in good condition.

The gates have minor leakage along the seal.

The manatee barriers (frames and grating) have several areas of minor corrosion/pitting.

CHANNEL

There are logs and heavy vegetation throughout the upstream channel.

Boat/Debris Barriers

Upstream

Boat/Debris barrier is comprised of seventeen timber pile clusters each with two to five timber piles, vertical supports and horizontal cables (10ft. high in some areas).

Clusters 1 through 4 and 14 through 18 have six vertical supports. Clusters 5 through 13 have five vertical supports.

Clusters 1, 2 and 18 are inaccessible due to logs.

Below the waterline, most of the vertical cable supports (pipe) at the boat barrier are broken or corroded through.

The bottom eye bolts are approximately 9ft, below the waterline at each cluster.

Several of the eye bolts at the timber piles are loose or are corroded through.

There are four visible cables (above the waterline).

There are minor checks and weathering in the timber piles.

Cluster 14 south pile, below fifth eye bolt from top has a void, 12in. H x 1-1/2in. W x 3in. D.

There are numerous logs on the channel bottom in front of all four gates/manatee barriers and along the boat/debris barriers.

Downstream

Floats are metal can type floats and have moderate corrosion and light pitting below the waterline.

Bottom Conditions/Water Depths South of Downstream Apron

Water depth and bottom material at end sill and extending south:

	S (1010) 201 0	155
Wild Control of the C	- EXECUTE	III OSHIGI
Exite infort most	200	THE TEXT
FE START START	- XIII	al 1, 5 = 1

Inspection Date: 08/02/21

PHOTO LOG:




Photo 1: North elevation/Log Build-up




Photo 2: Deterioration/Missing seal bolts (Gate 1 upstream)




Photo 3: Deterioration/Missing seal bolts (Gate 1 upstream)




Photo 4: Deterioration/Missing seal bolts (Gate 1 upstream)




Photo 5: Top of weir, typical scale (upstream)




Photo 6: East abutment, typical scale (upstream)




Photo 7: Gate 1 bottom seal bracket, typical bolt




Photo 8: Gate 1 manatee barrier, light corrosion




Photo 9: Pier 1, typical scale (upstream)




Photo 10: Deterioration/Missing seal bolts (Gate 2 upstream)




Photo 11: Boat barrier, deteriorated vertical support




Photo 12: Boat barrier, typical deteriorated eye bolt




Photo 13: Boat barrier, typical deteriorated eye bolt




Photo 14: Boat barrier, loose cables

District: 03

Inspection Date: 08/02/21




Photo 15: Boat barrier Cluster 14, void in pile




Photo 16: NW wingwall, light corrosion (upstream)




Photo 17: View of downstream




Photo 18: Downstream west sheet pile, light corrosion




Photo 19: Gate 4 weir, typical scale




Photo 20: Downstream Gate 4, leakage




Photo 21: Typical joint in apron




Photo 22: Lifting hole at end sill in steel sheet pile under apron




Photo 23: Downstream boat barrier float




Photo 24: Downstream boat barrier float, typical corrosion

Appendix D. Condition Assessment Report For Florida Dams and Impoundments



Date Prepared: September 28, 2021

Prepared By: Martin Kemps, PE

CONDITION ASSESSMENT REPORT FOR FLORIDA DAMS AND IMPOUNDMENTS

Dam Information

Name of Dam: Kirkpatrick Dam (Rodman Dam and Spillway)

National Inventory of Dams Identification Number: FL00156

Location-City/County: Palatka / Putnam County / Florida

Hazard Classification: Low Name of Waterbody: Rodman Reservoir

Purpose of Dam/Waterbody: Recreation / flood control Total Surface Area: 20.3 square miles

Crest Elevation: 28.0 (NGVD) Crest Width: 30 feet Crest Length: 7,200 feet

U/S Water Depth: 6' to 19' D/S Ground Elev.: 5.0 (NGVD) U/S Water Elev. 18.0 - 20.0 (NGVD)

Crest Material: Sand U/S Slope: 3(H):1(V) to 10(H):1(V) to 4(H):1(V) D/Slope: 4(H):1(V)

Owner's Information

Owner's Name(s): Florida Department of Environmental Protection

Owner's Address: 8282 S.E. Highway 314, Ocala Florida

Contact Person (if different from above): Mr. Mickey Thomason

Telephone No.: 352-236-7143

Email Address (or other means of communication): www.floridadep.gov

Owner's Engineer

Name of Engineering Firm or Engineer: Mead & Hunt, Inc.

Florida Professional Engineer License Number: 70468

Mailing Address: 2440 Deming Way, Middleton, WI 53562

Telephone Number: (Business): 608-273-6380

Date of Inspection: August 2nd and 3rd, 2021

1. Crest

a.	How would you	describe the vegeta	tion on the crest? (Check all that	apply)
Recently Mowe	d <u>X</u>	Overgrown	Good Cove	r <u>X</u>	Sparse
Other (describe)): <u>Rodman Dam</u>	Road which consis	ts of asphaltic cond	crete is locate	d on the crest.
		ees or other inappro			Yes No <u>X</u>
If yes, describe	the condition (fo	road or driveway or r example, good con ively good condition	ndition, numerous	cracks, newly	-
d.	Are there any de	epressions, ruts or h	oles on the crest?	Yes	No X
If yes, describe	(length and widt	h, location, direction	n of cracking, etc.):		
If yes, describe	(length and widt	acks on the crest? h, location, direction he due to age of the	n of cracking, etc.):	: Numerous m	ninor cracks in ad to slope instability.
f.	Other observation	ons on the crest: Cr	est is very wide, bu	ıt no cut-off v	vall exists.
2. Upstro	eam Slope (refe	r to Glossary for de	scription)		
a.	What is the rese	rvoir level today?			
At Normal Poo	I <u>X (19.6 NGVD</u>	Above Normal	PoolFeet	Below Norma	nl Pool Feet
b.	How would you	describe the vegeta	ntion on the upstrea	m slope? (Ch	eck all that apply)
Recently Mowe	ed X Overg	rown	Good Cover X	Sparse	
Other (describe):		***		
c.	Are there any tr Yes X No	ees or other inappro	priate vegetation o	n the slope?	

the upstream sl	ope that should be removed.
d.	Are there any depressions, bulges, ruts, or holes (such as animal burrows) on the slope? Yes $\underline{\hspace{1cm}}$ No \underline{X}
If yes, describe	(size, location, etc.)
	Are there any eroded areas on the slope (such as wave erosion along the shoreline)? No
If yes, describe	e (size of area, location, severity, etc.):
f.	Are there any cracks, sloughs or slides (vertical cliffs) on the slope? Yes No X
If yes, describe	(length, width, height, location, etc.)
g.	Is there any type of slope protection along the shoreline (such as riprap)? Yes X No
Other observat	what type and its condition (for example, riprap - adequate, inadequate, sparse, etc.): ions on the upstream slope Rip rap exists along the upstream slope to approximate El. 22 rap had adequate cover and consisted of high-quality granite material.
	stream Slope (refer to Glossary for description)
a.	How would you describe the vegetation on the downstream slope? (Check all that apply)
Rece	ently Mowed X Overgrown Good Cover X Sparse Sparse
Other (describe	e):
b.	Are there any trees or other inappropriate vegetation on the slope? Yes \underline{X} No
* '	e (type of vegetation, size, location, etc.): The right embankment had a small Palm tree astream slope that should be removed.
c.	Are there any depressions, bulges, ruts, or holes (such as animal burrows) on the slope? Yes X No
	(size, location, etc.): The right embankment contained some rutting due to vehicles main roadway.
d.	Are there any eroded areas on the slope (such as along abutment contacts)? Yes No \underline{X}

If yes, describe (type of vegetation, size, location, etc.): The left embankment had a small Palm tree along

If yes, describe (size of area, location, severity, etc.):
e. Are there any cracks, sloughs or slides (vertical cliffs) on the slope? Yes No X If yes, describe (length, width, height, location, etc.):
f. Are there any wet areas or areas of hydrophilic (lush, water-loving) vegetation? Yes X No
If yes, describe (length, width, height, location, etc.): Along the toe of each embankment seepage water collects in a trench that discharges into the river. Lush vegetation including cattails are present within these drainage trenches. The drainage trench is protected by a rip rap revetment.
g. Do any wet areas indicate seepage through the dam (such as rust-colored, stained water)? Yes X No_ N/A
If yes, describe (for example, new area of seepage, no change from past observations, size of area, location, etc.): The seepage in the drainage ditches appears to be similar when compared to the 2015 inspection of the project performed by Amec Foster Wheeler Environment & Infrastructure, Inc.
h. Are there any leaks (flowing water) from the slope or beyond the toe of the dam? Yes X No
If yes, describe (location, rate of flow, turbidity of flow, etc.): Along the toe of each embankment seepage water collects in a trench that discharges into the river. The flow was free flowing and did not appear to be turbid or carrying soil but was very difficult to tell since the natural color of the reservoir is very dark brown. Seepage along the left embankment that discharges through the culverts was estimated to be 45 to 70 gallons per minute. Seepage from the right embankment could not be estimated since there isn't any culverts or weirs installed to collect and monitor the seepage.
i. Other observations on the downstream slope: <u>None</u>
 4. Plunge Pool a. Is there any type of erosion protection around the plunge pool (such as riprap)? Yes X No
If yes, describe what type and its condition (for example, riprap - adequate, inadequate, obstructed by vegetation): A timber pile supported, 2'-6" thick reinforced concrete apron exists below the spillway. A sheetpile cut-off wall extends along the downstream end. The apron has a 2' high end sill to help dissipate flows. The downstream apron and end sill concrete appear to be in satisfactory condition based

- **b.** Is there any erosion around the plunge pool? Yes X No
- c. If yes, describe (size of area, location, severity, etc.): The divers reported that the downstream end of the downstream apron was undermined approximately 27-inches, exposing the sheet pile cut-off wall. Material has also eroded beneath the apron which extended 3'-8" upstream of the sheet piling.
- d. Other observations around the plunge pool: None

upon the dive inspection performed by Volkert, Inc. in August 2021.

5. Principal and Emergency Spillways

(Check all that apply) NA

	What types of spillways are on the dam and what is there composition (such as corrugated metal, concrete, or siphon pipe; concrete or earth channel)?
Principal Spillwa	ay X Emergency Spillway Other
operated, vertica wall extends alor	pillway consists of a four-bay reinforced concrete ogee weir with four hydraulically 1 lift gates. The steel gates are approximately 15' high by 40' wide. A sheetpile cut-off ng upstream face of the ogee weir. An upstream apron consisting of rip rap underlain by xtends 50' upstream of the weir. An operating platform contains the hydraulic operating
	Has the emergency spillway activated (had flow) since the last inspection? Yes No X (there is no emergency (auxiliary) spillway at the project)
If yes describe (d	date(s) of flow, reason for activation, depth of flow, erosion damage, etc.):
	For pipe spillways, is the intake obstructed in any way (such as with excessive debris)? Yes No X (there is no pipe spillway at the project)
	If yes, describe (type of debris, reason for obstruction, etc.):
	For pipe spillways, what is the condition of any trash racks (for example, adequate, inadequate, damaged)? NA
	For pipe spillways, are there any visible cracks, separations or holes in the pipe(s) (intake or outlet)? NA If yes, describe (location, width of crack or separation, etc.):
	For pipe spillways, are there any apparent leaks in the pipe(s)? <u>NA</u> If yes, describe (location, rate of flow from leak, etc.):
	For pipe spillways, how would you describe the overall condition of the pipe(s)? (Check all that apply) NA
Functioning Nor Inadequate	rmally Not Functional Deteriorated Damaged Adequate
	For concrete or earth channel spillways, is the entrance or channel obstructed in any way? Yes X No
upstream side of	(type of obstruction, location, etc.): <u>Heavy wood debris and vegetation extends along the f the concrete weir.</u> The upstream debris barrier is not operational, which allows debris to of the spillway. The debris limits the discharge capacity of the gates.
j.	For earth channel spillways, how would you describe the vegetation in the spillway?

	For earth channel spillways, are there any trees or other inappropriate vegetation in the spillway? <u>NA</u>
If yes, describe	(type of vegetation, size, location, etc.):
k.	For earth channel spillways, are there any eroded areas in the spillway? NA
If yes, describe	(size of area, location, severity, etc.):
1.	For concrete channel spillways, are there any cracks or holes in the spillway? Yes No X
If yes, describe	(width of crack or hole, location, etc.):
m.	For concrete channel spillways, are there any leaks or evidence of undermining (flow under the concrete)? Yes No X
If yes, describe	(location, rate of flow from leak, indicators of undermining, etc.):
n.	For earth or concrete channel spillways, how would you describe the overall condition of the spillway? (Check all that apply)
Functioning No Inadequate	ormally X Not Functional Deteriorated Damaged Adequate
0.	Other observations on the spillways: The spillway itself functions normally, however the debris present upstream of the spillway can lodge in front of the spillway gates and decrease spillway capacity during large rain events and overtop other areas of the project The woody debris may also prohibit the gates from operating properly(lodging).
6. Instru	mentation
a.	Are there any toe drains at the downstream toe or any other seepage drains on the dam? Yes X No
Along the toe of flow was free for the natural color through the cul	the condition (for example, clogged, free flowing, deteriorated, good condition, etc.): of each embankment seepage water collects in a trench that discharges into the river. The lowing and did not appear to be turbid or carrying soil but was very difficult to tell since or of the reservoir is very dark brown. Seepage along the left embankment that discharges verts was estimated to be 45 to 70 gallons per minute. Seepage from the right could not be estimated since there aren't any culverts or weirs installed to collect and page.
b.	For drains, is an animal guard installed at the outlet of each drain? <u>NA</u>
If no, which dra	ains lack animal guards?
c.	For drains, measure the rate of flow from each drain and record below (use additional

pages if necessary):

Designation/Location of Drain	Flow Rate	Flow Rate in GPM*	Turbidity Flow (Describe clear, muddy, etc.)	
Culverts left of spillway	45 to 70 gpm	45 to 70 gpm	Appeared clear, but natural color of water is dark brown	
d. Are there	d. Are there any piezometers on the dam? Yes No X			
If yes, describe the condition	on (for example, good cond	dition, damaged, etc.):		
e. For piezo	e. For piezometers, does each piezometer have a cap with a lock? Yes No			
If no, which piezometers r	need caps (to prevent rainwa	ater intrusion) and/or locks	s (to prevent tampering)?	
f. For piezo: Yes	meters, are you able to take	a measurement (depth to	water) in each piezometer?	
If yes, record depth to wat form.	er (in feet) in each piezome	eter, record on a separate p	age and attach to this	
g. Are there	any other monitoring device	es on the dam? Yes	No <u>X</u>	
	and the condition (for exan	•	ood condition, damaged,	
	Other observations on instrumentation: <u>Survey monuments located on operating platform</u> and concrete tailrace walls. These monuments are not surveyed.			
7. Outlet Pipe				
a. Any wate all that ap	er flowing outside of dischar oply) <u>NA</u>	rge pipe through the impor	unding structure. (Check	
Functioning Normally Inadequate	Not Functional De	teriorated Damaged_	Adequate	
b. Describe	any deficiencies:			
8. Stilling Basin				
a. Deteriora	tion of concrete structures	(Check all that apply)		
Functioning Normally X Inadequate	Not Functional Dete	priorated Damaged	Adequate	
b. Exposure	of rebar? Yes No	X		

c. Deterioration of basin sloes and repairs

done:

d. Any obstruction to flow:

9. Waterbody Structures a. Deterioration of concrete structures (Check all that apply) Functioning Normally X Not Functional Deteriorated Damaged Adequate Inadequate Describe: Overall the spillway was in good condition **b.** Exposure of rebar? Yes No \underline{X} c. Deterioration of basin slopes and any repairs Any obstruction to flow: Woody debris and vegetation is present upstream of the spillway which can lodge in front of the spillway gates, decreasing spillway capacity during large rain events. 10. Downstream Hazard Issues a. Deterioration of concrete structures (Check all that apply) Functioning Normally X Not Functional Deteriorated Damaged Adequate Inadequate b. Exposure of rebar? Yes___ No X c. Deterioration of basin sloes and any repairs done: Some minor voids were noted beneath

the grouted rip rap in the 2019 inspection by Greenman-Pedersen, Inc. These voids have not been filled. These areas appeared to be in the same condition in 2021 as compared to the 2019 photographs.

d. Any obstruction to flow: No


e. Are there homes downstream from the dam? Yes \underline{X} No____

Approximate distance: Closest dwelling estimated to be 1.3 Miles

11. Photographs

At a minimum, photographs should be taken of the crest, upstream slope, downstream slope, principle and emergency spillways, and any other notable features. (Example: structures, seepages, ruts, slope failure, etc.)


Photographs:



Photograph No. 1: View of downstream end of spillway



Photograph No.2: Spillway piers




Photograph No. 3: Diver inspecting Gate 1



.Photograph No. 4: Debris upstream of gates



Photograph No. 5: Corrosion of gate hoist supports





Photograph No. 7: Upstream slope of left embankment



Photograph No.8: Downstream slope of left embankment



Photograph No. 9: Upstream slope of right embankment



Photograph No. 10: Downstream slope of right embankment

OVERALL CONDITION ASSESSMENT OF IMPOUNDING STRUCTURE AND APPURTENANCES

(Check one) SATISFACT	TORY X FAIR \square POOR \square UNSATISFACTORY \square NOT RATED \square
1.	SATISFACTORY No existing or potential dam safety deficiencies are recognized. Acceptable performance is expected under all loading conditions (static, hydrologic, seismic) in accordance with the applicable regulatory criteria or tolerable risk guidelines.
2.	FAIR No existing dam safety deficiencies are recognized for normal loading conditions. Rare or extreme hydrologic and/or seismic events may result in a dam safety deficiency. Risk may be in the range to take further action.
3.	POOR A dam safety deficiency is recognized for loading conditions which may realistically occur. Remedial action is necessary. POOR may also be used when uncertainties exist as to critical analysis parameters which identify a potential dam safety deficiency. Further investigations and studies are necessary.
4.	UNSATISFACTORY A dam safety deficiency is recognized that requires immediate or emergency remedial action for problem resolution.
5.	NOT RATED The dam has not been inspected, is not under state jurisdiction, or has been inspected but, for whatever reason, has not been rated.
Supplemental (Comments (Add narrative on your overall assessment category):

CERTIFICATION BY PROFESSIONAL ENGINEER

I hereby certify, by signing, dating, and sealing, that the information provided in this report has been examined by me and found to be true and correct in my professional judgment.



This item has been digitally signed and sealed by Martin Kemps, PE on 9/28/2021.

Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.

E-Mail Tracy Woods, P.G., State Dam Safety Officer, at <u>Tracy.Woods@FloridaDEP.gov</u>, when the executed form is ready for download from a secure account.



Project Name:

Buckman Lock

Owner:

Department of

Environmental Protection

Mead & Hunt Representatives: Marty Kemps, PE (FL)

Jim Botz, PE

Date:


August 3 and 4, 2021

The following findings are a summary of Mead & Hunt's inspection. Detailed information regarding the inspection will be provided in the inspection report which will also contain the requested Condition Assessment, recommendations, additional photos, and repair / maintenance information.


Visual Inspection

The following is a summary of the observations made by Mead & Hunt during our inspection.


- A. No immediate safety concerns with regards to the lock structure were observed during our inspection.
- B. We observed both miter gates opening and closing. No binding or vibration was noted while operating.
- C. The canal water was flushed twice during our inspection. The emptying and filling valves appeared to function properly.
- D. No significant concrete deterioration of the lock chamber was observed. Some hairline cracking and minor efflorescence was noted throughout the lock chamber.
- E. Operator mentioned that approximately 75% of the lubrication lines used to grease the operating system no longer accept grease.
- F. No seepage around the structure was noted.
- G. Flap valves at the outlets of the drainage system, used to reduce hydrostatic pressures on the lock walls, appeared to function as intended.
- H. The concrete guide walls were in good condition with very minimal hairline cracking and efflorescence.




Photograph No. 1: View of lock looking upstream




Photograph No.2: Downstream miter gates




Photograph No. 3: Typical hydraulic ram for miter gates




Photograph No. 4: Lock chamber being lowered looking upstream




Photograph No. 5: Lock lowered looking downstream



Photograph No. 6: Upstream mitre gate seal leakage



Photograph No. 7: Downstream rip rap protection



Photograph No. 8: Downstream concrete guide wall



2021 Inspection Report

Buckman Lock

Ocklawaha River Putman County, Florida

Report prepared for

Florida Department of Environmental Protection

Report prepared by

Mead

I unt

www.meadhunt.com

November 2021



This item has been digitally signed and sealed by Martin Kemps, PE on 11/10/2021.

Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.

Table of Contents

		F	age			
1.	Gene	General				
2.	Project Description					
3.	Field	ield Inspection				
	3.1	Field Inspection Observations	3			
		3.1.1 Lock	3			
		3.1.2 Miter Gates	3			
		3.1.3 Concrete guide wall	4			
		3.1.4 Control Room	4			
	4.	Surveillance and Monitoring				
	5.	Opinion of Probable Cost and Timeline	5			
6.	Refer	rences	7			

Appendices

- A Project Drawings
- B Photographs
- C Condition Assessment Report For Florida Dams and Impoundments

1. General

The Buckman Lock (Project) is owned, operated, and maintained by the Florida Department of Environmental Protection (FDEP). Mead & Hunt, Inc. (Mead & Hunt) performed the inspection of the Buckman Lock on August 2 and 4, 2021. This report provides a summary of the inspection and recommendations for long-term monitoring along with a cost estimate for repairs.

The conclusions and recommendations herein are based on the engineer's opinion and are made independently of the FDEP, its employees, and its representatives. The conclusions regarding the condition and safety of the lock and related facilities are not guaranteed but do represent our best judgment.

This report was prepared by Martin Kemps, PE and reviewed by Jim Botz, PE.

2. Project Description

The Buckman Lock was designed by the U.S. Army Corps of Engineers (USACE) as part of the Cross Florida Barge Canal system. The Project connects the Rodman Reservoir to the St. Johns River.

The Buckman Lock consists of reinforced concrete with vertical walls and a horizontal floor. The walls range between seven to twenty-five feet wide at top elevation of 25.5¹. The bottom of the walls range between thirty-one to thirty-seven feet wide with a bottom elevation between -11.0 and -28.0. The concrete lock floor is two feet thick and has a top elevation of -16.5, with 5-foot-thick concrete struts. A pressure relief system beneath the floor consists of coarse filter material with 18-inch perforated, corrugated metal pipes.

The lock has four miter gates, each 47'-9" wide. The upstream gates are 19.5 feet high, while the downstream gates are 42 feet high. Each gate is controlled by a hydraulic power unit (HPU) with a horizontally mounted hydraulic cylinder. A manatee protection system is in-place at each set of the miter gates that prevents injury to passing by manatees due to operating the gates. There is an upstream concrete guide wall on the right² side of the lock and a downstream concrete guide wall along the left side of the lock.

The lock is open to the public Thursday through Sunday. During days when the lock is not open to the public, the lock chamber is flushed daily for environmental reasons.

Representative drawings of the lock structure can be found in Appendix A.

1

¹ Elevations in this report are referenced to NGVD 29.

² Left and right are referred to in this report relative to an observer facing downstream,

3. Field Inspection

The field inspection of the Project was performed on August 2 and 4, 2021. The following individuals participated in the visual inspection:

Arthur Annis – FDEP
Jim Botz, PE – Mead & Hunt, Inc.
Marty Kemps, PE – Mead & Hunt, Inc.

At the time of the inspection, the weather was overcast to heavy rains with temperature between 75°F to 82°F. The conditions allowed for a visual assessment of the lock. During the inspection, both the upstream and downstream miter gates were operated.

Visual observations of the Project's water-retaining structures were made during the field inspection to note the following conditions:

- Cracking of concrete
- Deterioration of concrete
- Joint movement or offsets
- Misalignment
- Movement
- Settlement
- Excessive debris

- Deformation of gate members
- Leakage
- Seepage
- Erosion
- Debris
- Instrumentation
- Offsets

The field inspection started along the left side of the lock, down to the end of the downstream guide wall, up the right side of the lock, across the upstream gates and up and down the upstream guide wall then inside the upstream control building. No condition that requires immediate action was noted during the field inspection. Photographs taken during the inspection and referenced below can be found in Appendix B.

The condition of Project components was evaluated relative to the following definitions.

Excellent Appearance is essentially equivalent to post-construction condition. Feature or system

functions as intended and without problems. Maintenance needs are less than or

equivalent to design intent.

Good Appearance has minor deterioration such as concrete shrinkage cracks or damage to

coatings over less than 5 percent of area, which would be expected for a structure or system of similar age and exposure. Feature or system reliably functions as intended.

Maintenance needs are essentially equivalent to design intent.

Fair Appearance has deterioration such as concrete cracking, spalling, joint offsets, or metal

corrosion over more than 25 percent of area, which is indicative of age, weathering, or wear. Feature or system accommodates design loadings and functions as intended;

however, operation may periodically require minor manipulation. Maintenance needs are evident and likely greater than design intent.

Poor

Appearance has significant deterioration that could be indicative of reduced structural integrity and ability to accommodate design loadings. Feature or system often does not function as intended and requires repair or replacement. Maintenance needs are frequent and far exceed the design intent.

Unsatisfactory The feature or system is no longer able to perform its function as intended and poses a threat to the safe operation of the facility. Immediate attention is required to remedy the condition.

As requested by the FDEP, A Condition Assessment Report For Florida Dams and Impoundments form was also completed and is included in Appendix C.

3.1 **Field Inspection Observations**

3.1.1 Lock

The lock appeared in good condition overall. Some minor hairline cracks along the concrete parapet walls (see Photograph Nos. 1 and 2) were observed. Efflorescence (Photograph Nos. 3 and 4) and light cracking (Photograph No. 5) was noted along the lock walls.

The lock was operated through a couple of cycles during our inspection (Photographs 6 through 10). Both the upstream and downstream gates appeared to operate smoothly without signs of binding or other problems. The uplift pressure relief system also appeared to be functioning as designed. Water could be seen flowing from the flap valve (Photograph No. 11) during dewatering. While the lock chamber was lowered, the top of the upstream gate sill was visible and appeared to be in good condition (Photograph No. 12). Although the gates operated smoothly, the operator mentioned that most of the grease lines are not operable. To help prevent more expensive future repairs, the grease lines should be repaired to allow for proper lubrication.

2021-REC-1 The grease lines for the lock should be repaired to allow for proper lubrication and to prevent more expensive future repairs by December 2022.

3.1.2 **Miter Gates**

The miter gates are from original construction (1968). Although gates appeared to be in good condition during the site visit, some minor corrosion was noted on the gates (Photograph Nos. 13 and 14). We understand that a detailed gate inspection has not been performed within the last ten plus years. To document the amount of corrosion and overall condition of the gates, the gates should be cleaned and a detailed, hands-on inspection which includes climbing the gates, along with taking thickness measurements be performed and the results reviewed by a qualified hydraulic steel structural engineer.



2021-REC-2 A detailed, hands-on inspection of the gates should be performed, including taking thickness measurements of gate members. The findings should be reviewed by a qualified hydraulic steel structural engineer by December 2023.

3.1.3 Concrete guide wall

The upstream and downstream concrete guide walls are also in good condition (Photograph Nos. 15 and 16). The rip rap shoreline protection (Photograph Nos. 17 to 19) was in good condition and had sufficient coverage. Some vegetation was noted on the left, downstream side that should be removed or killed before it becomes well-established.

2021-REC-3 The heavy vegetation along the left, downstream side of the lock within the rip rap should be killed or removed by July 2022.

3.1.4 Control Room

The upstream control room was observed. The operator reported that all controls were in working condition. The facility was clean and well maintained (Photograph No. 20). Air conditioning is kept on to maintain an anti-corrosion environment for the hydraulic power units (Photograph No. 21) and other operating equipment. The display monitor (Photograph No. 22) includes percentage of gate opening, lock chamber water level, and information regarding the manatee protection system.

4. Surveillance and Monitoring

The only monitoring currently performed is from operator observations during site visits and viewing staff gages to monitor lock chamber water level elevations. The Project does have twenty-seven piezometers, but they are currently, and historically not measured. Water was observed within the boxes that housed the piezometers and the system likely needs refurbishing repairs. Since the lock is constantly de-watered to the upstream sill elevation, with no signs of stress or movement, we recommend that the operators pay special attention to the uplift pressure release system to ensure it is still functioning as intended, instead of refurbishing the piezometer system and taking routine measurements. If water cannot be observed exiting or drastically reduced from the pressure relief valves in the future, then the pressure relief system should be inspected and cleaned.

2021-REC-4 Operators should pay special attention to the pressure relief system when de-watering the lock to ensure the pressure relief system is functioning as intended. If flow through the relief valves is not visible, or drastically reduced, the pressure relief system should be inspected and cleaned within one month of reduced / no flow.

5. Opinion of Probable Cost and Timeline

The cost estimate is considered a Class 4 estimate based upon the Association for the Advancement of Cost Engineering (AACE) International Cost Estimate Classification System – As Applied in Engineering, Procurement, and Construction for the Hydropower Industry. A summary of the Class 5 estimate is shown in Table 5-1 for reference:

Table 5-1. AACE Cost Estimate Matrix

COST ESTIMATE CLASSIFICATION MATRIX FOR THE HYDROPOWER INDUSTRY

	Primary Characteristic		Secondary Characteri	stic
ESTIMATE CLASS	MATURITY LEVEL OF PROJECT DEFINITION DELIVERABLES 1 xpressed as % of complete definition	END USAGE Typical purpose of estimate	METHODOLOGY typical estimating method	EXPECTED ACCURACY RANGE Typical variation in low and high Langes ^[a]
Class 5	0% to 2%	Concept screening	Capacity factored, parametric models, judgment, or analogy	
Class 4	1% to 15%	Study or feasibility	Equipment factored or parametric models	L: -15% to -30% H: +20% to +50%
Class 3	10% to 40%	Budget authorization or control	Semi-detailed unit costs with assembly level line items	L: -10% to -20% H: +10% to +30%
Class 2	30% to 75%	Control or bid/tender	Detailed unit cost with forced detailed take-off	L: -5% to -15% H: +5% to +20%
Class 1	65% to 100%	Check estimate or bid/tender	Detailed unit cost with detailed take-off	L: -3% to -10% H: +3% to +15%

Notes: [a] The state of technology, availability of applicable reference cost data, and many other risks affect the range markedly. The +/ value represents typical percentage variation of actual costs from the cost estimate after application of contingency (typicafly at a 50% level of confidence) for given scope.

The following table is a summary of costs with regards to Mead & Hunt's 2021 recommendations with a 20-30% contingency added included.

Table 5-2. Maintenance, Cost, and Timeline Estimation

BUCKMAN LOCK MAINTENANCE AND REPAIR ITEMS Mead & Hunt's 2021 Inspection Report **Estimated** Recommended Remarks Recommendation **Completion Date** Cost* Based upon previous contractor bids with inflation accounted for and The grease lines for the lock should contingency. be repaired to allow for proper \$215,000 lubrication and to prevent more December 2022 Contractors would need to (see remarks) expensive future repairs. visit the Project to review (2021-REC-1) existing conditions to develop a better understanding of costs. A detailed, hands-on inspection of the gates should be performed, including taking thickness measurements of Inspection includes physically dimbing the gates gate members. The findings should \$38,000 December 2023 be reviewed by a qualified hydraulic · Includes engineering review steel structural engineer. (2021-REC-2) The heavy vegetation along the left, downstream side of the lock within Assumes vegetation will be the rip rap shoreline protection should July 2022 removed by operating N/A be killed or removed. personnel (2021-REC-3) Operators should pay special attention to the pressure relief system when de-watering the lock to ensure the pressure relief system is Within 1 month after functioning as intended. If flow observing no flow through the relief valves is not visible, N/A None from pressure or drastically reduced, the pressure release valves relief system should be inspected and cleaned within one month of reduced/no flow,

(2021-REC-4)


^{*} Information presented on this sheet represents our opinion of probably project costs in 2021 dollars and is based upon limited engineering. Actual bids and total project cost will vary based on contractor's perceived risk, site access, market conditions, availability of materials, etc. No warranties concerning the accuracy of costs presented herein are expressed or implied.


6. References


- AACE International Recommended Practice No. 69R-12, Cost Estimate Classification System As Applied in Engineering, Procurement, and Construction for the Hydropower Industry, January 25, 2013.
- Amec Foster Wheeler Environmental & Infrastructure, Inc., Kirkpatrick Dam & Buckman Lock Geotechnical Inspection Report, July 2017.
- U.S. Army Engineer District, Jacksonville Corps of Engineers, *Cross Florida Barge Canal Plans St. Johns Lock*, February 1976.


URS Corporation Southern, Kirkpatrick Dam and Spillway Condition Assessment, September 2015.


Appendix A. Project Drawings


























Appendix B. Photographs




Photograph 1 - Typical light cracking of parapet wall




Photograph 2 – Typical light cracking of parapet wall




Photograph 3 - Lock wall with efflorescence




Photograph 4 - Lock wall with efflorescence




Photograph 5 – Light cracking along lock wall (looking down)




Photograph 6 – Lock chamber dewatered looking downstream




Photograph 7 - Lock chamber dewatered looking upstream from guide wall




Photograph 8 – Lock chamber being dewatered looking upstream.




Photograph 9 – Lock chamber full looking downstream




Photograph 10 - Lock chamber full looking upstream with gates partially open




Photograph 11 - Flap valve for uplift pressure release system




Photograph 12 - Upstream miter gate sill (gates not completely closed in picture)




Photograph 13 – Downstream gates with light corrosion




Photograph 14 – Upstream gates with light corrosion




Photograph 15 - Downstream concrete guide wall




Photograph 16 – Upstream guide wall




Photograph 17 - Rip rap along the left, downstream side of the lock




Photograph 18 – Upstream rip rap, left side of lock




Photograph 19 - Upstream rip rap, right side of lock



Photograph 20 - View inside of control room



Photograph 21 - Hydraulic power unit in upstream control building



Photograph 22 - View of control screen

Appendix C. Condition Assessment Report For Florida Dams and Impoundments



Date Prepared: October 1, 2021
Prepared By: Martin Kemps, PE

CONDITION ASSESSMENT REPORT FOR FLORIDA DAMS AND IMPOUNDMENTS

Dam Information

Name of Dam: <u>Buckman Lock</u>

National Inventory of Dams Identification Number: NA

Location-City/County: Palatka / Putnam County / Florida

Hazard Classification: <u>Unknown</u> Name of Waterbody: <u>Cross Florida Barge Canal</u>

Purpose of Dam/Waterbody: Boat/fish/Manatee passage Total Surface Area: 50,400 square feet (Lock)

Crest Elevation: Lock Walls 25.5 (NGVD) Width: Lock Chamber 84' Lock: Chamber Length 600'

U/S Water Depth: 18.0 – 20.0 (NGVD) D/S Ground Elev.: NA U/S Water Elev. 4.0 (NGVD)

Crest Material: NA U/S Slope: NA D/Slope: NA

Owner's Information

Owner's Name(s): Florida Department of Environmental Protection

Owner's Address: 8282 S.E. Highway 314, Ocala Florida

Contact Person (if different from above): Mr. Mickey Thomason

Telephone No.: 352-236-7143

Email Address (or other means of communication): www.floridadep.gov

Owner's Engineer

Name of Engineering Firm or Engineer: Mead & Hunt, Inc.

Florida Professional Engineer License Number: 70468

Mailing Address: 2440 Deming Way, Middleton, WI 53562

Telephone Number: (Business): 608-273-6380

Date of Inspection: August 2nd and 4th, 2021

1. Crest (refer to the Bureau of Reclamation's Glossary (Glossary) for description)							
a.	How would you describe the vegetation on the crest? (Check all that apply)						
Recently Mowe	ved X Overgrown Good Cover Sparse						
Other (describe	e): Although there isn't a crest associated with the lock, the grass adjacent to lock ined.	structure					
b.	Are there any trees or other inappropriate vegetation on the crest? Yes	No <u>X</u>					
If yes, describe	e (type of vegetation, size, location, etc.):						
	Is there a paved road or driveway on the crest? Yes No X						
If yes, describe	e the condition (for example, good condition, numerous cracks, newly paved, etc.):						
d.	Are there any depressions, ruts, or holes on the crest? Yes No \underline{X}						
e.	e. If yes, describe (length and width, location, direction of cracking, etc.):						
f.	Are there any cracks on the crest? Yes No \underline{X}						
If yes, describe	e (length and width, location, direction of cracking, etc.):						
g.	Other observations on the crest: There is no crest associated with the lock struct	ure					
2. Upstr	ream Slope (refer to Glossary for description)						
a.	What is the reservoir level today?						
At Normal Poo	ol X Above Normal Pool Feet Below Normal Pool Feet						
b.	. How would you describe the vegetation on the upstream slope? (Check all that a	ipply)					
NAX Recent	ntly Mowed Overgrown Good Cover Sparse						
Other (describe	pe):	_					
c.	Are there any trees or other inappropriate vegetation on the slope? Yes No X						
If yes, describe	be (type of vegetation, size, location, etc.):						
d.	. Are there any depressions, bulges, ruts, or holes (such as animal burrows) on the NAX Yes_ No_	e slope?					

If yes, describe	(size, location, etc.)
	Are there any eroded areas on the slope (such as wave erosion along the shoreline)? No
If yes, describe	(size of area, location, severity, etc.):
f.	Are there any cracks, sloughs, or slides (vertical cliffs) on the slope? Yes No \underline{X}
If yes, describe	(length, width, height, location, etc.)
g.	Is there any type of slope protection along the shoreline (such as riprap)? Yes X No
•	what type and its condition (for example, riprap - adequate, inadequate, sparse, etc.): Rip long the river slopes. Rip rap has adequate cover and consists of high-quality granite
Other observati	ions on the upstream slope:
3. Downs	stream Slope (refer to Glossary for description)
a.	How would you describe the vegetation on the downstream slope? (Check all that apply)
NAX Recen	atly Mowed Overgrown Good Cover Sparse
Other (describe	s):
b.	Are there any trees or other inappropriate vegetation on the slope? $NA\underline{X}$
If yes, describe	(type of vegetation, size, location, etc.):
c.	Are there any depressions, bulges, ruts, or holes (such as animal burrows) on the slope? NAX Yes No
If yes, describe	e (size, location, etc.):
d.	Are there any eroded areas on the slope (such as along abutment contacts)? NA_X_YesNo
If yes, describe	e (size of area, location, severity, etc.):
e.	Are there any cracks, sloughs, or slides (vertical cliffs) on the slope? NAX
If yes, describe	e (length, width, height, location, etc.):

f.	Are there any wet areas or areas of hydrophilic (lush, water-loving) vegetation? Yes No X
If yes, describe	(length, width, height, location, etc.):
g.	Do any wet areas indicate seepage through the dam (such as rust-colored, stained water)? Yes No X N/A
location,	(for example, new area of seepage, no change from past observations, size of area,
h.	Are there any leaks (flowing water) from the slope or beyond the toe of the dam? Yes No \underline{X}
If yes, describe	e (location, rate of flow, turbidity of flow, etc.):
i.	Other observations on the downstream slope:
4. Plung	e Pool (refer to Glossary for description)
a.	Is there any type of erosion protection around the plunge pool (such as riprap)? Yes X No
vegetation): R	e what type and its condition (for example, riprap - adequate, inadequate, obstructed by ip rap is present along the canal edges by the miter gates. Rip rap has adequate cover and h-quality granite material.
b.	Is there any erosion around the plunge pool? Yes No \underline{X} (nothing visible above waterline)
If yes, describe	e (size of area, location, severity, etc.):
c.	Other observations around the plunge pool:
5. Princ	ipal and Emergency Spillways (refer to Glossary for description)
a.	What types of spillways are on the dam and what is their composition (such as corrugated metal, concrete, or siphon pipe; concrete or earth channel)?
Principal Spill	way Emergency Spillway Other Miter gates associated with the lock
Describe: Mite	er gates do not act as a spillway but would provide some discharge capacity.

b.	Has the emergency spillway activated (had flow) since the last inspection? Yes No NA X
If yes describe	(date(s) of flow, reason for activation, depth of flow, erosion damage, etc.):
c.	For pipe spillways, is the intake obstructed in any way (such as with excessive debris)? Yes No NA X
If yes, describe	(type of debris, reason for obstruction, etc.):
d.	For pipe spillways, what is the condition of any trash racks (for example, adequate, inadequate, damaged)?
e.	For pipe spillways, are there any visible cracks, separations, or holes in the pipe(s) (intake or outlet)? Yes No NA \underline{X}
If yes, describe	(location, width of crack or separation, etc.):
f. If yes, describe	For pipe spillways, are there any apparent leaks in the pipe(s)? Yes No NA X (location, rate of flow from leak, etc.):
g.	For pipe spillways, how would you describe the overall condition of the pipe(s)? (Check all that apply)
Functioning No Inadequate	ormally Not Functional Deteriorated Damaged Adequate
h.	For concrete or earth channel spillways, is the entrance or channel obstructed in any way? Yes No NA \underline{X}
If yes, describe	(type of obstruction, location, etc.):
i.	For earth channel spillways, how would you describe the vegetation in the spillway? (Check all that apply)
Recently Mowe	ed Good Cover Sparse
Other (describe	e): <u>NA</u>
j.	For earth channel spillways, are there any trees or other inappropriate vegetation in the spillway? Yes No NA \underline{X}
If yes, describe	(type of vegetation, size, location, etc.):
k.	For earth channel spillways, are there any eroded areas in the spillway? Yes No NA X

If yes, describe (size of area, location, severity, etc.):						
	For concrete channel spillways, are there any cracks or holes in the spillway? Yes X No					
If yes, describe (widt chamber walls.	h of crack or hole, location, etc.):	Minor hairline cracks we	re noted along the			
	concrete channel spillways, are the the concrete)? Yes No		of undermining (flow			
If yes, describe (loca	tion, rate of flow from leak, indic	ators of undermining, etc.)	:			
	earth or concrete channel spillway pillway? (Check all that apply)	ys, how would you describe	e the overall condition of			
Functioning Normali Inadequate	y X Not Functional Deter	riorated Damaged	Adequate			
	o. Other observations on the spillways: Although the lock is not a spillway, the gates operated smoothly and without binding.					
6. Instrumen	tation (refer to Glossary for desc	ription)				
	a. Are there any toe drains at the downstream toe or any other seepage drains on the dam? Yes X No					
If yes, describe the condition (for example, clogged, free flowing, deteriorated, good condition, etc.): There is an uplift pressure relief system consisting of 18-inch diameter corrugated metal pipes that discharge through the flap gates on the downstream side of the canal. During our inspection, the drainage system appeared to operate as intended. Discharge water could be seen exiting the flap valves when the lock chamber water was being lowered.						
b. For drains, is an animal guard installed at the outlet of each drain? Yes X No						
If no, which drains lack animal guards?						
	drains, measure the rate of flow fires if necessary):	rom each drain and record	below (use additional			
Designation/Loca of Drain	tion Flow Rate	Flow Rate in GPM*	Turbidity Flow (Describe clear, muddy, etc.)			
Five lateral drain relief uplift press		<u>10-20 GPM</u>	Clear			

d. Are there any piezometers on the dam? Yes \underline{X} No____

	the condition (for example, good condition, damaged, etc.): Twenty-seven piezometers ect. The piezometers are not currently monitored by ad.	
e.	For piezometers, does each piezometer have a cap with a lock? Yes X No	
	ezometers need caps (to prevent rainwater intrusion) and/or locks (to prevent tampering)? was observed within the housing boxes.	
f.	For piezometers, are you able to take a measurement (depth to water) in each piezometer Not attempted, standing water in housing boxes.	
If yes, record d form.	epth to water (in feet) in each piezometer, record on a separate page and attach to this	
g.	Are there any other monitoring devices on the dam? Yes X No	
	what type and the condition (for example, monitoring wells - good condition, damaged, ge for water levels within the lock.	
h.	Other observations on instrumentation: <u>Survey monuments were noted along the top of the lock chamber walls. These monuments are not surveyed.</u>	
7. Outle	t Pipe (refer to Glossary for description)	
a.	Any water flowing outside of discharge pipe through the impounding structure. (Check all that apply) There is an uplift pressure relief system consisting of 18-inch diameter corrugated metal pipes that discharge through the flap gates on the downstream side of the canal. During our inspection, the drainage system appeared to operate as intended. Discharge water could be seen exiting the flap valves when the lock chamber water was being lowered	
b.	Describe any deficiencies:	
8. Stilling	g Basin (refer to Glossary for description) NA	
a.	Deterioration of concrete structures (Check all that apply)	
Functioning No Inadequate	ormally Not Functional Deteriorated Damaged Adequate	
b.	Exposure of rebar? Yes No	
c.	Deterioration of basin sloes and repairs done:	

d. Any obstruction to flow:_____


9. Waterbody Structures

a.	Deterioration of concrete structures (Check all that apply)				
Functioning No Inadequate	ormally X Not Functional Deteriorated Damaged Adequate				
Describe:					
b.	Exposure of rebar? Yes No \underline{X}				
	c. Deterioration of basin slopes and any repairs done: <u>NA</u> d. Any obstruction to flow: <i>No</i>				
10. Downs	stream Hazard Issues				
a.	Deterioration of concrete structures (Check all that apply)				
Functioning Normally X Not Functional Deteriorated Damaged Adequate Inadequate					
b.	Exposure of rebar? Yes No \underline{X}				
c. d.	Deterioration of basin sloes and any repairs done: <u>None</u> Any obstruction to flow: <u>No</u>				
e.	Are there homes downstream from the dam? Yes X No				


Approximate distance: Operator houses are located immediately downstream of lock.

11. Photographs


At a minimum, photographs should be taken of the crest, upstream slope, downstream slope, principle and emergency spillways, and any other notable features. (Example: structures, seepages, ruts, slope failure, etc.)




View of lock looking upstream




Downstream miter gates




Upstream miter gates




Tailrace channel




Upstream channel



Typical cracking along canal wall



Staff gauge on lock wall



Display panel in operating house

OVERALL CONDITION ASSESSMENT OF IMPOUNDING STRUCTURE AND APPURTENANCES

(Check one SATISFA	•	TORY $\underline{\mathbf{x}}$ FAIR \square POOR \square UNSATISFACTORY \square NOT RATED \square
	1.	SATISFACTORY No existing or potential dam safety deficiencies are recognized. Acceptable performance is expected under all loading conditions (static, hydrologic, seismic) in accordance with the applicable regulatory criteria or tolerable risk guidelines.
	2.	FAIR No existing dam safety deficiencies are recognized for normal loading conditions. Rare or extreme hydrologic and/or seismic events may result in a dam safety deficiency. Risk may be in the range to take further action.
	3.	POOR A dam safety deficiency is recognized for loading conditions which may realistically occur. Remedial action is necessary. POOR may also be used when uncertainties exist at to critical analysis parameters which identify a potential dam safety deficiency. Further investigations and studies are necessary.
	4.	UNSATISFACTORY A dam safety deficiency is recognized that requires immediate or emergency remedial action for problem resolution.
	5.	NOT RATED The dam has not been inspected, is not under state jurisdiction, or has been inspected but for whatever reason, has not been rated.

Supplemental Comments (Add narrative on your overall assessment category): No stability analyses of the project were available for review.

CERTIFICATION BY PROFESSIONAL ENGINEER

I hereby certify, by signing, dating, and sealing, that the information provided in this report has been examined by me and found to be true and correct in my professional judgment.

Martin Kemps, PE

October 1, 2021



This item has been digitally signed and sealed by Martin Kemps, PE on 10/1/2021

Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.

Technical Memorandum



To:

Richard J. Rowe, Florida Department of Environmental Protection

From:

Martin Kemps, P.E., Project Manager

Date:

8/20/2021

Subject:

Kirkpatrick Dam Breach Modelling Approach

1. Introduction and Background

The Kirkpatrick Dam consists of three water retaining structures: a southwest embankment, a concrete spillway with four lift gates, and a northeast embankment. The reservoir, known as the Rodman Reservoir, is created by the Kirkpatrick Dam and Buckman Lock, which span across the Ocklawaha River and the Cross Florida Barge Canal, respectively. At normal pool, the reservoir has a surface area of approximately 20.3 square miles, a gross volume of approximately 82,000 acre-feet, and a length of approximately 16.4 miles. The dam is currently listed as "Low Hazard Potential" in the National Inventory of Dams (FL00156), meaning failure or mis-operation results in no probable loss of human life and low economic and/or environmental losses.

To better understand downstream consequences and to assess the hazard potential of the dam, Mead & Hunt will perform a dam failure analysis (DFA). It is our understanding that there is not an existing dam breach hydraulic analysis that can be referenced. In advance of developing a hydraulic model and performing the DFA, this document summarizes available information, assumptions, and model parameters/methodology that will be used.

2. Computer Model

The computer program HEC-RAS (Version 6.0), developed by the U.S. Army Corps of Engineers (USACE), Hydrologic Engineering Center (HEC), will be used for the dam failure analysis. A coupled one-dimensional (1D) and two-dimensional (2D) unsteady-state model will be developed within HEC-RAS to analyze the flood wave resulting from a breach of the Kirkpatrick dam that travels down the Ocklawaha River and into the St. Johns River. Where needed, the RAS Mapper application included within HEC-RAS will be used in conjunction with ESRI's ArcGIS Pro to develop model geometric data using collected geospatial data.

3. Development of Geometric Data

The upstream extent of the coupled 1D/2D HEC-RAS model will be located at the approximate start of the Rodman Reservoir pool. The downstream extent of the model and inundation mapping will be the same as the downstream extent used in the June 2018 Emergency Action Plan, which is just upstream of the Seaboard Coastline Railroad bridge. The 1D portion of the model will cover the reservoir itself, whereas the 2D portion will include the length of the Ocklawaha River downstream of Kirkpatrick Dam and the St. John's River from south of the confluence with the Ocklawaha River north to the railroad bridge.

Technical Memorandum Richard J. Rowe 8/20/2021 Page 2

3.1 Topographic Data

The topographic data needed for the model were obtained from two LiDAR survey digital elevation models (DEM) that are publicly available. The first DEM was generated from a LiDAR survey performed in 2007 by the Florida Division of Emergency Management along the St. Johns River through Clay and Putnam Counties. The resulting DEM has a 5-foot grid resolution. The second DEM was produced from a LiDAR survey performed in 2012 by the St. Johns River Water Management District. This DEM has a 5-foot grid resolution and covers the project area outside of the 2007 survey extents. The two DEMs will be merged into a single 5-foot grid DEM and trimmed to the project area using tools in ArcGIS to create the model terrain.

Efforts are being made to obtain bathymetry data of the Ocklawaha River and St. Johns River from publicly available sources of depth contours as well as nautical/chart plotter companies. If contour data from these sources is obtained, the contours will be converted into a DEM with a 5-foot grid resolution using tools in ArcGIS. The bathymetry DEM will be merged with the terrain DEM to create a single DEM that will be used in the hydraulic model development. If this information cannot be obtained, a proxy bathymetry will be created using 1D channel geometry within the RAS Mapper application. This 1D generated bathymetry will be designed with a capacity that meets known conveyance capacity of the downstream Ocklawaha River.

3.2 Bridge Structure Data

Two bridges span the Ocklawaha River downstream of the Kirkpatrick Dam. Bridge piers in or near the river will be included in the model terrain to accurately reflect the impact of the bridge on water surface elevation and flow disruption. Bridge deck elevations will be considered when evaluating the model results to determine if overtopping occurs.

The two bridges are located on Florida State Road 19 and are managed by the Florida Department of Transportation (FDOT) and Florida State Highway Patrol. Bridge 760035 spans the main channel of the Ocklawaha River and has two large piers within the river channel as well as multiple piers on each overbank of the river. The distance between abutments is approximately 1,400 feet. Bridge 760036 spans the north channel of the Ocklawaha River and has six piers within the river channel. The abutments are located near the channel banks with a separation of approximately 300 feet.

Construction drawings of the bridges were obtained from the FDOT through an exempt document request. Information from these drawings will be used to add bridge piers to the model DEM.

3.3 Rodman Reservoir

The 1D portion of the model will represent the reservoir itself using a storage area with a level-pool routing scheme. The storage volume will be defined by a stage-storage relationship that was provided by the Kirkpatrick Dam principal operator. This stage-storage relationship was originally established by the USACE in 1977 and is shown in Table 1.

Technical Memorandum Richard J. Rowe 8/20/2021 Page 3

Table 1: Rodman Reservoir Stage-Storage Relationship

Elevation NGVD	Bosonie ir Volume (Apre 61)
Elevation NGVD	Reservoir Volume (Acre – ft)
Ma	
F I	
	I STRUE
	fi a sa
	Market 1
171	(E) 5 (
li El	
1BI	
FER	TU UV

^{*}Calculated using flood pool surface area determined in ArcGIS

3.4 2D Flow Area

The 2D flow area will be used within the HEC-RAS model to represent hydraulics downstream of the Kirkpatrick Dam. The 2D area will account for the flood wave resulting from a breach of the gated spillway propagating downstream through the Ocklawaha main channel, network of side channels, and overbank areas. These flow patterns cannot be accurately represented with a 1D model. A 2D mesh will be generated over the terrain DEM with varying cell sizes. A smaller cell size and break lines will be used to define high ground features, steep terrain, and areas near the river to improve model accuracy and performance.

The Manning's n roughness values for the 2D area will be defined based on polygons digitized in ArcGIS using aerial imagery. Roughness values for various surface types will be set based on common practice and engineering judgement.

3.5 Kirkpatrick Dam

The Kirkpatrick earthen dam and gated spillway will be represented in the model using a storage area connection which will connect the upstream storage area to the downstream 2D flow area. Geometry of the dam structure, the four gate bays, and the four lift gates were obtained from as-built construction drawings. The gates will be included in the connection as sluice gates with ogee sill weirs, and appropriate discharge coefficients will be selected for weir, orifice, and sluice discharge.

Gate openings will be based on reservoir inflows and assumed operations for each of the scenarios described below. From discussions with the principal operator, we understand that typical operating

Technical Memorandum Richard J. Rowe 8/20/2021 Page 4

procedure involves having the outer two gates opened less than the inner two gates for fishing benefits. This gate operation protocol will be applied to the model.

4. Model Scenarios

As outlined in our contract, we will model five dam breach scenarios involving different reservoir pool elevations: maximum design elevation, normal pool elevation, and three pool elevations below normal pool as shown in Table 2.

For the maximum pool scenario, we will assume that operations personnel will have all four gates fully open to prevent further pool rise. Based on dam and spillway data included in a 2015 Condition Assessment Report by URS, the peak spillway discharge at a headwater elevation of 23.2 feet with all four gates open is 36,300 cfs. To allow the reservoir to stabilize at the defined pool elevation for the maximum pool scenario, a reservoir inflow of 36,300 cfs will be used.

For the remaining four scenarios, we will assume that operations personnel have the gates open to maintain a minimum flow in the downstream river. From discussions with the principal operator, we understand that the minimum flow maintained through the spillway is 400 cfs. To allow the reservoir to stabilize at the defined pool elevation for each scenario, a reservoir inflow of 400 cfs will be used.

Scenario

Reservoir pool Elevation
NGVD

[CFS]

Maximum Pool

Normal Pool

Draw Down 1

Draw Down 2

Draw Down 3

Table 2: Summary of Model Scenarios


For all five scenarios, the 178-foot-wide concrete spillway structure will be breached down to an elevation of -4 feet NGVD. The breach will initiate after the model has stabilized and will form in 0.1 hours.


Kirkpatrick Dam Failure Analysis Breach Wave Results Table


	(Max)	(Normal)	Pool	Pool	Pool	
	Kirkpatrick Da	m				
Downstream Distance (miles Flood Wave Incremental Rise (feet Peak Flood Wave Stage (feet NGVD Flood Wave Arrival Time (hours Time to Peak Flood Stage (hours	0.0 1 1		100 163 163			
North	east of Dean Cr	eek Road				
Downstream Distance [miles Flood Wave Incremental Rise [feet Peak Flood Wave Stage [feet NGVD Flood Wave Arrival Time [hours Time to Peak Flood Stage [hours						
	SH19 Bridge	Studien-				
Downstream Distance [miles Flood Wave Incremental Rise [feet Peak Flood Wave Stage [feet NGVD Flood Wave Arrival Time [hours Time to Peak Flood Stage [hours						
St. John	Upstream Mo	del Extents				
Downstream Distance (miles Flood Wave Incremental Rise [feet Peak Flood Wave Stage [feet NGVD Flood Wave Arrival Time [hours Time to Peak Flood Stage [hours						
	Fruitland Con	/e				
Downstream Distance [miles Flood Wave Incremental Rise [fee Peak Flood Wave Stage [feet NGVE Flood Wave Arrival Time [hours Time to Peak Flood Stage [hours						
Be	echer Point - V	Velaka				
Downstream Distance [miles Flood Wave Incremental Rise [fee Peak Flood Wave Stage [feet NGVI Flood Wave Arrival Time [hour: Time to Peak Flood Stage [hour:	t]					


Kirkpatrick Dam Failure Analysis Breach Wave Results Table

	(Max)	(Normal)	Pool	Pool	Pool	
Steph	ens Point - W					
Downstream Distance [miles] Flood Wave Incremental Rise [feet] Peak Flood Wave Stage [feet NGVD] Flood Wave Arrival Time [hours] Time to Peak Flood Stage [hours]						
Rive	er Road - Sats	uma				
Downstream Distance [miles] Flood Wave Incremental Rise [feet] Peak Flood Wave Stage [feet NGVD] Flood Wave Arrival Time [hours] Time to Peak Flood Stage [hours]						
White	ney Street - Sa	itsuma				
Downstream Distance [miles] Flood Wave Incremental Rise [feet] Peak Flood Wave Stage [feet NGVD] Flood Wave Arrival Time [hours] Time to Peak Flood Stage [hours]					游 磨 を	
	Stokes Island	THE RES				
Downstream Distance [miles] Flood Wave Incremental Rise [feet] Peak Flood Wave Stage [feet NGVD] Flood Wave Arrival Time [hours] Time to Peak Flood Stage [hours]						
	arrentine Cre	ek				
Downstream Distance [miles] Flood Wave Incremental Rise [feet] Peak Flood Wave Stage [feet NGVD] Flood Wave Arrival Time [hours] Time to Peak Flood Stage [hours]						
Downs	tream Model	Extents				
Downstream Distance [miles] Flood Wave Incremental Rise [feet] Peak Flood Wave Stage [feet NGVD] Flood Wave Arrival Time [hours] Time to Peak Flood Stage [hours]						











Dam Failure Analysis and Hazard Rating Assessment

Kirkpatrick Dam

Putnam County, Florida

Report prepared for

Florida Department of Environmental Protection



Report prepared by



January 2022



This item has been digitally signed and sealed by Martin Kemps, PE on 01/26/2022.

Printed copies of this document are not considered signed and sealed, and the signature must be verified on any electronic copies.

Table of Contents

			Page
Exe	ecutiv	ve Summary	1
1.	intro	duction	2
2.	Proje	ect Description	3
3.	Mode	el Development	4
	3.1 3.2 3.3 3.4 3.5 3.6 3.7	Terrain Data Bathymetry Data Reservoir Stage – Storage Relationship Dam and Spillway Geometric Data State Highway 19 Bridge Geometric Data Manning's Roughness Values 2D Flow Area	5 7 7
4 .	Unst	teady Flow Data	9
	4.1 4.2 4.3	Ocklawaha River Inflows Kirkpatrick Dam Gate Openings St. John's River Inflows	10
5.	Mod	el Initialization	13
6.	Brea	ach Parameters	14
	6.1 6.2	Regression Equations	
7.	Brea	ach Results	18
	7.1 7.2	Breach Results	
8.	Ass	essment of Dam Hazard Potential	20
Da	foron	0.00	21

Page

Figures

Figure 2: USGS Gage No. 02244040 September 2021 Discharge	11
Figure 3: USGS Gage No. 02244040 Historical Stage-Duration Analysis	11
_	
Tables	
Pa	ge
Table 1: Summary of Model Scenarios	2
Table 2: Ocklawaha River Bathymetry Generation	6
Table 3: Discharge Channel Bathymetry Generation	6
Table 4: Rodman Reservoir Stage Storage Relationship	7
Table 5: Model Gate Opening Height	10
Table 6: Summary of Initialization Model Parameters	13
Table 7: Kirkpatrick Dam Tailwater Elevations	13

Appendices

- A Location Map
- B Dam Drawings
- C Maps and Exhibits
- D Affected Structures Table
- E Miscellaneous Information

List of Contributors

This report was prepared by or under the direct supervision of the individuals listed below:

Connor Collies, EIT
Jesse Piotrowski, PE, CFM
Marty Kemps, PE
Warren Hayden, PE
Jen Schuetz
Samantha Gulick

Executive Summary

This report presents the findings of a Dam Failure Analysis for the Kirkpatrick Dam in Putnam County, Florida.

Combined 1D/2D HEC-RAS models were developed to simulate a failure of the Kirkpatrick Dam under multiple reservoir pool elevation scenarios including reservoir at maximum pool elevation of 23.2 feet NGVD 29, reservoir at normal pool elevation of 20.0 feet, and the reservoir drawn down to elevations of 18.0, 16.0, and 14.0 feet. Results from these models were used to determine flood wave heights and arrival times at important locations downstream of the dam. An assessment of parcels with habitable structures that are impacted by dam failure under each scenario was also performed.

Results of the failure models and affected structure assessment were compared to FEMA standards for dam hazard potential classification. Based on FEMA guidelines and definitions of the hazard levels, Kirkpatrick Dam should be classified as a HIGH hazard dam. It is important to note that the hazard potential classification does not reflect in any way the current condition of the dam (e.g., safety, structural integrity, flood routing capacity).

The results and discussions presented in this report may assist the Florida Department of Environmental Protection in understanding the downstream hazard potential of the dam and how changes to reservoir elevation affect the hazard potential.



1. Introduction

The Kirkpatrick Dam (Project) is owned, operated, and maintained by the Florida Department of Environmental Protection (FDEP). The dam is currently listed as "Low Hazard Potential" in the National Inventory of Dams (FL00156), meaning failure or mis-operation results in no probable loss of human life and low economic and/or environmental losses. Recent consideration has been given to reducing the normal pool elevation of the reservoir to reduce operation costs and potentially reduce the downstream hazards.

The FDEP retained Mead & Hunt, Inc. (Mead & Hunt) to perform a dam failure analysis (DFA) of the Project under various reservoir pool elevations to better understand downstream consequences and to assess the hazard potential of the dam. The modeled scenarios include the reservoir at maximum design elevation, the reservoir at normal pool elevation, and three reservoir draw-down conditions as summarized in the table below.

Scenario Reservoir pool Elevation NGVD 291

Table 1: Summary of Model Scenarios

Two known DFA studies have previously been completed for the Project in conjunction with Emergency Action Plan (EAP) efforts. The first was developed by URS in April 2006 (URS Corporation, 2006) and considered a sunny-day breach at normal pool elevation. The second was developed by the FDEP in June 2018 (FDEP, 2018) and considered a sunny-day breach at both a normal pool and PMF event conditions. Reports for both studies were made available by FDEP and used as references during the development of this analysis. However, the associated models were not available, and a new model was needed.

¹ All elevations in this report are given in feet and referenced to the National Geodetic Vertical Datum of 1929 (NGVD 29).

2. Project Description

The Kirkpatrick Dam is located on the Ocklawaha River and impounds the Rodman Reservoir. The dam and nearby Buckman Lock are a part of the Marjorie Harris Carr Cross Florida Greenway. A location map is included in Appendix A. Downstream of the dam the Ocklawaha River flows through a swamp and bifurcates into multiple distributaries before a confluence with the St. John's River downstream of Lake George.

At normal pool, the reservoir has a surface area of approximately 20.3 square miles, a gross volume of approximately 82,000 acre-feet, and a length of approximately 16.4 miles (URS, September 2015). The earthen dam embankments measure approximately 7,200 feet long and consist of homogenous sand material. The crest is 30 feet wide with a top elevation of 28.3 feet. The crest is topped with an asphalt access road. The concrete spillway section measures 178 feet wide and contains four slide gates, each measuring 40-feet wide by 15-feet tall (U.S. Army Corps of Engineers Jacksonville District, January 1966).

Drawings for the dam are included in Appendix B.

3. Model Development

The U.S. Army Corps of Engineers (USACE) Hydrologic Engineering Center's River Analysis System (HEC-RAS) version 6.0.0 was used for the dam failure analysis. Due to the complexity of the downstream river, a coupled one-dimensional (1D) and two-dimensional (2D) unsteady-state model was developed within HEC-RAS to analyze the flood wave resulting from a breach of the Kirkpatrick Dam that travels down the Ocklawaha River and into the St. John's River.

The upstream extent of the coupled 1D/2D HEC-RAS model is the Rodman Reservoir pool. The downstream extent of the model and inundation mapping is the same as the downstream extent used in the 2018 FDEP report, which is just upstream of the Seaboard Coastline Railroad bridge. The 1D portion of the model covers the reservoir itself, whereas the 2D portion includes the length of the Ocklawaha River downstream of Kirkpatrick Dam and the St. John's River reach from 4.5 miles upstream of the confluence with the Ocklawaha River to the Seaboard Coastline Railroad bridge.

3.1 Terrain Data

Model terrain data was obtained from publicly available Light Detection and Ranging (LiDAR) Digital Elevation Model (DEM) files. The terrain data was processed, analyzed, and modified using tools in ArcMap version 10.7.

A DEM was obtained from the USGS National Elevation Dataset (NED) (USGS, 2021) with a 1/3 arc second cell size. This DEM covers the entire model domain but at a resolution of 1/3 arc second (approximately 10 meters), the Ocklawaha River channel is not clearly defined in some areas. The NED data was used to assess the accuracy of local DEM data sources.

A DEM raster was obtained from the National Oceanic and Atmospheric Administration (NOAA) Continuously Updated Digital Elevation Model (CUDEM) (NOAA, 2021). This DEM has a resolution of 9.84 feet (3 meters) and includes St. John's River bathymetry. The CUDEM covers the eastern portion of the model domain, extending approximately 3,000 feet west (upstream) of the State Highway 19 bridge. It was found that the CUDEM matches poorly with the NED data along the right² descending bluff line of the Ocklawaha River floodplain. During data processing, this region of disagreement with the NED data was clipped from the CUDEM data. The CUDEM also includes bathymetry for the Ocklawaha River; however, it only extends upstream from the St. John's River to approximately 5,000 feet east (downstream) of the State Highway 19 Bridge.

Two DEMs with resolutions of 5 feet were provided by the Saint John's River Water Management District (SJRWMD) (SJRWMD, 2012) which has jurisdiction over the model area. The first DEM raster covers the eastern portion of the model area, with a similar extent as the CUDEM data, but there is a 5-foot vertical discontinuity with the NED data in the floodplain. Due to this discontinuity and the availability of other data, this DEM raster was not used. The second DEM raster covers the western portion of the model domain and matches well with the NED data.

² Left and right are referred to in this report relative to an observer facing downstream.

The NED and CUDEM DEMs were projected to the North American Datum (NAD) 1983 Florida State Plane East (feet), converted from meters to feet, and snapped to the SJRWMD DEM grid. The three DEMs were then mosaiced together, with the lowest resolution NED data on bottom and the highest resolution SJRWMD data on top. The mosaiced raster was converted from a vertical datum of NAVD88 to the NGVD29 datum using the NOAA National Geodetic Survey (NGS) coordinate conversion tool. As shown in Appendix E, the conversion for the Project location is:

NGVD29 = NAVD88 + 0.9186 feet

These horizontal and vertical datums were used for the HEC-RAS model.

3.2 Bathymetry Data

As discussed above, bathymetric data of the St. John's River and portions of the Ocklawaha River were obtained from the CUDEM DEM data. High quality Ocklawaha River bathymetry ends approximately 5,000 feet east (downstream) of the State Highway 19 bridge. Additional bathymetry was required for the remaining Ocklawaha River reach between the outlet of the dam and the high quality CUDEM bathymetry.

Bathymetry was created using a combination of the RAS Mapper application and ArcMap tools. Within RAS Mapper, the Ocklawaha River centerline was digitized, and cross sections were drawn with sufficient spacing to approximate the channel path. Three locations with known channel invert elevations were used to determine channel slopes. As-built drawings of Kirkpatrick Dam and State Highway 19 bridge crossing show channel inverts of -4 feet and -6 feet, respectively. The CUDEM DEM shows that the channel invert at the confluence with the St. John's River is -9.4 feet.

Constant channel slopes between (1) the dam and bridge and (2) the bridge and confluence were used to interpolate channel inverts for the other cross sections. A schematic of Ocklawaha channel slopes is included in Appendix E. A constant elevation, representing the interpolated invert of the channel, was defined for the full width of each cross-section. Channel inverts are shown in Table 2. An interpolated surface was created between the cross sections and exported.

Downstream
Reach
Distance (miles)


Invert (ft NGVD 29)

Notes

Notes

Table 2: Ocklawaha River Bathymetry Generation

Table 3: Discharge Channel Bathymetry Generation



This process was repeated to create an interpolated surface representing the deepened discharge channel downstream of the dam spillway, see Table 3. Geometric data of the discharge channel was obtained from as-built construction drawings included in Appendix B.

The interpolated surfaces were imported into ArcMap. Each surface was clipped to the channel boundary using polygon features. The resulting surface represents a flat channel bottom at the interpolated invert elevation within the channel banks. The generated bathymetry data transitions to the CUDEM bathymetry data where the interpolated channel invert intersects the CUDEM data. The clipped surfaces were burned into the mosaiced DEM terrain to create the final model terrain.

3.3 Reservoir Stage – Storage Relationship

The 1D portion of the model represents the reservoir using a storage area with a level-pool routing

scheme. The storage volume was defined by a stage-storage relationship that was provided by the Kirkpatrick Dam principal operator. This stage-storage relationship was originally established by the USACE in 1977 and is shown in Table 4. The maximum elevation in the USACE table is 20 feet. Mead & Hunt extended the table to an elevation of 23.2 feet using ArcGIS.

Elevation NGVD 29 Reservoir Volume (Acre – ft)

Table 4: Rodman Reservoir Stage Storage Relationship

3.4 Dam and Spillway Geometric Data

The Kirkpatrick Dam and gated spillway were represented in the model using a storage area connection which connects the upstream storage area to the downstream 2D flow area. Geometry of the dam structure, the four gate bays, and the four lift gates were obtained from as-built construction drawings. These drawings are included in Appendix B. The spillway gates were included in the connection as sluice gates with ogee sill weirs. To improve model stability, the gates were modeled in two gate groups, each group containing two gates. The outer two gates were modeled as one gate group, and the inner two gates were modeled as a second gate group. Typical discharge coefficients of 0.6, 0.8, and 3.47 were used for sluice, orifice, and weir discharge, respectively.

3.5 State Highway 19 Bridge Geometric Data

Two bridges span the Ocklawaha River downstream of the Kirkpatrick Dam. The two bridges are located on Florida State Road 19 and are managed by the Florida Department of Transportation (FDOT) and Florida State Highway Patrol. Bridge 760035 spans the main channel of the Ocklawaha River and has two large piers within the river channel as well as 14 piers in the left overbank and 14 piers in the right overbank. The distance between abutments is approximately 1,400 feet. Bridge 760036 spans the north channel of the Ocklawaha River and has six piers within the river channel. The abutments are located

^{*}Calculated using flood pool surface area determined in ArcGIS.

near the channel banks with a separation of approximately 300 feet. Construction drawings of the bridges were obtained from the FDOT through an exempt document request (Florida Department of Transportation, 1966).

The bridges were modeled as internal connections within the 2D flow area of the model. Bridge piers were included to accurately reflect the impact of the bridge on water surface elevation and flow disruption. Bridge deck elevations were also included to evaluate whether overtopping occurs following a dam breach. Battered piers were modeled with twice the thickness of vertical piers.

3.6 Manning's Roughness Values

A land use polygon dataset was obtained from the SJRWMD geospatial open data portal (SJRWMD, 2012). The dataset was imported into RAS Mapper as a land cover layer and associated with the model. Each land use designation was given a manning's roughness value. Values were determined based on aerial and street view imagery and engineering judgement.

3.7 2D Flow Area

The 2D flow area was used within the model to represent the hydraulics downstream of the dam. The flow area perimeter was extended outward from the floodplain until a terrain elevation exceeding any probable flood wave elevation was reached. A 2D mesh with 100-foot cell size was generated within the flow area perimeter.

The 2D mesh was revised to improve model stability. The mesh was refined to a 25-foot cell spacing along the discharge channel and a break line was included to orient the cells in the direction of flow. Break lines were also added along the crest of State Highway 19 and the two bridge crossings. Near the State Highway 19 bridges, the mesh cell size was reduced to 50 feet and cells were oriented parallel to the highway centerline.



4. Unsteady Flow Data

Between the five modeled scenarios (see Table 1), there are two different unsteady flow conditions. For the normal pool and draw down scenarios, it is assumed that the river system will be experiencing average conditions that are independent of headwater management at the dam. For the max stage scenario, it is assumed that the elevated reservoir level is resulting from a significant flooding event within the river system. As such, this scenario must be treated differently for inflow and dam operations.

The 1D/2D model requires boundary conditions and defined gate openings at Kirkpatrick Dam. The upstream boundary conditions are inflow hydrographs for the Rodman Reservoir and St. John's River. A normal depth boundary condition matching the slope of the St. John's River water surface elevation was set at the downstream extent of the model domain.

4.1 Ocklawaha River Inflows

The USGS operates stream gages both upstream (No. 02243959) and downstream (No. 02243960) of the Kirkpatrick Dam (USGS, 2021). Review of readily available historical data and discussions with Project personnel has shown that the Ocklawaha River experiences varying trends in flow, occasionally experiencing long periods of drought and flood events following hurricanes.

During historical droughts, inflow into the Rodman Reservoir has been reduced to zero and discharge through the dam has been significantly reduced. During periods of low discharge, the downstream reach of the Ocklawaha River has been observed to flow upstream due to tidal effects in the St. John's River. When flows through the system allow, the principal gate operator maintains a minimum discharge of 400 cfs. In HEC-RAS, for the normal pool and draw down scenarios, the minimum flow of 400 cfs was set as a constant inflow to the reservoir. These conditions would be consistent with a typical sunny-day event at the Project.

The flood of record for the Project occurred on September 13, 2017, during landfall of Hurricane Irma. Flow in the river downstream of the dam was recorded at the USGS stream gage. As shown in Figure 1, discharge during this event reached a maximum of 13,100 cfs. This flow is significantly larger than any other historical values recorded since the gage was installed in 2002, with the next largest flow being 7,690 cfs which occurred on August 26, 2008. For the maximum pool scenario, the maximum historical discharge of 13,100 cfs was set as constant inflow to the reservoir.




Figure 1: USGS Gage No. 02243960 Discharge During the September 2017 Flood of Record

4.2 Kirkpatrick Dam Gate Openings

For all five model scenarios, gate opening heights were iteratively adjusted until the gates passed the reservoir inflow, allowing the reservoir elevation to stabilize prior to breaching the dam structure. The principal gate operator stated that it is common practice to have the inner two gates open slightly more than the outer two gates to promote favorable conditions for aquatic life downstream. This operating practice was included in the model gate openings. In the draw down model scenarios, larger gate opening heights were needed to pass the minimum discharge due to a decrease of head in the reservoir. A summary of the gate opening heights for each model scenario is shown in Table 5 below.




Table 5: Model Gate Opening Height

4.3 St. John's River Inflows

The USGS operates a stream gage (No. 02244040) (USGS, 2021) on the St. John's River at the downstream extent of the model domain, adjacent to the Buffalo Bluff railroad crossing. There are no St. John's River stream gages located upstream of the Ocklawaha River confluence. The St. John's River is tidally influenced from the river delta upstream to Lake George. The stream gage records daily fluctuations of flows moving both downstream and upstream following the rise and fall of the tide. The graph below shows an example of this oscillation for the month of September 2021. Due to these varying flow rates, the St. John's River can be considered a level pool.

A level pool is typically modeled with a constant stage downstream boundary condition which maintains the water surface elevation during simulation. During a dam failure model, a large volume of water must be passed through the downstream model boundary. Using a constant stage at the downstream boundary for a dam failure model would constrain outflow and artificially increase water surface elevations within the model domain. Instead, a normal depth slope matching the St. John's River slope was chosen as the downstream boundary condition. This boundary condition will allow the St. John's River to have a riverine profile during dam break.




Figure 2: USGS Gage No. 02244040 September 2021 Discharge

The St. John's River inflow determines the water surface elevation at the Ocklawaha confluence. To determine an appropriate water surface elevation of the St. John's River, the full range of historical stage data from the downstream gage was plotted as a duration curve. The historical data shows that the 50 percent exceedance (median) stage value is 1.0-foot NGVD 29. This value was chosen as the water surface elevation at the Ocklawaha River confluence.




Figure 3: USGS Gage No. 02244040 Historical Stage-Duration Analysis

An upstream inflow for the St. John's River which results in a water surface elevation of 1.0-foot at the

Section 4 Unsteady Flow Data

confluence was determined through multiple iterations of the model. All other values in the model, including Ocklawaha inflow, gate openings, and downstream boundary condition were left constant between iterations. It was determined that a St. John's River flow of 16,620 cfs would result in the desired water surface elevation. This flow was set as a constant inflow for the St. John's River for all five scenarios.

5. Model Initialization

A separate model for each of the five scenarios was created within HEC-RAS. Each model was based on the same geometry data as discussed in Section 3 of this report and individual unsteady flow data as discussed in Section 4 of this report. Model parameters for each scenario are summarized in the table below. The Kirkpatrick Dam was not breached during this modeling phase.

Outer Gate Inner Gate St. John Initial Opening Opening Reservoir River Simulation Reservoir Height **Elevation** Inflow inflow Height Time Model cfs cfs feet feet Days feet Scenario

Table 6: Summary of Initialization Model Parameters

The 2D flow area for each model was started dry, and models were run for a period of 5.5 days. This simulation time allowed water to flow through the system until flows stabilized and the downstream extent of the model reached a constant water surface elevation. Results from the end of these simulations were used as the initial condition for the dam breach models.

The initialization models were also used to provide dam tailwater elevations for each of the scenarios. These tailwater elevations have been incorporated into structural and stability analyses for the Project. The tailwater elevations determined from the initialization models are shown in Table 7 below.

Table 7: Kirkpatrick Dam Tailwater Elevations

Reservoir Elevation	Tailwater Elevation				
feet	feet				
	*45				
	Asi .				
530	779				
25	200				
を接					

6. Breach Parameters

This section of the report documents the procedure that was used to identify applicable regression equations, the sensitivity analysis performed using values developed from each equation, and the selection of breach parameters for each model scenario.

Multiple dam failure mechanisms were considered for this DFA. A common mechanism for dam failure is overtopping of the embankment and erosion of the downstream face until a breach occurs. As indicated in Section 4 of this report, for this analysis it was assumed that the gate(s) would be opened to pass reservoir inflows and maintain the reservoir elevation for each scenario. However, if the gates were closed for an extended period due to mis-operation or mechanical failure, water could flow over the top of the gates when reservoir stage exceeds 21 feet. This is well below the top of the dam elevation (28.3 feet) and thus overtopping is not likely to occur.

Excessive seepage or piping through the dam embankment is a major cause of failure for earthen embankment type dams. Piping failure occurs when seepage through the dam causes erosion, which in turn causes more flow to go through the dam, creating a positive feedback loop and an accelerating rate of material loss until failure occurs. A significant body of data is available regarding this type of failure. Piping failure was considered in this analysis.

A structural or mechanical failure could cause partial or complete failure of the concrete spillway structure. For this analysis, a sudden failure of the entire spillway structure was considered as a failure mechanism. For this mechanism it was assumed that the entire 173-foot-wide spillway width would be breached with vertical side slopes. It is also expected that a failure of the concrete spillway structure would form quickly, so a formation time of 0.2 hours was used.

6.1 Regression Equations

Several researchers have developed empirical regression equations by assembling data from historical dam failures. These equations are commonly used to estimate the breach parameters for dam failure analyses and have been proven to have strong correlation with historical data. The parameters that are determined from these equations are breach bottom width, breach side slopes, and breach development time.

HEC-RAS version 6.0 includes a "Parameter Calculator" within the breach data window of the structure. This calculator takes user inputs and applies them using five different regression equations to create possible breach parameters. The HEC-RAS manual references a dam safety research report written by Tony L. Wahl which discusses the data collection and analysis that occurred to create these equations (Wahl, 1998). These five regression equations are discussed below.

MacDonald et. al. (1984)

MacDonald and Langridge-Monopolis proposed a breach formation factor which is defined as the product of breach outflow volume and depth of water above the breach invert at time of failure. They used this factor and 42 case studies to estimate volume of embankment material removed during the breach. A breach time equation was also created as a function of eroded volume.

$$V_{eroded} = 0.00348 (V_{out} h_w)^{0.852}$$
$$t_f = 0.0179 V_{eroded}^{0.364}$$

Where V_{out} is volume of breach outflow in cubic meters, V_{eroded} is the volume of embankment material removed in cubic meters, h_w is the depth of water above the breach invert in meters, and t_f is the breach formation time in hours.

Breach side slopes were assumed to be 1H:2V and the breach width was determined based on the width needed to provide the eroded material volume. For this analysis the V_{out} term was assumed to be the reservoir volume above the bottom of the breach. An upstream dam face slope of 10:1 and downstream dam face of 4:1 were used (see Appendix B).

Froehlich (1995)

Froehlich revised his previous 1987 analysis in 1995 by adding data for an additional eighteen dam failures, bringing the total to 63 historical failure cases. From this collection of data, he developed new prediction equations for average breach width and time of failure:

$$B_{AVE} = 0.1803 K_0 V_W^{0.32} h_b^{0.19}$$

$$t_f = 0.00254 V_W^{0.53} h_b^{-0.90}$$

Where V_w is reservoir volume above breach bottom in cubic meters, h_b is the height of breach in meters, B_{AVE} is the average width of the breach in meters, and t_f is the breach formation time in hours.

Froehlich did not provide an equation for determination of breach side slopes in his 1995 report. Instead, he suggested that side slope ratios of 1.4 and 0.9 be used for overtopping and all other failure modes, respectively. K_0 is a constant set as 1.4 for overtopping and 1.0 for all other mechanisms.

Froehlich (2008)

Froehlich further revised his equations with an additional 11 dam failure cases in 2008.

$$B_{AVE} = 0.27 K_0 V_W^{0.32} h_b^{0.04}$$
$$t_f = 63.2 \sqrt{\frac{V_W}{g h_b^2}}$$

The K_0 constant was changed to 1.3 for overtopping and 1.0 for all other mechanisms. Also, side slopes were adjusted to be ratios of 1.0 for overtopping and 0.7 for other failure modes.

Von Thun & Gillette (1990)

Von Thun & Gillette used data collected by Froehlich and MacDonald to develop guidance for estimating breach parameters. They proposed that breach side slopes be 1:1 for dams with cohesionless soil. They developed the following relationships:

$$B_{AVB} = 2.5h_w + C_b$$
$$t_r = 0.020h_w + 0.25$$

Where h_w is the depth of water at the time of failure in meters, and C_b is a function of reservoir storage volume. For the Rodman Reservoir, C_b should be 54.9 meters.

Xu & Zhang (2009)

The breach development time from the Xu & Zhang equations include periods of initial erosion and periods of erosion after breach formation. These periods are beyond what is used in the HEC-RAS program and thus result in unrealistically large development times. This method is not recommended and was not used.

6.2 Selected Breach Parameters

A sensitivity analysis of the breach parameters determined by the four regression equations and spillway failure was performed to determine which set of parameters resulted in the largest discharge during the breach. The sensitivity analysis was performed for the normal pool scenario with reservoir at elevation 20.0 NGVD 29 and total reservoir breach volume at failure of 80,500 acre-feet (U.S. Army Corps of Engineers Jacksonville District, January 1966). A summary of considered parameters and the resulting discharge is shown in Table 8 below.

Bottom Formation Peak
Width Side Time Discharge
Method feet Slope hours cfs

Table 8: Sensitivity Analysis of Possible Breach Parameters

The largest discharge resulting from the sensitivity analysis was using the MacDonald et. al. equation. The breach width determined from this regression equation was significantly larger than the other methods and was considered unlikely to occur. For this reason, the MacDonald values were not selected for this analysis and the highest peak flow from the remaining methods was selected.

The breach parameters determined from the Froehlich 2008 equations were used for this DFA. The breach parameters for each model scenario are shown in Table 9 below. The breach centerline was

Section 6 Breach Parameters

placed where the embankment crosses the original Ocklawaha River channel because this is a common vulnerable area, with respect to potential failure, for earthen embankments.

Table 9: Breach Parameters for Model Scenarios

Model	Failure	Initial Piping Elevation	Final Bottom Elevation	Final Bottom Width	Side	Breach Weir	Piping	Breach Formation Time
	Mode		feet	feet	Slope	Coeff.	Coeff.	hours
	新		1	新				
	樹里			- M	ifb			
CONTRACT.					100			337
TEST STATE	13800			B330	190		600	200
THE PERSON	ASSESSED OF					DACE.		
ELIZABETH PROPERTY.								

7. Breach Results

7.1 Breach Results

HEC-RAS shows water surface elevation, water depth, and velocity results as rasters within RAS Mapper. These rasters were post-processed in RAS Mapper and ArcGIS Pro to produce inundation boundaries which graphically illustrate the areas that would experience flooding during a particular dam failure. Assessment locations were placed in critical areas within the model domain. Detailed results were extracted from these locations using hydrographs generated in RAS Mapper. From these results critical information including peak flood wave stage, incremental rise from antecedent conditions, time to peak flood stage, and flood wave arrival time were determined. Flood wave arrival time was defined by the time when the water stage at the location rose 1-foot from antecedent conditions. Time to peak and arrival time are measured from the initiation of breach.

Inundation boundaries were combined with other cartographic data in ArcGIS Pro to create map exhibits. These maps also present the assessment location information generated from the HEC-RAS results. Parcel data was included in the exhibits for use in the affected structure assessment.

HEC-RAS water surface elevation rasters were exported from RAS Mapper and processed in ArcGIS Pro to create incremental rise rasters. These rasters represent the difference in peak water surface elevation of the max pool scenario and draw down scenarios compared to the normal pool scenario. The exhibits can be used by FDEP to assess how a decision to lower the normal pool of the reservoir would affect downstream hazard potential.

Digital copies of the HEC-RAS models are provided with this report.

7.2 Affected Structure Assessment

As part of this DFA, affected structures were assessed to quantify the downstream hazard for each model scenario and to serve as a tool when comparing hazard potential between scenarios. Affected structures were assessed based on parcel data within the model domain and inundation boundaries developed during this DFA. Tabular results of the affected structure assessment, including parcel identification number and owner name, are included in Appendix D. Affected parcels are graphically shown on the inundation maps in Appendix C.

The methodology used to develop the information described above utilized the results of the 1D/2D modeling. This method was repeated for each model scenario. The method is summarized below:

Step 1: Current parcel data in GIS format was obtained from the Florida Department of Revenue (Florida Department of Revenue, 2021) and Putnam County's (Putnam County, 2021) GIS open data portal. This parcel data was imported into ArcGIS Pro along with inundation boundaries developed from the model results.

Step 2: Using tools in ArcGIS Pro, the inundation boundary was used to select all parcels that are partially or fully within the inundation boundary. All other parcels from the county wide data set were removed, leaving only the parcels inundated by the flood wave.

Step 3: The County parcel GIS data includes a "CLASSCD" attribute which is a three number and one letter code designating the property type of the parcel. Parcels with a CLASSCD code ending in V are designated as vacant, meaning no habitable structure is present. Tools in ArcGIS Pro were used to filter the remaining parcels and remove all parcels designated as being vacant, leaving only parcels that have a habitable structure and are inundated by the flood wave.

Step 4: The parcel attributes contain no information regarding structure location within the parcel, and no land survey was conducted to locate structures as part of this assessment. Therefore, in cases where the entire parcel is not located within the inundation boundary, the presence of a structure on the parcel does not necessarily signify that the structure is within the inundation boundary and affected by the dam breach. For each partially inundated parcel, a visual assessment was performed using aerial imagery to verify that the parcel contained a structure within the inundation boundary. Parcels found to have no habitable structures within the inundation boundary were removed from the data set.

Step 5: The parcels remaining after step 4 contain habitable structures within the inundation boundary. These parcels were shaded on the inundation maps and added to the affected structures results table.

The affected structures assessment was repeated for each model scenario. The results, expressed as number of affected parcels, is summarized in Table 10 below. It should be noted that the number of affected parcels is not synonymous with the number of affected buildings. Each parcel may contain multiple structures within the inundation boundary.

Number of Affected
Parcels
Scenario With Habitable Structures

Table 10: Summary of Affected Parcels

8. Assessment of Dam Hazard Potential

The Kirkpatrick Dam is currently listed as a low hazard facility on the web-enabled version of the National Inventory of Dams (USACE, 2021).

The Federal Emergency Management Agency (FEMA) has developed a dam hazard classification system (Interagency Committee on Dam Safety, 2004) which is applied uniformly by all federal and state dam safety agencies. It is important to note that this hazard potential classification does not reflect in any way the current condition of the dam (e.g., safety, structural integrity, flood routing capacity) but instead categorizes dams based on the probable loss of life and impacts on economic and environmental interests. Loss of life is considered probable at locations within the inundation zone that are occupied for long durations, such as homes and businesses. Areas of temporary occupation or recreational areas are not considered with this classification system. Further, no allowances for evacuation or other emergency actions that could remove people from inundated areas are considered.

The FEMA guidelines define three hazard classification levels:

Low Hazard Potential

"Dams assigned the low hazard potential classification are those where failure or mis-operation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property."

Significant Hazard Potential

"Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure."

High Hazard Potential

"Dams assigned the high hazard potential classification are those where failure or mis-operation will probably cause loss of human life."

As part of this assessment, comprehensive models for five different water elevation scenarios were developed. Following the results of the affected structure assessment presented in the previous section, there is evidence of probable loss of life resulting from a dam failure under all five model scenarios. The affected parcels listed in Appendix D contain structures which are expected to be occupied for extended periods or overnight. Neighborhoods located in Stephens Point and Beecher Point experience inundation depths exceeding 4-feet during the maximum pool failure scenario.

Economic losses are expected to occur on affected parcels and may affect private property owners as well as local infrastructure. A significant flood wave moving through the Caravelle Ranch Wildlife Management Area, downstream of Kirkpatrick Dam, has the potential to cause significant environmental damage to the ecosystem.

According to FEMA standards, the Kirkpatrick Dam should be classified as a **HIGH** hazard dam. It is important to note that this hazard potential classification does not reflect in any way the current condition of the dam (e.g., safety, structural integrity, flood routing capacity).

References


- FDEP. (2018). Emergency Action Plan for Kirkpatrick Dam and Rodman Reservoir. Tallahassee, Florida.
- Florida Department of Revenue. (2021). GIS and Cadastral Mapping. Retrieved from Florida Department of Revenue: https://floridarevenue.com/property/Pages/Cofficial_GIS.aspx
- Florida Department of Transportation. (1966, January). Plans of Proposed State Highway State road No. 19. Tallahassee, Florida.
- Interagency Committee on Dam Safety. (2004). Federal Guidelines for Dam Safety Hazard Potential Classification System for Dams. U.S. Department of Homeland Security FEMA.
- NOAA. (2021, September 1). *Digital Coast: Data Access Viewer*. Retrieved from National Oceanic and Atmospheric Administration: https://coast.noaa.gov/dataviewer/#/lidar/search/where:ID=8483
- Putnam County. (2021, November 4). *Putnam County Open Data*. Retrieved from ArcGIS.com: https://pc-open-data-site-pcgis.hub.arcgis.com/search?tags=property
- SJRWMD. (2012, April). *Geographic Information System (GIS) Development Program*. Retrieved from St. Johns. River Water Management District: https://www.sjrwmd.com/data/gis/#basemap
- U.S. Army Corps of Engineers Jacksonville District. (January 1966). Cross Florida Barge Canal Plans Rodman Dam and Spillway.
- URS Corporation. (2006). Rodman Reservoir Dam Failure Flood Boundary Mapping Assessment. Tampa, Florida.
- URS. (September 2015). Kirkpatrick Dam and Spillway Condition Assessment.
- USACE. (2021, April 1). *Kirkpatrick Dam and Rodman Reservoir*. Retrieved from National Inventory of Dams: https://nid.sec.usace.army.mil/#/dams/system/471799/summary
- USGS. (2021, May 3). *National Geospatial Program*. Retrieved from USGS.gov: https://www.usgs.gov/core-science-systems/national-geospatial-program/national-map
- USGS. (2021, November 15). National Water Information System. Retrieved from USGS.gov:

 https://nwis.waterdata.usgs.gov/nwis/uv?cb_00060=on&cb_00065=on&cb_63160=on&format=gif_stats&site
 _no=02244040&period=&begin_date=2010-09-20&end_date=2021-09-27
- USGS. (2021, November 15). National Water Information System. Retrieved from USGS.gov: https://nwis.waterdata.usgs.gov/nwis/uv?cb_00060=on&cb_00065=on&cb_45592=on&cb_45592=on&cb_45592=on&cb_45592=on&cb_45592=on&cb_45592=on&cb_63160=on&format=gif_stats&site_no=02243960&period=&begin_date=2017-04-01&end_date=2021-09-27
- Wahl, T. L. (1998). Prediction of Embankment Dam Breach Parameters: A Literature Review and Needs Assessment.

 U.S. Department of the Interior Bureau of Reclamation: Dam Safety Office.

Appendix A. Location Map








VICINITY MAD


LOCATION MAP


Kirkpatrick Dam Failure Analysis Florida Department of Environmental Protection





Appendix B. Dam Drawings
























































Appendix C. Maps and Exhibits










Mead (Hunt

PURPOSED DISSOSSIES PRESTO ZET ITZUDGEDBIACK SUIZ

No. 70408
STATE OF ST

encon Boods, Limbara Georgewher, Marocet on to 11, GE, FOSA, Fon, HERE, Care at 130, NOVA, USGS, FA, VES



Dam Failure Inundation Map - Pool 14.0

Kirkpatrick Dam Failure Analysis Florida Department of Environmental Protection


Mead Selfunt


(UTE. 1. The terms of fooding and the travel travel strawn on this map are appropriate a set of and solely as a guideline for exhibiting eventalish travel. The terms to frooding and the travel of setting the property of strategies for strategies and the fooding to the recording expect of "the contract" it contains a halfsake should written be recording expected or "thecket" it contains a halfsake should written be recording to enters.

I. Introduction noticed by these to be assumed to be assumed to the second of the second to the second of the seco

Thomas Imbustor bloom (1 des 1923) bear II Resources Willes and Color of the Color

8 TP1 4 1/10009005T1 T03/01/12CH-012/WYS Ubrick 1/1/10





Mead Stiunt

ed p in section of the state of the section of the



Dam Failure Inundation Map - Pool 20.0 (Normal)

Mead

Kirkpatrick Dam Failure Analysis Florida Department of Environmental Protection

Figure 5. The trans of looking and the travel linear shown on this map are approximate and should be used solely as a guideline for establishing eviguation shows. The actual execution zones and be opposite our smaller than the thodological solene for the constraint ance and "Websory" if it goalests a shipper of it constraint is whiteher of it constraints are shipped as sources within the invanishment entereds.


UND WITHOUT THE SERVENDENT INCREMENT INCREDED THE WAS GREEKENDED FOR THE PROBLEM CONFOLIZED BY PRESED & MUTT. Inc. November 2023 I. Downstein betracker, make wedness, roy name, also down class from the Route Gas properly Data Library.

L'ownstein data confidence from Patient Carriers GTS partie.

Coordinate Systems: NAVJ 1983 HARN State Plante Fluidia East (Feet)

Verifald (Debruit NAVJ 1982)

mar Geographica, Scientif controlled Filter Fore, Shills, Lorney, E.M. NOVA J. SON FPS, APS



	Day High Reach.						Sand and Gravel	Ban CGIMA USGA Mario Gomer H. Gis, PDLP Fra HEME, Gomes, LACANAA, USGA LPA, NNA Mario Gomer H. GRA PDLFF, ex. HEME, Correspondent Mario Control (2008) PDLFF, ex. HEME CONTROL (2008) PDLFF,	
	In Technical Control of the Party of the Par	říči	0	Open Land	☐ Park	p	□ Pond □ Ser	S GIN, EDER! ESSE, THERE, GREEGE, LWI, NORE, USE N. NPS, USDA	
	Legend	Airport	_		Cemetery		Golf Course	EST, CCHAR, USGS, Marcon Commer Sectionary, 1965, LP.	
	Land Use Classification Map	Mead Kirkpatrick Dam Failure Analysis	CITUAL FIXITING Department of Later concerned a concerned	spulkicz. 1. Data procesora performed by Hosal & Hunt, Int Movember 2021 2. Couzely knowledy, major nachwey, chy prame, art mee data from the Pfortial Geographic Data Ukrany.	erain data was observed from multiple sources in processed into a that raster. Sources and geoprocessing are detailed in the Enhanters, Dam Pali, and the Sources and geoprocessing are detailed in the Enhanters. Dam Pali	and ure classification class was obtained from ploaten agranges.	ordinate System: NAD 1983 MARN Stat; Plane Florida East (feet)	Verdical Distum: NGVD 1929	
是一种,在1960年,1960年				827	7		8	ş	

MOTELLIZATION CYMPZIDINSTVIO VELITICISOSOSLI: V ANG

Model Geometry

Kirkpatrick Dam Failure Analysis Florida Department of Environmental Protection

1. Hotel genomery has deviced from carrier mounted by Mead 8 Hent. (I.A. November 102)
1. Hotel genomery has deviced from carrier mounted by Mead 8 Hent. (I.A. November 102)
1. Hotel genomery may device the first review of the may are not food from 9 he force for the man was common from the force of the

Coordinate System: NAD 1983 HARN State Plane Florids East (feet.) Vertical Darum: MGVD 1929

Legend

Boundary Condition Line

SH-19 Breakline

Bridge Centerline

Kirkpatrick Dam Centerline [] Modeling Extents Storage Area

TSG, CGARL CSG, MB, Marant Goor H, GLY DHR Len, HERL, Comma, FW, NOAA, FG, EM, NFs Maros Const (LGAs) DHI Lon, HERL SEGGAG, FFT N OST NASA, USAN FP, NESTNIN

Model Terrain DEM

Mead

PRIN, KIRBOGSOOKZELLBY.OLYTECHIGISYAKO_nyuresijunippi

Kirkpatrick Dam Failure Analysis Florida Department of Environmental Protection

Coordinate System: NAD 1983 HARN State Plane Florida East (feet) Vertical Datum: NGVD 1929

SOURCET:

1. Disapprocessing performed by Neba & Hunt, Inc November 2021

2. County houndary, major madway, cry harre, are med data from the Floatia Geographic Data Librah:

2. County houndary, major madway, cry harre, are med data from the Floatia Geographic Data Librah:

3. Franch calls was contracted from mitliopis sources and processed may a final poster, Sources and geoprocessing are becaused in the Nintsworth Dam Pillure

4. Lind lark classification data was obtained from publicly analigible sources.

4. Lind lark classification data was obtained from publicly analigible sources.

Elevation (ft, NGVD29)



ESA, GGINETSKIS, Marco Ferri Le Ger 1991. Esa, 111 Kl., Ger ma, ESA NEXA, F. GART, L. M.S. M. maree are H. Gels 2021. Even (HEM) etwa wirfenge, METEANSE, 12 Geo. 12 V. N.S. F. 32A

Appendix D. Affected Structures Table

LIST OF PARCELS WITH AFFECTED STRUCTURES KIRKPATRICK DAM FAILNE AMAIYSIS

Kirkpatrick Dam Putnam County, Florida Florida Department of Environmental Protection

Parosi identification Number	Dends Kame	The Address	Mazerat Assessment Locardon	A THE
04-11-26-0000-0021-0000	STOKES LANDING LLC	560 STOKES LANDING RD PALATKA	Stokes Island	
D4-11-26-0033-0320-030C	JACKWAC PROPERTIES LLC	606 STOKES LANDING RD PALATKA	Stokes Island	
04-11-26-0000-0020-004C	MERCER JOHARY R + SHERRI 1	604 Stokes Landing RD Palatka	Stokes Island	
04-12-26-9200-0030-4020	MATHEN DAVID K + THEA M H/NV	901 FRONT ST WELAKA	Beecher Point	
26-12-26-0000-0370-0030	SANDS JOSEPH E + REBECCA H/W	122 M HUBERS FISH CAMP ND CRESCENT CITY	Fruitland Cove	
21-11-26-0000-0050-0012	SHELL HARBOUR LLC	148 SHELL HARBOUR RD SATSUMA	River Road	
26-12-26-0000-0540-0000	GUNTHER LA + TAMMY H/W	117 ST JOHNS FISHING LODGE ND CRESCENT CITY	St. John Upstream Extent	
26-12-26-0009-0470-0006	HARTZOG STACY R REVOCABLE TRUST	215 WALKER RD CRESCENT CITY	Fruffand Cove	
26-12-26-0000-0340-0000	HUBER CHARLES JOSEPH	125 S HUBERS FISH LAWP RU LASSCENI LIST	Fruitand Cove	
26-12-26-0000-0340-0040	SANDS JOSEPFFE IV	125 W MUBERS FOR CAMP KINCHESCENT CITY	Programa Comp	
26-12-26-0000-0711-0000	OU KING MEAL PROPERTY MOLDIANOS LLE	LIS CAMP GRONGE NU CARSCENT CITY	Control Course	
26-12-26-0000-0470-0000	MARIZOG STALY R REVOLABLE INUST	THE WALKER WOLFFER LITT	Con factors the extreme Entrant	
26-12-26-2770-0000-001C	CENTERCARVER DAYAN A VOOR WAY	20G C MAYER AN OREGENT OTH	St. John Mastrasm Extent	
10-11-20-1800-1890-1890	THOUGHT DOORS A LOADS E MAN	200 C HAVES AV CRESCEAT CITY	St. John Bostrosen Extent	
7000 0100 0001 9t 11 9t	INCOMES AMOUNT OF CARGO CAR AND CARGO CAR AND CARGO CAR AND CARGO	111 LUMMING AV CRESCENT CITY	St. John Unstream Extent	
13-12-26-7803-1870-005t	REHATE OFFE & CACHILL D. HAW	207 WALKER RD CRESCENT CITY	Fruitiand Cove	
26-12-26-7803-0080-0010	ROBERSON LEONARD R + MEIDI C M/W	107 LUDWIG AV CRESCENT CITY	St. John Upstream Extent	
27-12-26-0009-0930-0040	ASHIEY WILES H + USA A H/W	111 RAMONA RD CRESCENT CITY	Fruitland Cove	
26-12-26-2770-0306-0051	DAY TALLIFER REES + RITA CORNETT H/W	750 NATIONAL FOREST RD 75G PALATKA	St. John Upstream Extent	
26-12-26-7803-0060-0100	ANCHETA GEORGE TRUST	606 BASS DR CRESCENT CITY	St. John Upstream Extent	
26-12-26-7830-0340-0100	SEPTIEN CARLOS 66 + MARIANA H/W	219 PARK AV CRESCENT CITY	St. John Upstream Extent	
26-12-26-0000-0340-001€	WILLIAM DAKIEL B + MEREDITH ! H/W	134 S HUBERS FISH CANAP AID AID CRESCENT CITY	Fruitiand Cove	
23-12-26-0000-0110-0000	- 1	1028 COUNTY RD 309 CRESCENT CITY	Fruitland Cove	
26-12-26-7803-0060-0120		604 BASS OR CRESCENT CITY	St. John Upstream Extent	
26-12-26-7800-0040-0140	HAZELGROVE STANLEY BYRON + SUSAN LEKSH H/VV	118 LUDWIG AV CRESCENT CITY	St. John Upstream Extent	
26-12-26-0000-0780-000K	WHITEHEAD CARL J + VIRGINIA D H/W	TIRST COURT RG 305 CRESCENT CITY	St. John Upptream Extern.	
28-11-26-9220-0000	COOLDGE BRYAN M+AMYD FAMILY 7RUST	134 NORTONS FISH CAMP RUSALSCINA	HUVET WORK	
25-12-26-2770-0000-0094	SCHREIDER RICHARD G + LINDR S WAY	1/2 NATIONAL FUNEST RU 73% PARATRA	Cr. John Moutean Extent	
7007-007-007-07-07-07	COLORES DROW FAMOUR OR NATION (PROS)	124 December of Control of the Contr	Control Comp	
27-12-26-0000-0030-0090	BOSE DAND B	KIND PLACE DISCUSSION COLOR	St. Sohn Bostream Extent	
26.12.26.36.360.0030.011	MANUFACENE D	300 BASS DR CRESCENT CITY	St. John Upstream Extent	
300 000 000 000 30 13 30	DEACISY TRACTIMY	134 HAYES AV CRESCENT CITY	St. John Unstream Extent	
25-13-26-rest-052-0000	ANGI FRY DARACHSE I.C.	1171 COUNTY RD 309 CRESCENT CITY	Fruittand Cove	
25.17.26.0000.0280.004f	ICARES ANCHARE R	120 NATIONAL FOREST RD 29 PALATIKA	St. John Upstream Extent	
27-12-26-0009-0030-0050	BROUWER REGINALD A	115 RAMONA RD CRESCENT CITY	Fruitland Cove	
27.10.26.0000.0060.003€	JOHNSON CARY V	181 BLIFFALD BLUFF RD PALATICA	Downstream Model Extents	
21-11-26-0000-0050-0060	MCGUIRE RANDALL I + ADRIANA BALLESTERO H/W	141 SHELL HARBOUR RD SATSUMA	River Road	
26-12-26-7800-0030-0140	исна "Юзерн Раци	218 PARK AV CRESCENT CITY	St. John Upstream Extent	
28-11-26-0000-0010-003(WALTERS RANDY DEAN	134 EASY DR SATSUMA	River Road	
26-12-26-2770-0000-0080	GALFAS MILTON+FREDERICK GALFAS ET AL	739 NATIONAL FOREST RD 75G PALATKA	St. John Upstream Extent	
26-12-26-7800-0060-0160	WOOLEY HALLEY B JR+MARKDELL C TRUST	129 W PAIM AV CRESCENT CITY	St. John Upstream Extent	
26-12-26-7800-0020-0140	BENTLEY CAMILLA ELAINE	200 BASS DRICHESCENT CITY	St. John Upstream Extent	
26-12-26-7800-0030-0090	ADAMS ROBERT J	117 SHAFFER AV CRESCENT CITY	St. John Upstrezen Extent	
26-12-26-7803-0040-0120		120 LUDWIG AV CRESCENT CITY	St. John Upstream Extert	
26-12-26-0003-0360-0030	HAIR ROBERT + CYNTHIA SIRAMONS HAIR H/W	130 S POBERS PISH CAMP NO CRESCENT CITY	Prumarya Cone	
26-12-26-7800-0040-0060	PAINTER ELSA J LIFE ESTATE REM: MANINA GRILLIU!	ALE PARK AN CRESCENT CITY	St. John Opsonsom Exterio	
27.12.26-0000-0030-033(SPIECHT UAVION + KINNING I IV W	LAST PRODUCTION OF TAKESLESS LAST CONTRACTOR	Ch lodgen threshoosen Entrod	
26-17-26-0880-0770-031	CASA WOLLING ILL	CONTRACTOR DO COCCUMY CONTRACTOR	Englished Cono	
2.7.12-26-1440 0000 0031	LEARTH THE FEATURE OF THE CONTROL OF	746 MATIONER FOREST NO 750 DAI ATER	St. John Unstrazen Extent	
2.11.25.27.77.25.20.25.20.25.27.25.25.27.27.25.27.25.27.25.27.25.27.25.27.27.25.27.27.25.27.27.27.27.27.27.27.27.27.27.27.27.27.	IONICON KARTEW	120 DEAMS CREEK TRU. PALATKA	Dean Creek Road	
26-12-26-2770-0000-0073	COPELY ANDREW R. JR + BRENDA J H/W	756 MATIONAL FOREST RD 75G PALATIKA	St. John Upstream Extent	
26-12-26-7800-0010-0260	JLW RESIDENTIAL LLC	126 HAYES AV CRESCENT CITY	St. John Upstream Extent	
26-12-26-0303-0400-0300	ELLIOTT FREDERICK T + BETHANY A H/N	1965 COUNTY RD 308 CRESCENT CITY	Fruitiand Cowe	
27-12-26-0000-0030-0070	CRAWFORD MICHAEL B + LINDA D H/W	123 RAMONA RD CRESCENT CITY	Fruitland Cove	
33-11-25-0000-0020-0000	LOWENSTEIN PETER E + JAN DENISE H/W	7986 NATIONAL FOREST RD 74 PALATKA	Kirkpatrick Dam	
27-12-26-0000-0030-0030	BELCHER BOBBY I + LISA M H/W	107 RAMONA RD CRESCENT CITY	Fruitland Cove	
25-11-26-0000-0050-0003	SHELL HARBOUR LLC	151 SHELL HARBOUR RD SATSUNA	River Road	
	The state of the s	THE STANDARD CONTRACTOR OF THE STANDARD CONTRACTOR	Complement Column	

			THE STATE OF THE S	- CHOCKER	THORE SEE	Short	ì
Parcel Identification Rumber	Oversor North	Side Address	Consideration County				ı
33-10-26-3610-0000-0690	N. C. L. C.	AND TANKED OF THE COUNTY	St Schn Unstream Extent				L
28-12-26-7800-0020-0081		ALL PARTY BY VALATIVE	Downstream Model Extents				L
28-10-26-0000-0180-0110		JUSTANNIE BU PALATAN	Se John Lestroam Entern				
26-12-26-7800-0060-0050		IJB S HATES AV CRESCENI LI IT	St. South Olssa earth Eatern				I
33-11-26-0000-0200-0000		146 FLORIDIAN CLUB AD WELAKA	Separation		1		1
27-12-26-0000-0030-0120	AN + MICHELLE BOMBA H/W	145 KANNONA NU UNESCENI CIT	Proxising Cove				I
33-11-26-8791-0000-071(/1 CAMERIEE DR WELGGA	Steparens Furth				1
33-11-26-0000-0100-0020	*	112 FLORIDIAN CLUB IN WELAXA	Stephans Pour				Į.
25-12-26-2770-0000-0090		//b Mathonal Forest for Palatan	St. XORIN UPSUFERIN EARTH				I
33-10-26-3610-0000-2140	P+USA J FLOYD (JTRS)	103 ST JOHNS CT SATSUMA	Barremne Creek				I
26-12-26-7800-0020-0190		114 SHAFFER AV CRESCENT CITY	St. John Upstream Extent				I
33-11-26-0000-0350-000C		113 FLORIDIAN CLUB LN WELAKA	Stephens Point				I
27-12-26-0000-0030-0130	IBETH H/W	147 RAMONA RD CRESCENT CITY	Fruitiand Cove	100			J
26-12-26-0000-0540-0010	PENDULUM PROPERTIES LLC	119 CAMP GEORGE RD CRESCENT CITY	Fruitland Cove				Ţ
33-11-26-0000-0240-0000		103 FLORIDIAN CLUB LN WELAKA	Stephens Point			-	T
33-11-26-0000-0380-0000		141 FLORIDIAN CLUB RD WELAKA	Stephens Point				I
33-11-25-0000-0210-0000	W	133 FLORIDIAN CLUB RD WELAKA	Stephens Point				
26-12-26-7800-0060-0080		207 S MAYES AV CRESCENT OTY	St. John Upstream Extent		1		Ţ
26-12-25-7800-0030-0160		214 PARK AV CRESCENT CITY	St. John Upstream Extent				
26-12-26-7800-0040-0170	ROSAS GODOFREDO R + PEGGY B	110 LUDWIG AV CRESCENT CITY	St. John Upstream Extent				
28-11-26-9220-0000-004C	CARTER MELVIN O + SMERAN I. HVW	140 NORTONS FISH CAMP RD SATSUMA	River Road		No.		
33-11-26-0000-0108-0000		144 FLORIDIAN CLUB RD WELAKA	Stephens Point				
33-10-26-3510-0000-0860		110 PCINSETTIA DR SATSUMA	Barrentine Creek				
26-12-26-7900-0060-0020	MOFFPAUM JOHN WADE REVOCABLE TRUST	202 S MAYES AV CRESCENT CITY	St. John Upstream Extent				1
26-12-26-7900-0030-0080	ADAMS ROBERT J	115 SHAFFER AV CRESCENT CITY	St. John Upstream Extent				I
25-12-26-2770-0000-0093	WELL + LAURES	774 MATHOMAL FOREST HD 75G PALATKA	St. John Upstream Extent				
33-11-26-8791-0000-0766	ZIMMEN ARTHUR F 11 + JAMET M/W	76 CAREFREE DR WELAKA	Stephens Point				
33-11-26-0000-0250-0000	DOWN BY THE RIVER LLC	101 FLORIDIAN CLUB IN WELAKA	Stephens Point		9		
27-12-26-0000-0030-014[DITH ANN	151 RAMONA RD CRESCENT CITY	Fruitiand Cove				
33-11-26-8790-0000-0250		25 SCOTT ST WELAKA	Stephens Point				
26-12-26-7800-0030-0150	NN + GARY JAMES W/H	216 PARK AV CRESCENT CITY	St. John Upstream Extent				
33-10-26-3610-0000-2100	SHASTEEN CHARLES E + LINDA M H/W	111 ST JOHNS CT SATSUMA	Barrentine Creek				
28-11-28-0000-0020-0010	KMOTT MARK CALVIN	107 SHELL TRL SATSUMA	River Road				Î
26-12-26-0000-0370-0060	TRUST	114 N HUBERS FISH CAMP RD CRESCENT CITY	Fruitland Cove				
33-11-26-8791-0000-082(82 CAREFREE DR WELAKA	Stephens Point				J
33-11-26-0000-0070-0000	65 દાદ	108 FLORIDIAN CLUB LN WELAKA	Stephens Point			+	1
33-11-26-8791-0000-0920	λ 3 Λ	92 HAPPINESS OR WELAKA	Stephens Point				d
33-31-26-8791-0000-13.2(RALEY SCOTT &	112 MAPPINESS DRI WELAKA	Stephens Point	100			
28-11-26-9720-0000-0011	REDDING WAYNE 8 + VICKY L IVW	132 NORTONS FISH CAMP RD SATSUMA	River Road				
33-31-26-8790-0000-032(HADLEY RICHARD B + JOY A MCGURL- HADLEY H/W	32 SCOTT ST WELAKA	Stephens Point				
33-11-26-8791-0000-0W1C	HONOUR KIRK C+ TINA M H/W	41 SCOTT ST WELAKA	Stephens Point				
33.10.26-3610-0000-0901	LAGASSE WAYNE A + ELMA S H/W	318 POINSETTIA DR SATSUNA	Barrentine Creek				i
33-11-26-8790-0000-0060		6 HOCKEY DR WELAKA	Stephens Point				
33-11-26-8791-0000-0890	JOHNSON CONRAD A JR+KATHLEEN H/W LIFE ESTATE	89 HAPPINESS OR WELAKA	Stephens Point				I
33-11-26-8791-0000-0730	ROGERS EDGAR C + LAWARNA D H/W	73 CAREFREE DR WELAKA	Stephens Fount				
33-10-26-3610-0000-2151		IDI SI JOHNS CI SARSUMA	Barrentine Creek				I
33-11-25-0000-0050-0001	AMU BKALALY A JI KS	LIGO DEANS CREEK 18L TACHTICA	Stankens Briest				
33-11-26-8791-0000-0690	DE CAREFREE DRIVE RE MOLINIOS LLC	112 MADDINECT DRIVEN AND AND	Stephens Point				SI
33-11-20-8/31-UUUL-1131	COORCON VATUR IN	102 CHELL THE CATCHINA	Winger Presid				
AND SELECTION OF THE PROPERTY	CANCORD CTACA + DORN DOE WAW	139 FLORIDAN CLUB #D WELAKA	Stephens Point				
55-11-25-0000-0280-00000 55-11-25-8761-01000-06-21	AUSCEL KERY D + 1 FAM AL MAN	67 CAMEFREE DR WELAKA	Stephens Point				
22.11.26.6064.0000.11006	CLETH DOWN + (ANICE NAV	111 HAPPINESS DR WELAKA	Stephens Point				96
33-11-26-0000-0270-0000	HIPPENSTEEL RANDY C+LISA R M/W+AMANDA R (JTRS)	149 FLORIDIAN CLUB ND WELAKA	Stephens Point				
33-11-26-8791-0000-1290	SCHWAB RANDALL E + JANINE W H/W	130 PARADISE DR WELAKA	Stephens Point				
33-11-26-0000-0290-0000	SKAGGS FRANKE	105 TALL PALMS IN WELAKA	Stephens Point				
33-11-26-8791-0000-1071	GENTRY DONALD R+ TAMMIE L H/W	108 HAPPINESS DR WELAKA	Stephens Point				
33-11-26-8791-0000-1621		161 MODWLITE DR WELAKA	Stephens Point				ĺ
	STAHLIN/SORENSEN LAND TRUST WP+EM STAHLIN+DD+CL SCREWSEN			F			Ų.
33-11-26-8791-0000-1660	TASIS WANTED FOR EN WIND SET	100 MUCMITTE OR WELARA	Stochast Point				
33-11-26-8791-0000-1300	NUCLEI PARMICE INCOM	1163 COLIMIY AD 309 CRECENT CITY	Friftand Cove				
26-12-26-0000-0491-000A	DIS ARREST FROM TRUMENT FROM TRUME CON-	AND LOUIS 1 1st and business.	Transfer or the second	Market Street			4

LIST OF PARCELS WITH AFFECTED STRUCTURES KIRKPATRICK DAM FAILURE ANALYSIS

Kirtpatrick Dam Putnam County, Florida Fforida Department of Environmental Protection

braced belontification Manhor	Parente Monat	She Addinose	Leachtering
28 19 26 0000 0012 0010	VICEBO ROY HE ESTATE	107 HEYRITA IN PALATEA	Downstream Model Extents
11-26-8791-0000-079C	MCCUIONEN TREE + FEANEVA WAW	79 CAREFRE DR WELAKA	Stechens Point
33-10-26-0000-0012-0050	CRIDEN DONALD G + CHERNIEF G HAW	211 WOODBURY TRE SATSUMA	Downstream Model Extents
23 11 25 0701 0000 0245	SABCON DOWNERS A - PURDS - LAAR	25 COURT CT WICE AKE	Ctanhane Point
33.11.26.8791.0000.1500	PETER LARRY D + S LOIL MAN	1150 PARADISE DR WELAKA	Stephens Point
33-11-26-8791-0000-2000	PETERSON REA CHARLENE	200 SPORTSMAN OR WELAKA	Stephens Point
5-8791-0000-1190	MALL DENNIS P	119 Paradise dr Welaka	Steptiens Point
33-11-26-8791-0300-2050	DEKLE DOROTHY M + JOHN R W/W	205 SPORTSMAN DRI WELAKA	Stephens Point
35-11-25-4KKK-0020-4KK	UNITED STATES OF AMERICA	ASSUES STATE RULES PARATRA	Section Section
33-11-26-8701-0000-1900	ROBER THOMAS P + PATSY A M/W LIFE ESTATE	190 SPORTSMAKE DR WELAKA	Steelbert Point
33-11-26-0731-0000-1350 33-11-26-6791-0000-1350	GARRIER TANAMIE W. + VICKIE F. W.B. TERS	114 TADDINGCOD WELDER	Standbars Postat
. 0000.0012.0036	MADDIC OKTORUK 1 1 YOUN D LAAM	215 WOODGEST THE CATCOMA	Descriptions Mandel Extens:
33-11-26-8791-0000-1916	LATHBURY SEAR L	191 SPORTSMAN DR WELAKA	Stephens Point
	HAGGARD WILLIAM ANDREW LIVING TRUST WILLIAM ANDREW		
33-11-26-8791-0300-0740	MAGGARD TRUSTEE	74 Carefree Dr Welaka	Stephenis Point
33-11-26-8791-0000-1540	CZEPIEL RICMÁRD J LIFE ESTATE	154 MOONLITE OR WELAKA	Stephens Point
33-11-26-8791-0Ki0-1370	RENEROE MICHAEL B + PERMY R M/W	157 PAKRUSE UN WEERAG	Sterpoveries POSTIC
21.11.76.8791.0006.02%	CCACCC CRANKIE W. + DERBE C. HAW	42 SCOTT ST WEIGHT	Stephens Point
33-10-26-0000-0011-004E	PICKENSIOER	125 WOODBURY TRE SATSUMA	Dawastream Model Extents
26-11-26-0000-0270-0000	SAPP WILLARD J.R.	108 MATIONAL FOREST RD 29 PALATICA	St. John Upstream Extent
33-11-26-8791-0000-2120	CHIODO RUSSEL L	212 Sportsman dr Welaka	Stephens Point
33-10-26-0000-0011-0014	HARRISON MICHAEL CHARLES + KIMBERLY SUZAN M/W	128 WOODBURN TRL SATSUMA	Devenstrazion Model Extents
33-11-26-8791-0300-0880	JOHNSON CONRAD A JR+KATHLEEN D HAW LIFE ESTATE	BB HAPPINESS DR WELAKA	Stephens Point
33-11-26-8791-0000-2010	CASTRILLO VICTOR + AMY L H/W IT/RS	ZOU SPORTSMAN OR WELAKA	Stephens Point
0000-0015-0050	HUDSON PATRICIA P + RONALD D W/H	219 WOODBURY TRL # URIT 1 SATSUMA	Dokenstream Neode Exterits
33-11-26-8791-0006-1460	DICAGODO MENTINE LIFE ESTATE DICAGODO MENTINE A CODIDOR TORICIAMA A CODI	146 PARALISE UN WELARA	Mephens Pons
33.11-26-8791-0000-1010		101 Happiness or Welaka	Stephens: Point
33-11-26-8791-0000-1700	MASON RICKIE + KAREN H/W	170 MOCRUITE DR WELAKA	Stephens Point
33-11-26-8791-0000-0700	FAULTINER GEMA H+ HARRY P JR W/H	70 CAREFREE DR WELAKA	Staphens Point
33-11-26-8791-0000-2160	PORATH MICHAEL L+ LAURIE J M/W	216 SPORTSMAN OR WELAKA	Stephens Point
3791-0000-1710	GREGROW DENNIS R + DIANA WW	171 MOONLITE DR WELAKA	Stephens Point
33-11-26-8791-0000-1680	BURKHART WAYNE	168 MOONLITE DR WELAKA	Staphens Point
33-11-26-8791-0000-1470	CONTENT AND E + CARET A MIVE	LOV PARAMETER DA VELICIA	Charles of College
33-11-70-8/91-4500-2190		129 SPORTSWAY ON WELANDA	St. John Unstroam Enlant
33.10.26.0000.0030.0061	MAIDHRUSHERMANE + GENEVA B WW LIFE ESTATE	323 E BUFFALO BILIFF RD SATSUMA	Exremine Creek
	SANFORD STEVE + ROBIN POE H/W + DEVIN W + ELZABETH I SMITH		
33-11-26-0000-0190-0000	жж	137 FLORIDIAN CLUB RD WELAKA	Stephens Point
28-10-26-0000-0180-0080	OWERS RANDY H	124 KRANTZ RD PALATKA	Dewmstream Model Extents:
33-11-26-8791-0000-0780	FAUIKNER RICHARD R + KAV H H/W	78 CAREFREE DR WELAKA	Steamberrs Point
3790-0000-0260		26 SCOTT ST WILLARA	Stephens Point
38-12-26-7800-090-010K	HOXWORTH STEPHEN ANDREW JR ET AL (TRS)	130 WALKS AW CRESCENT CITY 20 CONT STAND AWA	St. John Upstream Extent
33-11-26-8791-0000-0390	WINE D BROWN	SUSCOUNT OF WELPERA	Stephens Point
33-11-26-8791-4KIKI-1UKI	MEMAFFE WARY EAT	1100 PERFERENCES UM WELKEN	Description of Comment
28-10-26-0003-0180-0020	CADAKE DAIR E	115 KRAWIE BU FARAKA 115 KRAWIE BO PALATE	Director of the Standard Extension
23 10 75 0000 0010 0000	FARMER PAUL E	THE BRICKS IN DATABLE	Stocking februari
33-10-26-0008-0010-0500	OMERC PICEN SANDATER WIGHTER PROBERT CONCHINERS	221 DEANS CREEK RD PRIATION	December Research
-5610 0000 - 211	SCHWER GAIDE	107 ST JOHNS CT SATSURA	Name at the Creek
33-10-20-5040-0000-2414 33-11-35-0000-0000-0014	MANAGE TECHNICA OF CTENERS OF CTENERS	224 DEANS CREEK RUPALATKA	Dean Creek Road
33-10-26-36f0-0000-213f	FLOYD GENEVIEVE P + LISA J FLOYD (JTRS)	105 ST JOHNS CT SATSURIA	Sarrentine Creek
38-12-26-7800-0090-0210	HASIEBALIC	152 HICKS AV CRESCENT CITY	St. John Upstream Extert
33-10-26-0006-0040-0020	WEICHERT BRADLEY A + RITA J H/W	319 E BUFFALO BLUFF RD SATSUMA	Barnentino Creek
33-11-26-8791-0000-1820	HOWARD EDGAR PAUL + JANET N H/W	182 SPORTSMAN DR WELAKA	Stephens Point
33-11-26-8791-0000-1920	STAINAKER WALTER	192 SPORTSMAN DR WELAKA	Stephens Point
33-11-26-8791-0000-1520	THE RESERVE THE PARTY OF THE PA	and the definitions of the left spile that it was	O Stephens Point
33-11-26-UKKU-0305-UUK	BANK PKEUERICK + KMUNUA K M/VV	140 FLORISIAM LLUB RU WELPSA	Suegonetts Proges
AND LEKELINGER	A HANDE SET ASSESSED AS IN ADMINISTRAL AND A PARTY AND	EPOT O DESCRIPTION OF THE PROPERTY AND ADDRESS.	NAME AND ADDRESS OF TAXABLE PARTY.

LIST OF PARCELS WITH AFFECTED STRUCTURES KIRKPATRICK DAM FAILURE ANALYSIS

Kirkpatnek Oam Putnam County, Florida Florida Department of Environmental Protection

		Eten deliberation	Meanest Assessment Locator	A flex sad in Lindel	Scenario:
CATALOG ENGINEERING WILLIAMS	WILLIAMS CLAUDE + SHIRLEY HAVE LEST REM: DENNIS CLAUDE				
28-11-26-9220-0000-0110	WILLIAMS	150 NORTONS FISH CAMP RD SATSUMA	River Road		
26-12-26-7800-0070-9031	BURRELL SMARON C	119 LUDWIG AV CRESCENT CITY	St. John Upstream Extent		
38-12-25-7800-0090-0080	ALEXANDER VIVIAN J	126 HICKS AV CRESCENT CITY	St. John Upstream Extent	200 200	
33-11-26-8791-0000-0770	ODWYER WILLIAM J	77 CAREFREE DR WELAKA	Stephans Point		
33-11-26-0000-0180-0000	DOWN BY THE RIVER LLC	106 FLORIDIAN CIUB LN WELAKA	Staphens Point	SIN SIN	
33-11-26-8791-0000-1560	ACKLAND KAY I REVOCABLE LIWING TRUST	156 MOONLITE OF WELAKA	stephens Point		
33-11-26-8791-0000-1280	DEAN SOUGLAS A + DANA H/W	123 PARADISE DR WELARA	Megners Point		
33-11-25-8791-0000-0910	MAHAN JAMES J LIFE ESTATE	91 HAPPINESS DR WELARA	Mephero Point		
33-11-26-0000-034/0-000C	MCCULLERS SEAN DANIEL + MELISSA M BIBLE (17RS)	145 FLORIDIAN CLUB ND WELAKA	Stepmens Fount		
33-11-26-0000-0330-000K	WIGAND HARRY J + JEANNE E H/W	147 FLORIDIAN CLUB ND WELAKA	Stephens Point		
28-11-26-9220-000-0050	KIMBROUGH MARVIN WINSTON LIKE ESTATE	142 NORTONS FISH CAMP RD SATSUMA	KIVET HOSID		
28-10-26-0000-0010-0000	BROTHERS WILLIAM E + KATHLEEN L H/W	318 PENIEL CHURCH RU PALATRA	CONTINUED INDOMENTED		
33-11-16-8791-0000-1410	PATRICK DEBRA G	141 PARADOS UN WELARA	Stephens Point		
38-12-26-7800-0090-0190	BARRUS BRIAN	148 HICKS AV CRESCENT CITY	M. John Opstream Extent		
	DAUGHERTY MARTHA R	ZUZ SPUKISMAR DA WELARA	Stephens Point		
33-11-26-8791-0000-1620	PAGANO KENNETH I + DYANE H/W	162 MUMITEUM WELDER	Checkens Doint		
33-11-26-8791-0008-1640	PITTMAN IN DIANNE + LANDER WILSON W/H	104 IMDUNITED WELARA	Charle Daint		
33-11-26-8791-0000-0400	JOHNS RICHARD A SR + TERESA L H/W	40 SCULL ST WELAKA	Stephene Fumi		
33-11-26-8791-0006-2070	BRIM WILLIAM F + KATHLEEN H N/W LIFE ESTATE	207 SPORTSHAIN UR WILLARA	Stephens Point		
33-11-26-8791-0000-1420	MCDANIEL ROY BRUCE + SUSAN P H/W	142 PARADISE DR WELAKA	Stephens Point		
33-11-26-0000-0104-000C	COTTON ANTHONY 5 + SUSAN H H/W	103 TALL PALMS LN WELAKA	Mephens Point		
33-11-26-0000-0108-0000	LOGAN JOHN BRUCE LIFE ESTATE	142 FLORIDIAN CLUB RD WELAKA	Staphens Point		
33-11-26-8791-0000-0330	OBRIEN CHRISTOPHER L + CYNTHIA L H/W	33 SCOTT ST WELAKA	Stephens Point		
33-11-26-8791-0000-1760	WINDSOR KIM D	176 MDONLITE DR WELAKA	Stephers Point		
33-11-26-8791-0000-1380	ROUNTREE USA + HARRY W/H	138 PARADISE DR WELAKA	Stephens Point		
33-11-26-8791-0000-1090	LECREUX THEODORE J + LEIGH M H/W	109 HAPPINESS DR WELAKA	Stephens Point		
33-11-26-8791-0000-1970	KILCHRISS DORIS HEIRS OF	197 SPORTSMAN DR WELAKA	Stephons Point		
33-13-26-8790-0000-0270	CHRISTOPHERSON CHAD + LOLA H/W	27 SCOTT ST WELAKA	Stephens Point		
33-11-26-0000-0370-0000	MCCULLERS DANIEL 8 + CAROLYN L H/W	143 FLORIDIAN CLUB AD WELAKA	Stephens Point		
18-12-26-7800-0090-014(ROBINSON MAGNOLIA	138 HICKS AV CRESCENT CITY	St. John Upstream Extent		
38-12-26-0000-0040-0010	PETERSON RAND G + DEBORAH A M/W UFE ESTATE	123 HICKS AV CRESCENT CITY	St. John Upstream Extent		
33,11,26,8791,0000.1930	TREECE FAMILY REVOCABLE UVING TRUST	193 SPORTSMAN DR WELAKA	Stephens Point		
13,11,25,8791,10000,096£	EISMAN JOINT REVOCABLE TRUST	96 HAPPINESS DR WELAKA	Staphens Point		
33.11-26-8791-0000-2030	RUNNERSTROM THERESA M	203 SPORTSMAN DR WELAKA	Stephens Point		
33.11.26.8791.0000.1220	HANLON KATHLEEN ANN	122 PARADISE DR WELAKA	Stephens Point		
33-11-26-8791-0000-0620	LANEWORMA	62 CAREFREE DR WELAKA	Stephens Point		
39.10.26-3610-0000-2070	JOHNSON SCOTT A	117 ST JOHNS CT SATSUMA	Barrentine Creek		
33-11-26-8791-0000-1250	BUSH PAMELAK	125 PANADISE DR WELAKA	Stephens Point		
33.11.26-8791-0000-2150	BERRY RICHARD E + DEBORAH A WEYER HIVE	215 SPORTSMAN OR WELAKA	Stephens Point		
33.11-26-8791-0000-2170	KELLY TIMOTHY P + SALLY J H/W	217 SPORTSWAN DR WELAKA	Stephens Point		
27-12-26-0009-0030-0060	IMAGE PROPERTIES LLC	119 RAMONA RD CRESCENT CITY	Fruitland Cove		
26,12,26,0000,0260,0000	LYNN BELINDA SEPARATE PROPERTY TRS1	101 NATIONAL FOREST RD 29 PALATKA	St. John Upstream Extent		
38-12-26-7800-0090-0030	LARION WILLIAM M + CANDACE CH/W	118 HICKS AV CRESCENT CITY	St. John Upstream Extent		
39-10-76-3610-0000-2020	THE POWDER TRUST	127 ST JOHNS CT SATSUMA	Barrentine Creek		
33-11-26-8791-0000-139C	CRABTREE NICOLE + MICHAEL F W/H	139 Paradise dr Welaka	Stephens Point		
33-11-26-8791-0000-1600	LEWIS DWIGHT + LISA H/W	160 MOGNUTE DR WELAKA	Stephens Point		
33-11-26-8791-0000-1330	BEHRENDT ROBERT H + BARBARA H M/W	133 PARADISE DR WELAKA	Stephens Point		
39-10-26-3610-0000-2090	PLISKA FRANK III + HOLLY S PLISKA (ITRS)	113 ST JOHNS CT SATSUMA	Sarrentine Croek		
33-11-16-8791-0000-1751	YOHO CARDLYN M	175 MOONLITE DR WELAKA	Stephens Point		
33-11-26-8791-0000-0980	WRIGHT MARLEEN H	98 HAPPINESS DR WELAKA	Stephens Point		
33-11-76-8791-0000-1840	WONDRSKI JANET K + WALTER CHABOUDE (ITRS)	184 SPORTSMAN DR WELAKA	Stephens Point		
28-10-26-0000-0080-0000	BEMNETT BRETT M + CHELSEY M M/W	350 PENIEL CHURCH RD PALATKA	Downstream Model Extents		
28-10-26-0000-0180-0060	WALSON RAE LAUREN + NE ASHA NEOMI HUNTER	142 SESAME ST PALATKA	Downstream Model Extents		-
33-11-26-8791-0000-0600	SMITH BRUCE A + JANET Y H/NY	60 CAREFREE DR WELAKA	Stephens Point		100-100-1
33-11-26-8791-0000-0630	LEWIS FRANCIS T + PEGGY A H/W	63 CAREFREE DR WELAKA	Stephens Point		
	TUCKEN TIMA+CHARLES REVOCABLE TRSTS TINA TICKER+CHARLES	A CONTROL OF LANCE AND A	Grandway Polist		
33-11-25-8790-0000-0300	TUCKER TRUSTEES	SCOULS WELKING	Ramantine Crask		
33-10-52-3610-0000-013(GREEN WELLE J	THE DECOMES DOINT OF WEIGHT	Seether Point		
	TORRESON TOREN A SA TOURING TO W	AND THE FAIR OF THE ROSATSUMA	Downstream Model Extents		
33-10-28-0000-0011-0013	TANGED ON TOWN	27 SCOTT ST WELAKA	Staphers Point		
33-11-20-6/91-UANN-USOL	I HALLON LALASTAN				

Downstreem Model Extents St. John Upstream Extent St. John Upstream Extent St. John Upstream Extent Barrentine Creek Boacher Poin 1 PALMETTO ST WELAKA 106 WILLIAM BURSTRAN DR. CRESCENT CITY 154 BEECHES POINT ON WELAKA 1134 BECHERS FOUNT ON WELAKA 1138 BUCHENS FOUNT ON WELAKA 140 PARADISE DR WELAKA 213 SPORTSMAN DR WELAKA 123 BECCHESS POINT DR WELAKA 778 MATIONAL FOREST RD 75G PALATIKA 122 SAUGFER AV CRESCENT CITY 173 MOOWLITE DR WELAKA 116 WILLIAM BARTPAM DR CRESCENT CITY 186 SPORTSMAN DR WELAKA 135 PARADISE DR WELAKA 1075 FRONT ST WELAKA 104 RVER BEND CT # BLDG A WELAKA 104 VHILLIAKA BARTRAKA DR CRESCENT CTTY 108 WILLIAM BARTRAM DR CRESCENT CITY 124 PARADISE DR WELAKA 221 HERRITS DR. SATSLINAA 122 WILLIAM BARTRAAN DR. CRESCENT CITY 128 PARADISE DR WELAKA 120 ROGERS IN PALATKA 575 CARAVELLE FARMS ND PALATIKA 223 RIVER BEND PL # BELDG D WELALKA 100 CAMPELILA DE NSTOSTANA 133 RIVER BEND PL # 8:205 E WELALKA 223 HERNATS DR SATSUNA 104 NATIONAL FOREST RD 29 PALATICA 123S COUNTY RD 309 CRESCENT CITY 146 HICKS AV CRESCENT CITY 29 SCOTT ST WELAKA Sine Address 259 HERATIS DE SATSURAE 162 BEECHERS POINT DR WELAKA 209 HERATIS DE SATSURAE 121 HERAMIS DE SATSURAE 117 ST JOHNE CT SATSURAE 110 WP PALM AV CRESCENT CITY 325 e Buffalo Bluff no Satsuma 163 BEECHERS POINT OR WELAKA 144 MCKS AV CRESCENT CITY 136 BEECHERS POINT DR WELAKU 148 FLORIDIAN CLUB RD WELAKA 103 HAPPINESS OR WELAKA 126 PAKADISE DN WELAKA 158 MOONLITE DR WELAKA 9 HOCKEY OR WELAKA 108 DEXTER CT CRESCENT CITY 209 SPORTSMAN OR WELAKA 210 SPORTSMAN OR WELAKA 208 SPORTSMAN OR WELAKA 149 BUCHANAN CIR SATSUNAA 229 SPORTSMAN DR WELAKA 172 MOCHLITE DR WELAKA 227 HERMITS OR SATSURIA 121 TERONDA RD WELAKA 87 HAPPINESS DR WELAKA BOS FRONT ST WELAKA SEITA PATRICIA I REVOCABLE TRUST PATRICIA I SEITÄ TRUSTEE SPEAS CARON LIFE ESTATE FERCH JOSEPH + THOMAS SLAVIK + SHAWIN PATCH COLGAN LEFFREY M + MAICHEE HVW TOLLE DAVID RUSS + CYNTHA. S HVW SHARP GARY L-KARIN E HVW-GARRETT T SHARP LITES SIMTH LESUE ANN CONTAGE RICHARDE E HANIS C N/W STARLING RICHARDE + JOHN KARRUS + MAX I (TTRS) BRADBERRY VECTOR 4 - DELANNE H/W MAL SHARON B + THOMAS D W/H THTF/FWCC CARAVELLE RANCH WALDLIFE MIGHT AREA SEASHORE GREGORY F+MARIORIR A TRUST SCOTT ROBERT ALAN + MARY ANN EDWARDS H/W VICCARTY ROBERT A + PAULA WYW PRINE THOMAS CHARLES + CHARLOTTE LYNN H/W DOYLE THOMAS 5 + PAMELA ANN MONROE (ITRS) DOWAGALSKI ROBERT GERARD COURCMESNE SCOTT E+SUSÁN C BARNES (JTRS) HARR JOHN + ELLA HVW Torrey derek richard + domna kaye H/Vs RICHMAR GREGORY PAUL + CATHY LYNK H/W PENDLETON RONALD DAVID + CAROLE F H/W HOLZDERBER DONALD J + PHYLLIS C H/W BEECHERS POINT CONDOMINIUM OWNERS GILES BARBARA LLOYD REVOC TRUST SAYDER TINA J + JAMES H WILLKINS (STRS) MCGEE ROBERT L+ DOWNA H JIMMERSON MORTON PATRICIA A + PAUL L W/H HUNSERFORD KENNETH W + SALLY ! H/W MARONEY MICHAEL T + LYNN A MARONEY YAN BELINDA SEPARATE PROPERTY TRST SPRINKLE TODD LEE + JERRIE DANA H/W AU CARL N + BETTY A H/W LIFE ESTATE ORLEVITCH CHRISTOPHER + JOAN H/W SCHLITZ CHARLES + MARIA VEIT (JTRS) BREEDEN MAYMARD J SR LIFE ESTATE SCHROOR BARRY D + VICKI L H/W L EST WILKINSON BARNEY A HEIRS OF PEELER W RENEE REVOCABLE TRUST Sarnon William I + Tammie H/W MARNER MICHAEL + PATRICIA M/W WOODMAN WILLIAM S II JARTER MELVIN O + SHERAN L H/W HEMMY ARTHUR + MARSHA H/W SENGSTAKEN DAVID + KERRI H/W ADGETT JAMES RAY LIFE ESTATE STALDER RICKY L + FELICIA 30 H/W PSHONICK DAVID + JOAN B H/W PHILIPS JOSEPH TRAVIS EMERSON WILLIAM MICHAEL IR MADDEN JOSEPHINE GARMON DONALD JOHN JR LICKEY ADRIENNE ATKINS WCLENDON BRANDON VEWMAK HERSCHEL BOLLES MONTA M CLIDIO KATHLEEN 25-12-26-2770-0000-009; 26-12-26-7800-0020-016(33-11-26-8791-0000-103(35-11-26-8790-0000-0080 36-12-26-7800-0090-0170 40-12-26-0530-0000-0030 33-11-26-8791-0000-1720 37-12-26-6085-0930-0130 40-12-26-0530-0500-0110 40-12-26-0000-0230-0011 39-11-26-8234-0040-0170 38-12-26-7800-0090-0186 33-11-26-8790-0000-0296 33-10-26-3610-0000-0266 nool Identification Numb 33-10-26-3610-0000-018C 33-10-26-3610-0000-018C 39-10-26-3610-0000-197C 33-11-26-0000-0260-0300 37-12-26-6085-0020-0110 33-11-26-8791-0000-1240 13-11-26-8791-0030-135(13-11-26-8791-0030-209K 13-11-26-8791-0030-208(13-11-26-8791-0030-208(45-11-26-8791-0000-229C 40-12-26-0000-0210-000C 40-12-26-0095-0010-104C 37-12-26-6085-0010-013C 10-12-26-0530-0010-100C 10-26-3610-0000-0410 35-11-26-7800-0070-0140 33-11-26-8791-0000-1400 33-11-26-8791-0000-213C 3.11.16-8790-0000-0050 -10-26-3610-0000-038K 10-12-26-0530-0000-0150 -11-26-8791-0000-1260 3-11-26-8791-0000-158 3-12-26-0030-0276-0300 3-11-26-8791-0000-087 0-12-26-0530-0000-0280 12-26-0000-0000-026 12-26-6085-0020-0080 -11-26-8791-0000-1860 11-76-8234-0040-0250 -10-26-0000-00030-0096 11-26-0000-0010-0510 10-11-26-0530-0010-2230 13-10-26-3610-0000-0670 10-12-26-0530-0020-1330 33-10-26-3610-0000-0240 1.12-26-9200-0010-001 3-11-26-6790-0000-028 -11-26-0000-0260-002

LIST OF PARCELS WITH AFFECTED STRUCTURES KIRKPATRICK DAM FAILURE AMAIYSIS

Kirkpatnek Dam Putnam County, Rorida Florida Department of Environmental Protection

			the state of the state of	
Partal Mantification Number	Outside Name	SOUR ACCUSES	Bace hot Priest	
-12-26-0000-0180-0014	CARTER PATRICIA 4 44US	114 FORM SOUTH ON WELLAND	Stanbors Point	
11-26-8791-0000-1510	MODULIN LEGIST W	TOTAL EDON'T CTURE AKA	Reecher Point	
40-12-26-0000-0190-0030	SCHERWINGS, MARKY 5 + LINE FIRS 5 V V	117 PINES SEND PLACE CARLAGE	Beerher Point	
WIT-01/0-0500-07-71-08	TOTAKO CHANGO NOVALO SA	TO WORK AV CONCENT CITY	St. John Unstream Extent	
1/10-0/00-000/-07-21-05	EARLY COLORS A MARKON CHARL	116 HVER BEND PL # BIDG CWELAKA	Beecher Point	
TOTAL PROPERTY OF THE PROPERTY	CONTRACOUNTATION	248 WHITMEY ST SATSJIMA	Whitney Street	
23-11-20-0000 000 0000 0000	MC CCH POMETU D. A SUN EV AZ LIVA	200 CARATOGA DA SATSUIMA	Biver Road	
39-11-60-0400-0003-0011	TOCACLISC LACK D + CHISHEY I WANTING DOTATE	123 ST JOHNS CT SATSUMA	Barrentine Creek	
53-10-10-3010-000-5041 54-10-10-3010-000-5041	LINCOM BOWALD D. DATRICLA D M/W	113 MVFR BEND PL # BLDG B WELAKA	Beecher Point	
1511-0200-0520-07-71-05-05-07-71-05-05-05-05-05-05-05-05-05-05-05-05-05-	PRINCIAL COMMIT AL + CHINDAL FLAIME	179 RIVER BEND PL # BLDG E WELAKA	Beecher Point	
40 12 76 0620 0000 0157	I AMPENIE CHASIES + RETA MAN	164 BEECHERS POINT DR WELAKA	Beecher Point	
JPD/ 0000 1025 35 11 25	BOWD BERRY TRICT	94 HAPPINESS DR WELAKA	Stephens Point	
22-11-26-8751-0000-1643C	PARATNET INVESTORS 11C	143 PARADISE DR WELAKA	Stephens Point	
22.11.26.9701.0600.180f	CIELDS SHERRIY + WILLIAM P ALLMAN (ITRS)	180 SPORTSMAN DR WELAKA	Stephens Point	
22 14 25 8701 0000 205C		206 SPORTSMAN DR WELAKA	Staphens Point	
33.11.26.8791.0000.20MC	MOLTON ROBERT	204 SPORTSMAN DR WELAKA	Stephens Point	
37-12-26-6085-0020-0200	MCCOLLUM JAMES M + LINDA & H/W	162 MOUNT ROYAL AV CRESCENT CITY	Fruitland Cove	
33-11-26-8791-0000-1880	SPORTSMANS HARBOR COMMUNITY CLUB	188 SPORTSMAN DR WELAKA	Stephens Point	
45-11-26-8791-0000-2320	CLEMENTS JACK + CAROLYN H JOHNT TRUST	232 SPORTSMAN DR WELAKA	Stephens Point	
33-11-26-8791-0000-0800	FALESKIE FAMILY TRUST	80 CAREFREE DR WELAKA	Stephens Point	
40-12-26-0530-0000-017(STEVENS ROBERT GARY + LINDY CLEMONS H/W	166 BEECHERS POINT DR WELAKA	Beecher Point	
39-11-26-0000-0063-0000	IACKSON GEORGE F + PATRICIA D H/W	311 SARATOGA DR SATSUMA	River Road	
40-12-26-0000-0400-0000	MARTY NATHANIEL + CHELSY L H/W	105 TERONDA RD WELAKA	Beecher Point	
33-10-26-0000-0030-004;	PARRISH RICHARD M + YVORNE C H/W	121 CODY DR SATSUMA	Barrentine Creek	
41-12-26-9200-0010-0020	KIELAS MICHAEL ANTHONY + ESTELLA J FRANSBERGEN	603 FROMT ST WELAKA	Beecher Point	
37-12-26-6085-0010-0150	CHANDLEE SUSAN M	113 WILLIAM BARTRAM DR CRESCENT CITY	Fruitiand Cove	
45-11-26-8791-0000-2410	GEISEL PROPERTIES LLC	241 SPORTSMAIN DR WELARA	Sugmens rount	
37-11-26-0000-0100-0000	RODEMEAVER BOYS RANCH INC	380 BOTS RAINCH RO PALATICA	Withing Street	
33-10-26-3610-0000-0620	BOVETT RITA COLLINS	112 CAMELIA DA SATSUMA	Barrentine Creek	- 126 - 62E - 1
39-10-26-3610-0000-1880	WMEELES RONALD WINSTON + DEBRA D	AND LOVE UR SALSOWA	Days antition Coop	
33-10-26-3610-0000-0310	WEEDMAN RANDOLPH P	25/ RECORDS ON SALISONAL 244 CONDUCTABLE ON SALISONAL	Storbers Point	
45-11-20-8/31-00000 3444	COLEC MINE A LAMABIE H COARS 17/05	216 RIVER BEND PL # BLDG C WELAKA	Beecher Point	
32.10.76.3610.0006.076	JENNINGS JEFF A + SANDRA M HEADLEY (TIC)	119 CAMELLA DR SATSUMA	Barrentine Creek	
40-12-26-0530-0030-2060	WILLIAMSON CURTIS JR + TERRI L M/W	206 RIVER BEND CT # BLDG A WELAKA	Beacher Point	
11.126-8791-0000-1656	KR COMMONS PATRICK MICHAEL	165 IADONLITE DR WELAKA	Stephens Point	
37-12-26-6085-0020-0100	BUTENSKY JAN D + BARBARA P H/W	112 WILLIAM BARTRAM DR CRESCENT CITY	Fruitland Cove	
35-12-26-7800-0060-0187	FARNHAM HEATHER LEA + STEPHEN FRANK JR WW	125 W PALM AV CRESCENT CITY	St. John Upstream Extent	
45-11-26-8791-0000-0531	RANEY DARWIN 5 + ELIZABETH A H/W	53 SPORTSMAN DR WELAKA	Stephens Point	
39-10-25-3610-0000-1980	CATTERTON CHESTER J	133 ST JOHNS CT SATSUMA	Barrentine Creek	
40-12-26-0530-0020-1070		107 RIVER BEND CT # BLDG A WELAKA	Beecher Point	
-12-25-0000-0370-0051	ADVANTA IRA ADMINISTRATION (LC FBO JOSEPH SANDS IV IRA	118 N HUBERS FISH CAMP RD CRESCENT CITY	Fruitland Cove	
40-12-26-0000-0180-001:	ACKERMAN JAMES 1 + SALLY M W/W	110 POINT SOUTH DR WELAKA	Beecher Point	
33-11-26-8791-0000-2110	BENNETT ROLAND + S CAROL H/W	211 SPORTSMAN OR WELAKA	Stephens Point	
-11-26-8791-0000-1980	BARNETT DOWALD J	198 SPORTSMAN DR WELAKA	Stephens Point	
40-12-26-0000-0230-0010	MARCHIONE MARK A + MICHELLE N LESTER H/W	117 TERCINDA RO WELAKA	Beecher Point	
40-12-26-0530-0030-2270	VETTEN CORNELIUS N + KATHLENE H/W	227 RIVER BEND PL # BLDG D WELAKA	Beecher Point	
33-11-26-8791-0000-1020	BASS ROY + WILLA DEAN H/W	102 HAPPINESS DR WELAKA	Stephens Point	
39-11-26-8234-0040-0260	FAZEKAS NICHOLAS J JR + LINDA IM FAMILY LIVING TRUST	151 BUCHANAIN CIR SATSUMA	Barrenthe Lreek	- 200 200-
39-10-26-3510-0000-1870	LEVY WILLAM R + SHARON M H/W	464 COVE DR SATSURA	Barrenting Creek	
45-11-26-8791-0000-2450	STURM ROBIN SR + BRADLEY (JTRS)	245 SPONTSMAM DR WELAKA	Staphens Point	
38-12-26-7800-0090-0010	MARDIE FAMILY TRUST JOSEPH A 118 + PAMELA H HARDIE TRS	112 HCIS AV CRESCENT CITY	St. John Upstream Extent	
33-10-26-3610-0000-0480	MEADORS STEVE L+RYDKD K H/W	LAU PIERWEIS UM SALSUMA	Boochee Drint	
40-12-26-5117-0320-0011	SAZY LIAYS CAMIP RESONT LOT OWNERS ASSOCIATION INC.	225 COCHTCMAN OF WEI AKA	Stephens Point	
45-11-26-8791-UUO-2254	HAMPENS DOWNED HAT THEN ELLE BIT BY THE	189 SPORTSMAN DR WELAKA	Stephens Point	IKS INS DIS
24 11 26 GROD ROSELANDS		599 STOKES LANDING RD PALATIKA	Stokes Island	
45.11.26.8790.0000.0190	KOESTERING JAMES	19 SCOTT ST WELAKA	Stephens Point	
3-11-25-8791-0000-081(PAPPAS JACQUELINE A + MICHAEL S W/H	BI CAREFREE DR WELAKA	Stephens Point	
An 12 34 Mean Appen 1251	BRAZII DONALD K	131 HVER BEND PL# BLDG E WELAKA	Beecher Point	
THE R. P. LEWIS LANSING MICH. SPICE LANDING. LANDING.	Manual Community or	The same of the sa		

LIST OF PARCELS WITH AFFECTED STRUCTURES KIRKPATRICK DAM FAILIRE AMALYSIS

Kirkpatrikk Dam Putnam County, Florida Florida Department of Environmental Protection

arcel Identification Number		She Address	Cocation
40-12-26-0530-0010-2240	ENFINGER GERALD E + JAKETTE M OMOND N/W	224 River Bend Fl R Bling o Welaka	Beacher Point
40-12-26-0530-0010-1020	ENLANEY PAUL + TERESA H/W	102 RIVER BEND CT # BLDG A WELAKA	Beecher Point
39-11-26-8234-0040-0190	BURAP NANCY H HERS OF	137 Buchanan Cr Satsuma	Barrentine Creek
33-11-26-0000-0310-0010	WELLS CAROL A LIFE ESTATE	136 FLORIDIAN CLUB RD WELAKA	Stephens Point
33-10-26-0000-0012-0000	HOLLAND KEITH V + GEORGA ISRAEL III	221 WOODBURY TRI SATSUMA	Downstream Model Extents
33-10-76-3610-0000-0650	JANKOWSKI KENNETH A	106 Camella dr Satsuma	Barrentine Creek
10-2300	MUGHES REVIN C + SANDRA E H/W	230 RIVER BENID PI, IF BIDG E WELAKA	Beechar Point
33-10-26-3610-0300-0770	3.0	121 CAMELLA DR SATSLIMA	Barrentine Creek
33-16-26-3610-0006-0230		221 HERMITS OR SATSUMA	Barrentine Creek
40-12-26-0530-0030-213C		2113 RIVER BEND PL # BLDG B WELAKA	Beacher Point
45-11-26-8791-0000-233C	CAME MACHAEL R + MYRNA P H/W	233 SPORTSMANI DRI WELAKA	Stephens Point
45-11-26-8791-0000-085C	FISH BRANTLEY MICHAEL + LORINDA G H/W + BRANTLEY 1	85 SPORTSMAN DR WELAKA	Stephens Point
26-12-26-0000-0271-000K	SAPP WILLARD J. JR.	110 MATIONAL FOREST RD 29 PALATICA	St. John Upstream Extent
40-12-26-0530-0020-105C	BURBRIDGE M CLINTON + AMO H/W	105 RIVER BEND CT # BLOS A WELAKA	Seecher Point
45-11-26-8790-0000-0130	MAXWELL JOHN + WILMA	14 HOCKEY DR WELAKA	Steakens Point
27.12.26-6085-0010-0110	SHORT WILLIAM	163 MORINE ROYAL AV CRESTENT CITY	Freshand Com
40-12-26-0530-0000-0100	LEONARD LINDA INJING TRUST	250 REFCHERS POWIT OR WELLKA	Standard Driet
39-11-26-8234-0040-0220		TAR RENTHAMEN FIR CATCURAGE	Ramonting Crook
35-12-26-7800-0060-0246	N+ MANCY 15F HVW	THE WEBSING AV CRECCENT OFF	Se Inkin Singtrane Cutost
40.12.26.0530.0020.135f		135 BRUTE BESIDE A BRITE CARE AND	Discontinue Delicate
0.718/	E CCT ATE	218 SHIPS SEARCH SINGLE SEARCH	Oceanies Posts
45-11-36-8791-0000-733r		202 CONDICTION OF WITH BIND	Chambaran Daine
40 5 3 36 05 30 00 30 35 pt		THE DESIGNATION OF THE PARTY AND	Company of the second
18.17.76.76/1.0000.006/	AL LISE SCHATE	ACA SINGLE AND DESCRIPTION OF WELLAND	Dewing Pomit
11,11,76,8791,000,104f		104 CONDICIONAL DE SACO AVA	Constitute Dates
0.0 41 95 05 05 00 00 00 00 00 00 00 00 00 00 00	#31GE 3100000100 G 100100 G	134 STORY STREET OF STREET	Stephiers Posts
40-12-20-0334-W30-2300	I KOS I	ASO MYEN BENEVE PLANELIAN E WELARA	Beacher Point
70-0551		245 Permants un satscuria	Barrenthae Creek
40-12-26-0530-0010-1300	DAL ELAINE	130 RMER BEND PL# BIDG E WELAKA	Beacher Point
40-12-26-0000-0220-0000		103 Teronda nd Welaka	Beecher Point
39-11-76-8234-0040-0200		139 BUCHAWAY CIR SATSUMA	Barrentine Creek
40-12-26-5117-0320-0330	POLAND CYNTHIA A LUEDERS+LADONNA L LUEDERS WILSON	1074 FRONT ST # LOT 31 WELAKA	Beecher Point
40-12-26-0000-0180-0030	SEVACOUR WILLIAM G-MARY M JOINT LIMING TRUST	128 BEECHERS POINT OR WELAKA	Beechar Point
45-11-26-8790-0000-0240	ROBERTSON LAURA ET AL (JTRS)	24 SCOTT ST WELRKA	Stephens Point
0-0180		166 IMDUST ROYAL AV CRESCENT CITY	Fruitiand Cove
39-10-26-3610-0000-1830		456 COVE DR SATSUNGA	Barrentine Croek
33-10-26-3610-0000-0430	GINTERT CHARLES WALTER LIFE ESTATE RINDR:BRIAN LYNN GINTERT	263 Herrits or Satsuma	Barrentine Creek
33-10-26-3610-0300-0690	-	100 CAMELLIA DR SATSURA	Barrentine Creek
13-10-26-3610-0000-0370	MATANPA DAVID	249 HERNETS DR SATSUMA	Barrentine Creek
45-11-26-8791-0000-1260	WEBB CYNTHIA	226 SPORTSIMAN DR WELAKA	Stephens Point
33-10-26-3610-0000-0210	WELL MARIIZABETH A BELL	219 RERMITS OR SATSUMA	Samentine Creek
37-12-26-6085-0020-0230	VE UN TRUES	156 MONINE ROYAL AV CRESCENT CITY	Ferifilmed Conc
20.00	TOWN THOSE	TO INCOME WORLD'S WE CAN SEE STATE OF THE SECOND SE	rigidal Core
37-12-26-6085-0020-0166	WRA L H/W	107 WHILIAM BARTRAM OR CRESCENT CITY	Fruitiand Cove
33-11-26-8791-0000-1810		ibi sportskam dr welaka	Stephens Point
39-10-76-3610-0000-2056	CREAGLE JIMMANE H SR LIFE ESTATE	119 ST JOHNS CT SATSUMA	Barrenthre Creek
40-12-26-0530-0010-1320	£ TRUST	132 RIVER REND PL # BLDG E WELAKA	State har Spins
AN. 17. 76. 0520. 0120. 2757		THE DESIGN BUILDING SECURITY OF SECURITY AND	Operation Define
T. Carlo	STREET STREET AT COURSE BIT IN	ALT WARN DEAUL FILM DALM IN THE THEFT	decement Porm.
40-12-26-0530-0010-2030		203 RIVER BEND CT # BLDG A WELAKA	Beether Point
40-12-26-5117-0320-0190		1074 FRONT ST# LOT 19 WELAKA	Beecher Point
40-12-26-0530-0010-124(PETERS MALCOLM W + BONNIE LH/W	124 RIVER BEND PL # BLDG D WELAKA	Seecher Point
Jart u		TAR COMPETERATION TO MAKE BIES	Principle page Parkets
20 10 26 2610 0000 2000		END AT CITIES AND LESS IN LEASTINGS.	Diegoverns indent
V-2081		115 ST JOHNS CF SATSUMA	Barrending Creek
40-12-26-0530-0330-2080		208 RIVER BEND: CT # BLDG A WELAKA	Beecher Point
41-12-26-8790-0000-0180	ALVAREZ ROBERT + ROMA COMPART (JTRS)	18 SCOTT ST WELAKA	Stephens Point
40-12-26-0530-0020-1270		127 RWER BEND PLANDOS DIMELAKA	Beacher Point
32 15 36 6700 0000 0002			Market Company of April 1979,
D-tal/t		MULTET UN WELLAND	Stepment Point
45-11-26-6790-000-0110	SPRINKLE LAWRENCE EUGENE + ROSEMARIE H/W	II HOCKEY DR WELAKA	Stephens Point
45-11-26-8791-0000-1160	BLAIR JEANNER & JERRY L HOLLINGSWORTH W/H	1116 PARADISE OR WELAKA	Stondams Point
40.17.76.0530.0000.030C	ava.	15.0 DEFENDENC BOTHER DO WEELSTE	Boor hor Daint
32 50 35 0000 000 5 000		10 and Charles to a transfer	
1-001	E1	SAU WELCHELING SHESSERVE	LOWINGER IN WOOR! EXCERTS
40-12-26-0530-0010-2090		20S RIVER BEND PL# BLOG B WELAKA	Reservan Print

LIST OF PARCELS WITH AFFECTED STRUCTURES FIRST OF PARTENING ANALYSIS.

Kirkpatrick Dam Putnam County, Florida Florida Department of Erwronmental Protei

UNE AMALYSIS		
KINKEN TRUCK DAM FAIL		
	stection	

		Chine, Refolement	Cocalitan	
AC 13 76 OCOS OTODO 3055	DAILTHAN DOIDE N + ANN P HAN	205 RWER BEND CT # BLDG A WELAKA	Beecher Point	
ACCOUNTS ACC	MANDER PAIN A 11FE ESTATE	115 RIVER BEND PL # BLDG C WELAKA	Beecher Point	
AC 15 DE STON OFFICIALITY		84 SPORTSMARI DR WELAKA	Stephens Point	
22-10-25-26-0-000-03-00	CORPAN TERRY	235 MERIMITS DRISALINA	Barrentine Creek	
39.11-25-8461-0060-0160	LARRY FRANKLIN PROPERTIES INC	129 RIVER RD SATSUMA	River Road	
37-11-26-0000-0110-0010	THIT/DEP-GREENWAYS GREENWAYS STATE REC PARK	202 BUCKNAM LOCK ND PALATICA	Whitney Street	
40-12-26-0530-0020-1200	SMITH THORAGS A + LOUISE B H/W	120 RIVER BEND PL # BLDG C WELAKA	Seecher Point	
45-11-26-8791-0000-2340	MARRELL THOMAS CARL	234 SPORTSMAN DR WELAKA	Stephens Paint	
			Commission Commission Co.	
45-11-26-8791-0000-2390	MILES HENRY GAINES MERS OF JOHN A + WILLIAM E MILES PERS REPS	** 239 SPORTSMAN DR WELASA	Magniferia Politic	
33-10-26-3610-0000-0780	DUNCAN STEVEN + SHERRY MY W	LOS CANNELLIA UN SIN SOUMINA	Destructive County	
39-11-26-8234-004D-021C	MYERS STEVEN R + WARROOL H/ WH	141 BUCHANAN LIN SAISUMA	Date et 1117 M. L. Tenen.	
40-12-26-0530-0000-0320	OPFERMAN JAMES M	155 BEECHERS POINT DR WELAKA	BROCHET FOUNT	
34-10-26-0000-0010-0156	Parker amanda Dawn + Matthew Alan Knighton (TIC)	157 PINE TREE RD PALATRA	DOWNSTREAM WOODE ENGINE	
38-12-26-7800-0050-0190	SYKES PHILLIP + DOROTHEA A H/W	106 HICKS AV CRESCENT CITY	St. John Upstream Extert	
34-11-25-0000-0020-000K	May Steven e + Brenda W M/W	100 GUMPS PL PALATKA	Dean Creek Road	
40-12-26-0530-0030-2330	BURNETT INCHARD JIR+JOAN P H/W LIFE ESTATE	233 RIVER BEND PL # BLDG E WELAKA	Baecher Point	
39-11-26-0000-0023-0000	NUCKOLLS WILLIAM S + SHARON H H/W	237 WHITNEY ST SATSUMA	Whitney Straet	
39-11-26-0000-0020-0000	DANAMDDIE KAREN S	ZAS WENTINEY SE SALSUMA	VOTHERSY STREET	
41-12-26-5070-0090-0000	DIXON LOUISE W LIFE ESTATE	I BOSILWE SI WELDER	Singments Point	
39-10-26-3610-0000-200f	SOUCIA GERALD + ABBIE M/W	THE ST YOMNS OF SATSUMA	Barrentino Liees:	
33-11-26-8791-0000-1740	RUSSELL RAYMOND W + BEKETTA D FAMILY TRUST	174 MUNICIPE ON WELARA	Design William Column	
40-12-26-0000-0300-0000	SHEPARD ROBERT D + PAIRICIA A M/W	110 BEFUNDS FOIRS DR WELANA	Steelings Fullia	
45-11-26-8791-0000-2300	MADAWAY RAYMOND TERRY	CAU SPLINGERS LINE WELMAN	Drawfers Delief	
40-12-26-0530-0010-1230	PERKINS CARTON DAVID IR	125 RIVER SEND FLW BLING INVESTMENT	Described Found	
40-12-26-0530-0010-2040	PUTNAM RENTALS LLC	ALM RIVER BEING L. R BLING A VELARAL	Speed ner Pomit	
40-12-26-0530-0010-1090	SK WATSON LIC	TOWNSHIND FOR BUILD BY WELSHAM	Open-turn Polish	
41-12-26-9200-0020-0030	STEELE ALLEM J	ACT DICKARDER CID CATCLESS	Dames Pine Crock	
39-11-26-2234-0040-0271	KKSGS CHRISTOPHER ASPER	AND SUCCESSION CAN DATE SOME	Charleng Delet	
45-11-26-8790-0000-0220	WARENS HAROLD H + JANKE T BYW	22 SCOTT ST WELFANA 226 GEBLUTC DE CATCHARA	Removine Creek	
33-10-26-3610-0000-0471	MARKO PANCONE I TUEBONAN WAY	ACC ONTINESS OF THE DATE AND	Rose hav Boint	
40-12-26-0530-0000-0180	PALUSZYNSKI KALMARI A + KAY C NY W	TOS SECUTERS POTING ON WELCOME	Sy Info Bertream Extent	
35-12-26-7800-0060-0196	HOWIET ALBERT	THE CONSTRUCTIONS	Stachans Point	
11-11-12-20-0000-0-02-11-11-11-11-11-11-11-11-11-11-11-11-11	SACOCO SICHED 1	VOD CAMERITA DR SATSUMA	Barrentine Creek	
12-10-12-12-12-12-12-12-12-12-12-12-12-12-12-	WENDER TANASAY 1 4 CEORGANNA W BEITHER (FESS)	1074 FRONT ST # LOT 33 WELARA	Seacher Point	
AC 15 36 DEPO 0340 DEPO		113 TEROWIN NO WELAKA	Beacher Point	
2000-04-00-000-04-04-04-04-04-04-04-04-04	SICKLES OCCUPATION	201 RIVER BEND CT # BLDG A WELAKA	Beacher Point	
46-11-26-8791-0000-2021	TOWN THE PROPERTY.	222 SPORTSMAN DR WELAGA	Stephers Point	
22 10.26.2610.0000.0457	MANUE AND A	265 HERNOTS DR SATSUMA	Barrentine Creek	
40-19-36-06-00-00-00-00-00-00-00-00-00-00-00-00	BELL ROLAND & + KATHY L MAN	232 RIVER BEND PL & BLDS: E WELAKA	Beecher Point	
17.12.26.6085.0020.0150	DAUGHTERY JOEY + LISA DISAW	103 WILLIAM BARTRAM DR CRESCENT CITY	Fruitland Cove	
39.10-26-3610-0000-1950	SMALL PAMELA JEAN	480 COVE DRI SATSUMA	Barrentine Creek	
40-12-26-0530-0010-1010	GREGG JOHN L + JEMMIER L HYW	101 RIVER BEIND CT # BLDG A WELAKA	Beacher Point	
A0-12-26-0000-0231-0000	SHEPARD ROBERT + PATRICIA M/W	122 BEECHERS POINT OR WELAKA	Seecher Point	
34-10-26-0000-0010-014[CONE JESSICA LYNN + DANIEL EDWARD W/H	147 PINE TREE RD PALATKA	Downstream Model Extents	
40-12-26-0530-0020-1110	HOLLAND CHARLES R	111 RIVER BEND PL # BLDG B WELAKA	Seecher Point	
40-12-26-0530-0030-2120	SPALDING MARC + LINDA FARRLY TRUST	212 RVERBEND PL # BLDG B WELAKA	Beecher Point	
40-12-25-0530-0000-0200		172 BEECHERS POINT ON WELAKA	Beecher Point	
45-11-26-8791-0000-2280	WEATHERWAY BRIAN + HEATHER DAVIS (ITRS)	228 SPORTSMAN DR WELAKA	Stepwens Porns	
40-12-26-0530-0030-2350	MAMN JOHN CHARLES + LYNDA R H/W	235 KIVER BEND PL # BILZ: E WELARA	Second voin	
40-12-26-0530-0000-0421	MAXIVELL DENNIS 1 LIFE ESTATE	135 BEECHERS POINT OR WELAKA	Beecher Point	
40.12-26-0530-0010-1030	Beerbower Peggy Acmichael Living Trist	103 RIVER SEND CT # SLING A WELAKA	PERSONAL PORTS	
39.10.26-3610-0000-1850	JAMPES SAWUEL	ADD COVE ON SHIP OF SOUNDS	Starther Print	
40-12-28-0830-0030-107	K B CONDUMENTUM ASSOL IM.	122 DEFINES POWY DE WELSE	Rearriest Print	
40-12-26-0530-0000-0010	PUDE FROM THE WAIT IS	NOTA TROUT STATEMENT	Specifical Policy	
40-12-20-5117-0920-0200	MEIGHER THOUSE - ANN MAN HEE ESTATE	219 HVER BEND PL # BLDG C WELAKA	Beecher Polen	
39.11.26.8461.0050.015(131 RWER RD SATSUMA	River Road	
40-12-26-0000-0380-0000	CARTER S RUSSELL JR + COURTNEY 1	109 TERONDA ND WELAKA	Beecher Point	
40-12-26-5117-0320-0300	WALDRON JASON + KIMBERLY H/W	1074 FRONT ST # LOT 30 WELAKA	Beecher Point	
	The state of the s		Direct Space Director	

LIST OF PARCELS WITH AFFECTED STRUCTURES KINDATRICK DAM FAILURE AMAIYSES

Kirkpatrick Dam Putnam County, Florida Florida Department of Environmental Protection

And the second district th			Waterday Albert Strategy
Parcal Identification Mumber As. 11.26, 8701, APRO 0567	DAMES RESTANT FUGERE + JONE USA WAY	ST CAREPREE OR WELAKA	Steamer Point
100000000000000000000000000000000000000	HAGGARD WILLIAM ANDREW LIVING TRUST WILLIAM ANDREW		
45-11-26-8791-0000-2210	HAGGARD TRUSTEE	221 SPORTSMAN DR WELAKA	Stephens Point
45-11-26-8791-0000-2400	GEISEL RAYMOND J. JR. TRUST	240 SPORTSMAN DR WELAKA	Stephens Point
39-11-26-8234-0046-024(HUTCHINSON ROSE MARY	147 BUCHANAN CIR SATSUMA	Bazzentine Creek
39-11-26-8234-0040-0180		13S BUCKANAN OR SATSCINA	Barrentine Creek
45-11-26-8791-0000-2310	CLEMENTS IACK + CAROLYN M JOINT 14051	251 SPORISMAN 291 WELAKA	scapmens, roung
40-12-26-0530-0010-2100	EMLERS DENNIS M + CAROLYM F M/W	210 RIVER BEND PL # BLDG B WELAKA	Georgian Point
55-10-20-3010-00000-0134	MESSAER RIVAL + VOLLIAND J W/77	THE BUILD BEIND BY MOI DO CHARLAGE	Constitution Contract
74 74 04 0400 0400 05 41 -1	THE CASE DAIN WEST OF	SA SOCIETAMEN DO NOT BUT	Creations Deline
42-11-50-0131-0200-0341	GENERAL CHERNIANIN	238 SPORTSMAN DR WELAKA	Steedheers Point
39.11-26-0000-0022-0000	VORKOVA NADEZDA	241 WHITHEY ST SATSUNGA	Whitney Street
40-12-26-0530-0010-2290	RITTER ROBERT	229 RIVER BEND PL # BLDG E WELAKA	Beecher Point
40-12-26-0530-0010-1100	THEMAN DONALD WAYNE	110 RIVER BEND PL # BLDG B WELAKA	Beether Point
40-12-26-0530-0010-2020	GROOMS RUSSELL E JR + CATHERINE M	202 RIVER BEND CT # BLDG A WELAKA	Beecher Point
40-12-26-0530-0030-2200	LEE THOMAS RJA	220 river bend pl # Bldg C welaka	Beechar Point
40-12-26-5117-0320-0340		1074 FRONT ST # LOT 34 WELAKA	Beecher Point
45-11-26-8791-0006-0580	CLARKE KIMBERLY DANESE + ROBERT JOHN JR W/H	S8 CAREFREE DR WELAKA	Stephens Point
45-11-26-8791-0000-0830	WOLF DONALD I + PATRICIA K/W	83 CAREFREE OR WELAKA	Stephens Point
45-11-26-8791-0000-0450	SKAGGS FRANKIE W + DEBRA C H/W	45 SCOTT ST WELAKA	Stephens Point
45-11-26-8791-0000-2350	DICKS ROWALD D + AIMREE R H/NV	235 SPORTSMAN DR WELAKA	Stephens Point
45-11-26-8791-0000-2420	FERRY RICHARD P	242 SPORTSMAN OR WELAKA	Staphens Point
40-12-26-0530-0020-1250	FERBER GEORGE A LIVING TRUST ET AL	125 RIVER BEND PL# BLDG D WELAKA	Beecher Point
45-11-26-8790-0000-0150	CHRISTOPHERSON MARY DAWN	15 HOCKEY DR WELAKA	Stephens Point
45-11-26-8791-0300-2460	VOHO CAROLYN REVOCABLE TRUST	246 SPORTSMAN DR WELGEA	Stephens Point
45-11-20-8791-000-0436	ON MANK	THE STORY OF WELLIAMS	September Const
40-12-26-0530-0030-2110	COX JAMES S + TARMAY S N/W	211 RIVER BEND PL & BLDG B WELAKA	Beeringt Portic
3571-0000 0030 30 11 00 00 00 00 00 00 00 00 00 00 00 00	DADETE METER TO MATTINE MAKE	THE BEST OF STATE OF SECOND	State Solver
40-12-16-05-00-10-12-12-12-12-12-12-12-12-12-12-12-12-12-	GUNTE DAIL - PHYLIS	226 RIVER BEND PL# BIDG D WELAKA	Bleecher Point
33.10.26.0000-0060-0040	BIRKETT BARRY + 5USAN ZABAWA	439 COVE DR SATSURVA	Burnentine Creek
40-12-26-0530-0030-2216	LEVIN ROY STUART + CYNTHIE LYNN H'VW	1221 RIVER BEND PL # BLDG C WELAKA	Bercher Point
40-12-26-0030-0360-0000	EVANS JEFFREY S + BARRY & H/W (JTRS)	123 TERCHDA RD WELAKA	Beacher Point
45-11-26-8790-0000-0210	MCGAULEY GILBERT E + JEANNETTE B	21 SCOTT ST WELAKA	Stephens Point
45-11-26-8791-0000-2246	LIGHTKEP BAXTER	224 Sportsman dr Welaka	Staphens Point
45-11-76-8790-0000-0120	LAMB CHRISTINA MARIE + DANIEL W/M	12 HOCKEY DR WELAKA	Staphens Point
45-11-26-8791-0000-2200	GREEN ALBERT E JR + LYNETTE IM HYW	220 SPORTSMAN DR WELAKA	Stephens Point
40-12-26-0530-0020-1220		122 RIVER BEND PL # BLDG C WELAKA	Seecher Point
40-11-26-0530-0030-134K	BUSH JAMES F + ALICIA M H/W + KIMBERLY A STONER	234 RIVER BEND PL # BLDG E WELAKA	Beacher Point
40-12-26-0530-0030-2140	HOLLAND CHARLES R	214 KIVER BEND PL # BUX B WELAKA	Beecher Point
40-12-26-0530-0000-004(BEASLEY MARRY B + PATSY R H/W	140 BEECHERS POINT OR WELAKA	Beecher Point
40-12-26-0003-0340-000X		104 BEECHERS PORT OR WELKE	Beecher Fourt
46-12-26-0530-0030-2280	TOWNSEND MELANIE Y + WILLIAM W W/H	ALSO NO DALLA ALL CONTROL OF THE STATE OF TH	Continue Therefore Court
32-17-50-7822-0000-01511	MELSON BRANCOM JOSEPH + JANNIN NYW	145 W PALMANIA TO CATCOMA	Elementarios Caralis
39-11-26-8234-0340-0231 40-17-26-0620-0010-2210	ARBATHANZE BATH + DOROTHY WES KIND	231 RVERBEND PLASING EWELKE	Seecher Point
45.1(.76.8794.mmn.736.	GANN FMI V+ O'SFORD W/H	236 SPORTSAAN DR WELAKA	Steatiens Point
45-11-26-8791-0000-1150	MOODY FRANK M+ SUSAW MH/W	115 HAPPINESS OR WELAKA	Stephens Point
40-12-26-0000-0280-0000	COWAN CAROL L + HENRY S W/H	110 BEECHERS POINT DR WELAKA	Beecher Point
	FENDER FRANKLIN D-MARRION B TRUST FRANKLIN D-WARRION B		
38-12-26-0000-0042-0320	FENDER TRUSTEES	147 HICKS AV CRESCENT CITY	St. John Upstrezm Extent
40-12-26-0530-0010-2170	SCOTT ROBERT A	217 RIVER BEND PL # BLDG C WELALA	Beacher Point
05648-001-00	BROWN DOROTHY M TRUST		Dean Creek Road
010 000 00	IDAI INVISI I CHANGE IT AL		Dean Creek Road

Appendix E. Miscellaneous Information

NGS Coordinate Conversion and Transformation Tool (NCAT)

- NGS Home
- About NGS
- Data & Imagery
- Tools
- Surveys
- Science & Education

Search

Single Point Conversion Multipoint Conversion Web services

Downloads About Conversion Tool

Convert/Transform from:

Horizontal

Horizontal+height

XYZ

Select the type of horizontal coordinate:

Geodetic lat-long

SPC

UTM

USNG

Select a height

Ellipsoidal

Orthometric

Enter lat-lon in decimal degrees

Lat

29,5113300273

```
Lon
 -81.8151855469
or degrees-minutes-seconds
 Lat
  N
  29-30-40.78810
 Lon
  W
  081-48-54.66797
 or drag map marker to a location of interest
Input reference frame
(historically called 'horizontal datum')
NAD83(HARN)
Output reference frame
(historically called 'horizontal datum')
NAD83(HARN)
Don't see a reference frame in the list? Click here to learn more.
Orthometric Height (m)
 0.000
Input geopotential datum
(historically called 'vertical datum')
NAVD88
Output geopotential datum
(historically called 'vertical datum')
NGVD29
SPC zone
Auto Pick (default zone)
```

ter green

Export Results to







Click blue bar(s) to expand/collapse

lighted mark of farmather to

Input Coordinate

Latitude

N29° 30′ 40.78810″ N293040.78810 29.5113300273

Longitude

E278° 11′ 5.33203″ W0814854.66797 -81.8151855469

Ellipsoid Height (m)

Not given

Orthometric Height (m)

0.000

Reference Frame

NAD83(HARN)

Geopotential Datum

NAVD88

Output Coordinate

Latitude

N29° 30′ 40.78810″ N293040.78810 29.5113300273

Longitude

E278° 11′ 5.33203″ W0814854.66797 -81.8151855469

Ellipsoid Height (m)

Not given

Orthometric Height (m)

0.279

Reference Frame

NAD83(HARN)

Geopotential Datum

NGVD29

Total Change + Uncertainty

Latitude

0.000000" ±0.000000"

 $(0.000 \text{ m} \pm 0.0000 \text{ m})^*$

Longitude

0.000000" ±0.000000"

 $(0.000 \text{ m} \pm 0.0000 \text{ m})^*$

Ellipsoid Height

Not given

Orthometric Height

0.279 m ±0.008 m


czepania i naddoate

Website Owner: National Geodetic Survey / Last modified by ngs.ncat Jun 23 2021

NOS Home NGS Employees Privacy Policy Disclaimer USA.gov Ready.gov Site Map Contact

Webmaster

^{*}Approximate value to aid interpretation and not an actual distance. See <u>TM NOS</u> NGS 82 for more details.



Slope Stability Analyses

Kirkpatrick Dam

Report prepared for

Florida Department of Environmental Protection



Report prepared by



February 2022



This item has been digitally signed and sealed by Martin Kemps, PE on 02/10/2022.

Printed copies of this document are not considered signed and sealed, and the signature must be verified on any electronic copies.

Table of Contents

		Pag	е
١.	Introd	luction	1
	A.	Project description	1
	B.	Background	1
	C.	Limitations	1
2.	Slope	Stability Analysis	2
	A.	Description	2
	B.	Analysis criteria	2
	C.	Load Cases	2
	D.	Phreatic Surface Development	2
	E.	Material Properties	2
	F.	Results	3
	G.	Conclusions	3

Appendices

- A Left Embankment Graphical Output
- B Right Embankment Graphical Output

List of Contributors

This report was prepared by or under the direct supervision of the individual listed below:

Martin Kemps, P.E.

Project Engineer

This report was reviewed by:

Jim Botz, P.E.

Senior Engineer

1. Introduction

A. Project description

The reservoir, known as Rodman Reservoir, is created by the Kirkpatrick Dam and Buckman Lock, which expands across the Ocklawaha River and the Cross Florida Barge Canal, respectively. The normal reservoir pool elevation of Rodman Reservoir is 20.0 feet, NGVD 29¹ at which the reservoir has a surface area of approximately 20.3 square miles, a gross volume of approximately 82,000 acre-feet, and a length of approximately 16.4 miles. The Kirkpatrick Dam (dam) consists of three water retaining structures: a left² (southwest) embankment, a concrete spillway with four lift gates, and a right northeast embankment.

B. Background

To better understand how factors of safety of the embankment change with various headwater levels, the Florida Department of Environmental Protection (FDEP) requested Mead & Hunt, Inc. (Mead & Hunt) to perform slope stability sensitivity analyses of the earthen embankments with the headwater elevations ranging from elevation 14.0 (six feet below normal) to elevation 23.2.

C. Limitations

All calculations and modeling were based upon as-built drawings and soil borings from the original construction. No surveys, soil borings, or laboratory tests were performed for this evaluation.

¹ All elevations in this report are given in feet and referenced to the National Geodetic Vertical Datum of 1929 (NGVD 1929).

² Left and right are referred to in this report relative to an observer facing downstream.

2. Slope Stability Analysis

A. Description


The embankments at Kirkpatrick Dam are homogenous and consist of sand. The crest is 30 feet wide with a top elevation of 28.3. The downstream section consists of 4(H):1(V) downstream slopes. The downstream slopes contain a rip rap revetment to elevation 19.3 which is underlain by a two-stage filter system. The upstream slopes consist of 4(H):1(V) slopes to elevation 25.0, 10(H):1(V) slopes to elevation 13.0, and a 3(H):1(V) slope that ties back into the existing ground surface. The drawings do not indicate that an impermeable core or cut-off wall was included in the design.

B. Analysis criteria

Since the state of Florida does not have slope stability criteria for embankment dams, factors of safety were compared to the recommended values in the Federal Energy Regulatory Commissions (FERC), Engineering Guidelines for the Evaluation of Hydropower Projects, Chapter IV, Embankment Dams, September 2006.

C. Load Cases

The following headwater and tailwater elevations were used in the models:



Seismic conditions were not analyzed since the current USGS data estimates a peak ground acceleration (PGA) between 0.02g and 0.04g at the Kirkpatrick Dam for a 2% chance of exceedance in 50 years (i.e. a return period of 2,500 years).

D. Phreatic Surface Development

Mead & Hunt performed seepage analyses of both the left and right embankments using the 2D finite element analyses (FEA) module within the Slide2 software by Rocscience (Version 9.005, 2020) to estimate the phreatic surface. Soil type was obtained from the subsurface exploration program performed in 1964. As requested, headwater elevations used ranged from a maximum pool elevation of 23.2 to a drawn-down pool elevation of 14.0. A horizontal to vertical permeability ratio of 3.0 was used for the granular embankment and foundation soils. Normal tailwater was used for all cases except for the maximum pool. Tailwater at the maximum pool was estimated to be at elevation 9.55 based upon the dam failure analysis performed by Mead & Hunt in 2022. The seepage model results appear reasonable, but they could not be calibrated because there are no monitoring wells in the embankment to measure the phreatic surface.

E. Material Properties

Material strength parameters used in the analyses were estimated from the N-values obtained during sampling during the subsurface exploration program performed during original construction. Unit

weight assumptions were based on values provided in Table 6 of Naval Facilities Design Manual 7.01, Soil Mechanics.

Hydraulic soil properties from Figure 8.3.2.3.3-1 of the *U.S. Bureau of Reclamation Design, Standard No.* 13 were used in the model to estimate permeability rates.

F. Results

Mead & Hunt conducted slope stability analyses for the right embankment using the Slide2 (Version 9.005) slope stability program (Rocscience, 2020). The procedure used was the simplified Bishop's Method of Slices which satisfies all conditions of force and moment equilibrium. Both circular and non-circular searches were performed to find the lowest global FOS. The models were checked to see if tension cracks could develop. No tension within the soils was determined to exist. Global failure of the cross-sections was considered to be those failure surfaces having a FOS, which could realistically lead to a breach of the dam and an uncontrolled release of water. As a result, shallow surface failures were eliminated from consideration. Results of the slope stability analyses are presented in Table 2.

Table 2. Slope Stability Analyses Results

	Left Emi	oankment	Right Embankment		
Headwater Elevation	Calculated Factor of Safety	Recommended Factor of Safety	Calculated Factor of Safety	Recommended Factor of Safety	
323				羅	
A BOOK STATE					
LAN.					
that I					
988	- AV 5				

Graphical cross-sections of the slope stability analysis results and controlling failure surfaces are presented in Appendix A and B for the left and right embankments, respectively.

G. Conclusions

The existing embankment slopes exceed the factor of safety as recommended by the FERC for all load cases analyzed. The factor of safety does increase with lower pool elevations which would be expected. The relatively high factors of safety can be attributed to the wide crest and gradual slopes.

Appendix A. Left Embankment Graphical Output



_
=
ä
2
$\underline{\mathbf{v}}$
Þ
g
¥
÷

grants	Left Embankment	Scenario	HW = 23.2
Drawn By	M. Kemps, PE Reviewed J. Botz, PE	Company	Mead & Hunt, Inc.
Date	October 2021	File Name	Grkpatrick Dam Left Embankment.slmd



	E	
(<u>k</u>	
-		
	Ē	7
	C	
	Ì	
2		

Aceresia Aceresia $+20$	J. Botz, PE Company Mead & Hunt, Inc.	File Name Kirkpatrick Dam Left Embankment.slmd
w Left Embankmen	wn 8y M. Kemps, PE Reviewed J. Botz, PE	P October 2021



479
Ε
<u>m</u>
상
Ē
Ø
꿏
5
and the

canto	Left Embankment	Scenario	HW = 18
Drawn By	M. Kemps, PE Reviewed J. Botz, PE	Сотралу	Mead & Hunt, Inc.
A38D	October 2021	File Name	Kirkpatrick Dam Left Embankment.slmd



TEO AS	Scenario HW = 16	Company Mead & Hunt, Inc.	File Name Kirkoatrick Dam Left Embankment.s
Nikpatick Dam	Left Embankment	M. Kemps, PE Reviewed J. Botz, PE	October 2021



E
ळ
꿈
Ē
ᅏ
9
T
\mathbf{Y}

Groups	Left Embankment	Scenario	HW = 14
Drawn By	M. Kemps, PE Reviewed J. Botz, PE	Сотрапу	Mead & Hunt, Inc.
Date	October 2021	File Name	Kirkpatrick Dam Left Embankment.slmd

Appendix B. Right Embankment Graphical Output



k Dam	
Kirkpatrick Dam	
ω¥	

(Brank)	Right Embankment	Scenario	HW = 23.2
Drawn By	M. Kemps, PE Reviewed J. Botz, PE	Сотралу	Mead & Hunt, Inc.
Date	October 2021	File Name	kirkpatrick dam right embankment.slmd



Dam	
Satrick	
조	

HW = 20	Mead & Hunt, Inc.	kirkpatrick dam right embankment.slmd
Scenario	Company	File Name
Right Embankment	M. Kemps, PE Reviewed J. Botz, PE	October 2021
Group	Drawn By	Date



Ε
ā
-
Ů
Б
g
돈
Ż

HW = 18	Mead & Hunt, Inc.	kirkpatrick dam right embankment.simd
Scenario	Company	File Name
Right Embankment	M. Kemps, PE Reviewed J. Botz, PE	October 2021
Group	Drawn By	Date



1		
4 4 .	Very contraction of	

Right Em Kemps, PE Re Octobe	Right Embankment Xxenam HW = 16	M. Kemps, PE Reviewed J. Botz, PE Company Mead & Hunt, Inc.	October 2021 File Name kirkpatrick dam right embankment.slmd
------------------------------------	---------------------------------	---	--



		0
	7	5
	1	2
3.40		1

Group	Right Embankment	Scenario	HW = 14
Огамт Ву	M. Kemps, PE Reviewed J. Botz, PE	Сотрэлу	Mead & Hunt, Inc.
Date	October 2021	File Name	kirkpatrick dam right embankment.slmd

Stability Analysis

Gated Spillway

Kirkpatrick Dam

Report prepared for

Florida Department of Environmental Protection



Report prepared by



February 2022



This item has been digitally signed and sealed by Martin Kemps, PE on 02/10/2022.

Printed copies of this document are not considered signed and sealed, and the signature must be verified on any electronic copies.

Table of Contents

			Page
1.	Intro	duction	1
	A.	Project description	1
	B.	Background	1
	C.	Analysis objectives	1
2.	Stab	ility Analysis	2
	A.	Description	2
	В.	Analysis criteria	
	C.	Analysis methodology	
	D.	Load cases	
	E.	Assumptions	
	F.	Material Properties	
	G.	Results	
	H.	Conclusions	

Appendices

- A Loading Diagrams
- **B** Stability Calculations
- C Weighted Creep Uplift Calculations

List of Contributors

This report was prepared by or under the direct supervision of the individual listed below:

Gary Ruchti, P.E.

Lang Buckers

Project Engineer

The following individuals also contributed to the development of this document and/or the analyses presented herein:

Jeff Anderson, P.E.

Jonathan Salomon, E.I.T.

Samantha Gulick

1. Introduction

A. Project description

The reservoir, known as Rodman Reservoir, is created by the Kirkpatrick Dam and Buckman Lock, which expands across the Ocklawaha River and the Cross Florida Barge Canal, respectively. The normal reservoir pool elevation of Rodman Reservoir is 20.0 feet, NGVD 29¹ at which the reservoir has a surface area of approximately 20.3 square miles, a gross volume of approximately 82,000 acre-feet, and length of approximately 16.4 miles. The Kirkpatrick Dam (dam) consists of three water retaining structures: a southwest embankment, a concrete spillway with four lift gates, and a northeast embankment.

B. Background

The Florida Department of Environmental Protection (FDEP) retained Mead & Hunt, Inc. (Mead & Hunt) to provide a dam safety inspection and stability analyses of the embankments and gated spillway structure. To better understand how factors of safety are impacted with various headwater levels, the FDEP requested Mead & Hunt to perform a sensitivity stability analysis of the gated spillway structure.

C. Analysis objectives

The objective of this document is to summarize the sensitivity stability analyses performed for the gated spillway section and to provide supporting documentation of the analyses. This report summarizes the methodology, assumptions, results, and conclusions of our analyses.

¹ All elevations in this report are given in feet and referenced to the National Geodetic Vertical Datum of 1929 (NGVD 1929).

2. Stability Analysis

A. Description

The gated spillway consists of a mass concrete Ogee weir with four gates supported by three piers and two abutments. Additionally, the piers support a concrete service bridge, operating platform, and a walkway. The structure is founded on a sand foundation with steel sheet pile cut-off walls to reduce seepage, which are located along the upstream face of the spillway structure and along the edge of the downstream concrete apron.

B. Analysis criteria

The following is a summary of the references that served as a basis for this analysis:

Federal Energy Regulatory Commission, Engineering Guidelines for the Evaluation of Hydropower Projects, Chapter 3, Gravity Dams, March 4, 2016.

Naval Facilities Engineering Command, *Design Manual 7.02, Foundations & Earth Structures*, September 1, 1986.

C. Analysis methodology

The stability of the gated spillway section was evaluated utilizing the mass gravity method in accordance with Chapter 3 (Gravity Dams) of the Federal Energy Regulatory Commission's (FERC's) *Engineering Guidelines for the Evaluation of Hydropower Projects*. Lane's weighted creep method was used to determine the uplift distribution and load on the gated spillway structure.

D. Load cases

The load cases that were evaluated as part of the sensitivity analyses are presented below. The loading diagram for each load case are presented in Appendix A.

Table 1 - Load Cases

Load Case	Gate Position	Headwater Level	Tailwater Level ²
	(i		

² The corresponding tailwater levels were calculated based on the results of the dam failure analyses performed by Mead & Hunt in 2022.

E. Assumptions

The following is a summary of the assumptions made as a part of this analysis:

- The uplift pressure distribution was determined using Lane's weight creep method.
- The following items were considered outside the scope of this study, and therefore, <u>not</u> included in the sensitivity analyses performed:
 - o Ice expansion load
 - o Seismic and debris loading
 - Sliding failure along one of the spillway structures construction joints
- The spillway structure gate was assumed to be fully opened during flood conditions (Load Case I), with a headwater level of 23.2 feet. The gate was assumed closed during lower headwater conditions (Load Cases II through V), with a headwater level of 20.0 feet or less.
- For Load Case I, where the gate is fully open and the water is moving over the weir, the tailwater
 elevation was reduced to 60% of expected height for the horizontal force on the dam to account
 for Nappe forces in accordance with the FERC Engineering Guidelines 3-2.3.2. The other load
 cases are assumed to have low/no flow and the Nappe forces were ignored in accordance with
 FERC Engineering Guidelines.
- The stability of the gated spillway structure was analyzed as a single bay (44 feet wide). The
 plane of analysis for overturning was taken at the base of the structure slab (elevation -13.0).
 The plane of analysis for sliding was taken at the bottom of the shear key (elevation -21.0)

F. Material Properties

- The unit weight and friction angle of the silt were assumed to be 110 pcf and 30 degrees, respectively. Horizontal silt loads were determined using at-rest earth pressure.
- The unit weight of concrete was assumed to be 150 pounds per cubic foot (pcf) and the unit weight of water was assumed to be 62.4 pcf.
- Historic soil boring provided in the project construction drawings were used to classify the
 underlying soil as medium to fine sand. The unit weight and friction angle of the underlying soil
 were assumed to be 125 pcf and 31 degrees, respectively. Passive and active lateral earth
 pressures were only considered for the sliding failure method.
- The allowable foundation bearing pressure was assumed to be 3.5 (ksf).
- Cohesion at the foundation interface was not anticipated due to the sand foundation and therefore not considered.

G. Results

The results of the sensitivity stability analyses performed for the structure are presented below. Supporting calculations for the stability analysis are provided in Appendix B and the uplift calculations are presented in Appendix C.

Case II Case III Case IV Case V

Case III Case III Case III Case IV

Case V

Case V

Case III Case III Case IV Case V

Case V

Case V

Case III Case III Case IV Case V

Case V

Case V

Case V

Case IV Case V

Case V

Case V

Case IV Case V

Case IV Case V

Case V

Case IV Case V

Case IV Case V

Case IV Case V


Case III Case III Case III Case III Case IV Case V

Table 2 - Stability Analysis Results


H. Conclusions

The stability analysis results presented in the previous section indicate that the dam has acceptable factors of safety with respect to overturning and sliding for the loading conditions evaluated.


Appendix A. Loading Diagrams




For all cases: Earth pressures and sliding failure plane




Case 1: Head and Tail-water Horizontal Forces and Silt Forces on the Dam




Case 1: Head and Tail-water Vertical Forces on the Dam




Case 1: Uplift Forces on the Dam




Case 2: Head and Tail-water Horizontal Forces and Silt Forces on the Dam




Case 2: Head and Tail-water Vertical Forces on the Dam




Case 2: Uplift Forces on the Dam




Case 3: Head and Tail-water Horizontal Forces and Silt Forces on the Dam




Case 3: Head and Tail-water Vertical Forces on the Dam




Case 3: Uplift Forces on the Dam




Case 4: Head and Tail-water Horizontal Forces and Silt Forces on the Dam




Case 4: Head and Tail-water Vertical Forces on the Dam




Case 4: Uplift Forces on the Dam



Case 5: Head and Tail-water Horizontal Forces and Silt Forces on the Dam



Case 5: Head and Tail-water Vertical Forces on the Dam




Case 5: Uplift Forces on the Dam

Appendix B. Stability Calculations



JOB OF OF SHEET NO CALC BY CHECKED BY JMS DATE 10/6/21 DATE 4606900-211187.01 SCALE JOB NO.

Stability Analysis Summary - Kirkpatrick Dam **Loading Combinations** Case 8 Case IV Analysis Results



1. The corresponding tailwater levels were calculated based on the results of the dam failure analyses performed under Subtack 3 of the project proposal by Mead and Hunt and will be presented in its forthcoming report

Analysis Assumptions

- During the maximum flood elevation of 23.2, it is assumed the gates are fully opened and there is no resulting Invdrostatic force on them.
- The gales are assumed to be fully closed during cases II-V and the resulting hydrostatic forces are accounted for in 2) the calculations.
- During the site inspection, the sitt level could not be determined due to debris. For this analysis, it was assumed the silt layer elevation was to the tangent point on the Ogee Weir, NGVD29 EL 35
- Per the scope for the project, seismic and debris loads on the structure were not considered.
- To be conservative, a single bay was analyzed for stability utilizing its selfweight, the lateral earth pressures, and the aliding friction under its splikesy.
- The uplift pressure distribution was determined using Lane's weighted creep method accounting for both sheet pile 6) walls and the downstream apron.
- For loading case I where the gate fully open and the water is moving over the weir, the tailwater elevation was reduced to 60% of expected height for the horizontal force on the dam to account for Nappe forces per FERC Engineering Guidelines 3-2 3.2. The other load cases are assumed to have low/no flow and the Nappe forces can be ingomed per FERC Engineering Guidelines.
- The passive and active lateral earth pressures were only considered for the sliding analysis.

Section Geometry

Considering 1 Bay, see plan to 15 Base Length (B) = Width of Analysis (W) = Structure Height (H) =





Key Elevations

Plane of Analysis (overturning) = Plane of Analysis (sliding)



ked degrees

Multina

Active

degrees

Ib/ft^3 Al-Rest bdf

Top of Structure =

Material Property Assumptions

Cohesion (c) = y (Insyupa) 125-62.4= Km sand = $\tan^2\left(45 - \frac{6}{2}\right)$ $|Kp \text{ sand}| = \tan^2\left(45 + \frac{\theta}{3}\right)$ Φ_{υστ} = (Bouyant) y 110-62.4=

ice Expansion Load =





	-	Ŀ	oads				Forces	(Nips)	Arms (feet)	Morsen Lå,	(ft-kips)
Load Sun	nmary - Dam						i				
delicusions.	Conds (Still) Lord Conset						(+)	(+)		(1)	(1) 4
41	Description	Material	Unit Weight		Access!	Height/Length ft	THE REAL PROPERTY.	VEIL	150	1000	18.
1)	Service Sridge Pier	Concrete	0.15 0.15			200	19.24			1,000	100
3) 4)		Concrete	0.15 0.15		100	3	LANCE OF	862	8	318 a	200
5)	Service Bridge	Concrete	0.15		- 60	100			1000	124 S	
6) 7)		Concrete Concrete	0.15 0.15			100	1000	5.00	483	17.2	6.6
B)	Wallouray	Steel	2, assumed W	In44 bears	s. 4 et long	BEAM.		0.25	Jest =	450	(63)
Q)		Steel	2.5, 21WF62 a	nd) 2', 249AVF1	201, 40 feet long		289		313	200	E
fater Load	ls at 23.2' Headwater							and a	O.		2.5
HW S	Description HW on the Spitway	Material Water	Limit Weight 0.0024	Shape Trapezoid	- Hois	the Width Length	Mar.	390 a		1200	11/25
HW 2)	HW on the Pierwith the gate open	Water	0.0624	Triangle			533				
TW)		Water Water	0.0624	Triangle Rectangle	163		100	MES.	100 T		1980
H2)		Water	0.0624	LONGOUS SPINE		105XI	1.68	8.05	MEST		1000
H3)		Water	0.0824		- St. 16		180		2.3	THE REAL PROPERTY.	100
Uplift 1) Uplift 2)		Water	0.0024	Trapezoid			0.1	PALE		125	50 v
Nater Load	is at 20.0" Headwater								UTIES T		100
	Description	Material	Unit Weight	Shape	Heir	att Width Length	1937	100		温度	
HW)		Water	0.0624 0.0624	Triangle Triangle			R.T.	125	TO S	15.	TO I
Ht	Weight of water above Spilway from HW	Water	0.0824	Rectangle				1123.5			100
H2)		Water	0.0624			E E A A A A A A A A	May 1	12/2017		3500	120
Uplift 1)	Vertical Upfit cate. Weighted Creep				WAY	新 新州 · 高		1.57	100	RESEAR	1176
Up68 2)		Water	0.0824	Trapezoid			8 FL	755			
Nater Load	is at 18.0 Hisachrator							4			
F-MRIT	Description HWI with the gate closed	Material Water	Unit Weight 8.0624	Shape Triangle	DESCRIPTION OF THE PERSON NAMED IN	Width Land	0.00	1000	100		100
TW)) TW	Water	0.0624	Triangle			10000		150		50
148)		Water	D.0624	Rectangle	100 M		1000	2.01		SE	100.0
H2)		Water Water	0.0824		200		41000			121100	III.
Uplift. 1)	Vertical Uplift catc. Weighted Creep						1000	1200		10000	
Uplift 2)		Water	0.0624	Trapezoid			50.00	Mark 1	1530	400	ie18
Water Load	to at 16.0' Headwater					0:55W * 5: -3V		34			
HW		Water in	Unit Weight 0.0624	Shape Triangle			51 W			A COLUMN	
TW)		Water Water	0.0024	Triangle Rectangle				100	HEED	100	100.00
H2) Weight of water above Spilway from HW	Water	0.0824	T CC CHILL IGNIL	ESh N		60	100	ing t	8939	100
H3) Uplift 1)		Weter	0.0624		53		- ETER	M 200	11 000	10250	
Upiñ 2		Water	0.0824	Trapezoid				100	1	150	****
Water Load	fs. at 54.0" Headerster						100	144			
	Description	Material	Unit Weight	Shape	Hai	old Width Length	(Value		100		W
HW/		Water Water	0.0824	Triangle Triangle	(C)	10 2201	100	E-1648		18678	13
HE	Weight of water above Spilway from HW	Water	0.0624	Rectangle	207		PSSS U	rep.	الإخوا	信力的	1000
H2 H3) Weight of water above Spilway from TW	Water Water	0.0624		ESS 11		129/201	1994	PAGE	EAN)	100
Uplift 1 Uplift 2	Vertical Uplift calc. Weighted Creep	Water	0.0624	Trapezoid		is at	dia.	4000	(22)	525	10
	(Al Lord Cases)	- V madera	V.AndeT	· · ugrudAHil			3 T		631	BY	
	Description	Material	Unit Weight	Q.L.	-		1		1	1515	
Six	Sit build up - Lateral Earth Pressure	Site	0.0476	Triangle			70no	16.8		THE STATE OF	
Sit		Sit	0.0478	Rectangle	6		638		Fat		117
1	(Sliding Only)	Sand	0.0826	Triangle						1	E
Soil Loads Soil	 Passive Lateral Earth Pressure 	Sand	0.0826	Triangle Rectangle			0.27	15951			11.15
Sqil Sqil) Active Lateral Earth Pressure	Caret	14.94464	·	0.00		1000				1000
Sqif) Active Lateral Earth Pressure	Sandi									
Sail Sail) Active Lateral Earth Pressure	Sand			Lord Com I.		1,500	100	11/5	18.	DISE
Sal Sal Sal	Active Lateral Earth Pressure Weight of soil above Sliding plane	Sand			Load Case I -		120	1	1/5		
Sail Sail	Active Lateral Earth Pressure Weight of soil above Sliding plane	Sand			Load Case 8 - Load Case Ni Load Case N				12.0 W		10
Sail Sail Sail Load Summ	Active Lateral Earth Pressure Weight of soil above Sliding plane	Sand			Load Case 8 - Load Case 8 Load Case 6 Load Case V			热线	Total Control		
Sail Sail Sail Load Summ	Active Lateral Earth Pressure Weight of soil above Sliding plane weithout Uplift(Overturning)	Sand			Load Case 8 - Load Case 8i Load Case 6/ Load Case 7 Load Case 7 -						
Sail Sail Sail Sail	Active Lateral Earth Pressure Weight of soil above Sliding plane weithout Uplift(Overturning)	Sand			Load Case 8 - Load Case Ni Load Case N Load Case V Load Case I - Load Case 8 - Load Case 8 -			地震			
Sail Sail Sail Sail	Active Lateral Earth Pressure Weight of soil above Sliding plane weithout Uplift(Overturning)	Sand			Load Case 6 - Load Case Ni Load Case N Load Case I Load Case I Load Case I Load Case II Load Case Ni			· · · · · · · · · · · · · · · · · · ·	たなるがは	THE PERSON NAMED IN	
Sail Sail Sail Load Summ	ii) Active Lateral Earth Pressure iii) Weight of soil above Sliding plane many without Uplifft Overhaming) many without Uplifft (Sliding)	Sand			Load Case 8 - Load Case Ni Load Case N Load Case V Load Case I - Load Case 8 - Load Case 8 -			建筑线		がある。	
Soil Soil Soil Load Summ	ii) Active Lateral Earth Pressure iii) Weight of soil above Sliding plane many without Uplifft Overhaming) many without Uplifft (Sliding)	Sand			Load Case 6 - Load Case Ni Load Case N Load Case V Load Case I - Load Case II Load Case III Load Case IV Load Case V			· · · · · · · · · · · · · · · · · · ·	大学	がある。	
Soil Soil Soil Load Summ	ii) Active Lateral Earth Pressure iii) Weight of soil above Sliding plane many without Uplifft Overhaming) many without Uplifft (Sliding)	Samo			Load Case 8 - Load Case N Load Case N Load Case V Load Case 1 - Load Case 8 - Load Case 10 Load Case 10 Load Case N Load Case 6 - Load Case 6 - Load Case 8 - Load 8		是是是是	の大きな	の多数ない	一般 一	
Soil Soil Soil Load Summ	ii) Active Lateral Earth Pressure iii) Weight of soil above Sliding plane many without Uplifft Overhaming) many without Uplifft (Sliding)	Samo			Load Case 6 - Load Case Ni Load Case V Load Case I - Load Case I - Load Case II - Load Case IV Load Case V Load Case IV			· 人名 · · · · · · · · · · · · · · · · · ·	の名がある。	· · · · · · · · · · · · · · · · · · ·	地震 からままり



OF **JMS** DATE GAR DATE N/A JOB NO.

HWL =

Kirkpatrick Dam Assessment 10/6/21 10/12/21 4606900-211187.01

Load Case I

Analysis Paramaters:

Base Length (B) = Width of Analysis (W) =



feet

TWL =

feet feet

Load Summary:

	Forces			Moments
190	100	511		
(88)			8684 F	MARK TO THE REAL PROPERTY.
		8.5	528 H	

Area =

Calculate Base Pressures Without Uplift

Eccentricity:

 $\mu = (M_V + M_H) / V =$ e = B/2 - u = % Base = µ / B =



feet feet

Resultant falls within middle third of base, therefore O.K.

Uplift Pressures:

 $U_{u/s} =$ $U_{d/s} =$



ksf, see weighted creep uplift calculations ksf, see weighted creep uplift calculations

Base Pressures:

Pu/s = V/A * [1 - (6e/B)] = P_{d/a} = V/A * [1 + (6e/B)] =



> Uu/s, therefore O.K. ksf > Uu/s, therefore O.K. ksf

Calculate Base Pressures With Uplift

Eccentricity:

 $\mu = (M_V + M_H + M_U) / (V + U) =$ $e = B/2 - \mu =$ % Base = µ / B =



feet feet

Resultant falls within middle half of base, therefore O.K.

Base Pressures:

 $P_{u/v} = (V + U) / A * [1 - (6e/B)] =$ $P_{d/m} = (V + U) / A * [1 + (6e/B)] =$



ksf Compression ksf Compression

Sliding Stability

Verti	cal Loads	Horizontal Loads		
V =	kips	H=	kips	
U=	kips			

Shear Friction Factor = $[(V + U) \tan \Phi]/H =$



Where:

tanΦ =



4 OF JMS DATE GAR DATE N/A JOB NO.

Kirkpatrick Dam Assessment 10/6/21 10/12/21 4606900-211187.01

feet

feet

Load Case II

Analysis Paramaters:

Base Length (B) = Width of Analysis (W) =



feet feet Sf

HWL =

TWL =

Load Summary:

	orces	Mon	nents
V =	kips	M _√ =	ft-kips
H=	kips	M _H =	ft-kips
U =	kips	M _U =	ft-kips

Area =

Calculate Base Pressures Without Uplift

Eccentricity:

 $\mu = (M_V + M_H) / V =$ $e = 8/2 - \mu =$ % Base = $\mu / B =$



feet feet

Resultant falls within middle third of base, therefore O.K.

Uplift Pressures:

U_{u/s} = U_{d/a} =



ksf, see weighted creep uplift calculations ksf, see weighted creep uplift calculations

Base Pressures:

$$P_{u/s} = V/A * [1 - (6e/B)] = P_{d/s} = V/A * [1 + (6e/B)] =$$



> Uu/s, therefore O.K. ksf ksf > Uu/s, therefore O.K.

Calculate Base Pressures With Uplift

Eccentricity:

 $\mu = (M_V + M_H + M_U) / (V + U) =$

 $e = B/2 - \mu =$ % Base = μ / B =



feet feet

Resultant falls within middle half of base, therefore O.K.

Base Pressures:

 $P_{u/s} = (V + U) / A * [1 - (6e/B)] =$ $P_{d/e} = (V + U) / A * [1 + (6e/B)] =$



ksf Compression ksf Compression

Sliding Stability

Ve	rtical Loads	Horizontal Loads		
V =	kips	H =	kips	
U =	kips			

Shear Friction Factor = $[(V + U) \tan \Phi]/H =$



Where:

tanΦ =



5 OF JMS DATE GAR DATE N/A JOB NO.

HWL =

TWL =

 Kirkpatrick Dam Assessment

 OF
 7

 DATE
 10/6/21

 DATE
 10/12/21

 JOB NO.
 4606900-211187.01

Load Case III

Analysis Paramaters:

Base Length (B) = Width of Analysis (W) =



feet feet

Load Summary:

	Forces		oments
V =	kips	M _V =	ft-kips
H=	kips	M _H =	ft-kips
U =	kips	M _U =	ft-kips

Area =

Calculate Base Pressures Without Uplift

Eccentricity:

 $\mu = (M_V + M_H) / V =$ e = B/2 - μ = % Base = μ / B =



feet feet

Resultant falls within middle third of base, therefore O.K.

Uplift Pressures:

U_{u/s} = U_{d/s} =



ksf, see weighted creep uplift calculations ksf, see weighted creep uplift calculations

Base Pressures:

$$P_{u/s} = V/A \cdot [1 - (6e/B)] = P_{d/s} = V/A \cdot [1 + (6e/B)] =$$



ksf > Uu/s, therefore O.K. ksf > Ud/s, therefore O.K

Calculate Base Pressures With Uplift

Eccentricity:

 $\mu = (M_V + M_H + M_U) / (V + U) =$ $e = B/2 - \mu =$ % Base = $\mu / B =$



feet feet

Resultant falls within middle half of base, therefore O.K

Base Pressures:

$$P_{u/s} = (V + U) / A * [1 - (6e/B)] = P_{d/s} = (V + U) / A * [1 + (6e/B)] =$$



ksf Compression

Sliding Stability

Vertic	cal Loads	Horizontal Loads		
V =	kips	H=	kips	
U=	kips			

Shear Friction Factor = $[(V + U) \tan \Phi] / H =$



Where:

tanΦ =



6 OF JMS DATE GAR DATE N/A JOB NO.

HWL =

TWL =

Kirkpatrick Dam Assessment 10/6/21 10/12/21 4606900-211187.01

feet

feet

Load Case IV

Analysis Paramaters:

Base Length (B) = Width of Analysis (W) =

Агеа =



feet feet sf

Load Summary:

	orces	Me	oments
V =	kips	M _V =	ft-kips
H =	kips	M _{F0} =	ft-kips
U =	kips	Mu =	ft-kips

Calculate Base Pressures Without Uplift

Eccentricity:

 $\mu = (M_V + M_H) / V =$ $e = B/2 - \mu =$ % Base = µ / B =



feet feet

Resultant falls within middle third of base, therefore O.K.

Uplift Pressures:

U_{use} = U_{dfa} =



ksf, see weighted creep uplift calculations ksf, see weighted creep uplift calculations

Base Pressures:

$$P_{u/s} = V/A * [1 - (6e/B)] = P_{d/s} = V/A * [1 + (6e/B)] =$$



> Uu/s, therefore O.K. ksf ksf > Ud/s, therefore O.K.

Calculate Base Pressures With Uplift

Eccentricity:

 $\mu = (M_V + M_H + M_U) / (V + U) =$ e = 8/2 - µ =

% Base = µ / B =



feet feet

Resultant falls within middle half of base, therefore O.K.

Base Pressures:

 $P_{u/s} = (V + U) / A \times [1 - (6e/B)] =$ $P_{dh} = (V + U) / A * [1 + (6e/B)] =$



ksf Compression ksf Compression

Sliding Stability

	Vertical Loads		Horizontal Loads		
V =	kips	H=	kips		
U=	kips		-		

Shear Friction Factor = $[(V + U) \tan \Phi] / H =$



Where:

tanΦ =



OF JMS DATE GAR DATE JOB NO.

Kirkpatrick Dam Assessment

feet

feet

10/6/21 10/12/21 4606900-211187.01

Load Case V

Analysis Paramaters:

Base Length (B) = Width of Analysis (W) =

Area =



feet feet sf

N/A

HWL =

TWL =

Load Summary:

F	orces	M	oments
V =	kips	M _V =	ft-kips
Н=	kips	M _H =	ft-kips
U=	kips	M _U =	ft-kips

Calculate Base Pressures Without Uplift

Eccentricity:

 $\mu = (M_V + M_H) / V =$ $e = B/2 - \mu =$ % Base = µ / B =



feet feet

Resultant falls within middle third of base, therefore O.K.

Uplift Pressures:

 $U_{u/s} =$

U_{d/s} =



ksf, see weighted creep uplift calculations ksf, see weighted creep uplift calculations

Base Pressures:

 $P_{u/s} = V/A * [1 - (6e/B)] =$ P_{d/a} = V/A * [1 + (6e/B)] =



ksf > Uu/s, therefore O.K ksf > Ud/s, therefore O.K.

Calculate Base Pressures With Uplift

Eccentricity:

 $\mu = (M_V + M_H + M_U) / (V + U) =$

 $e = B/2 - \mu =$ % Base = $\mu / B =$



feet feet

Resultant falls within middle half of base, therefore O.K.

Base Pressures:

 $P_{u/s} = (V + U) / A * [1 - (6e/B)] =$ $P_{d/s} = (V + U) / A * [1 + (6e/B)] =$



ksf Compression ksf Compression

Sliding Stability

V	ertical Loads	Horizontal Loads		
V =	kips	H=	kips	
U =	kips			

Shear Friction Factor = [(V + U) tanΦ]/H=



Where:

tanΦ =

Appendix C. Weighted Creep Uplift Calculations



Job No. 46	06960-211187.01	Sheet	of _
Job Name	Kirkpatrick	Dym	Assess ment
Task	weighted Creek	uple	A Layout
Calculated by	JMS	_ Date _	7/28/21
Checked by		Date .	grave and the country of the country

(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)		
	自己 新港市	
医疗性 医自己联合性 医多克氏氏管		
多种性的 数型 医多种性性		
A. T.		
	经线束的证据	
TO THE PARTY OF THE PARTY OF THE PARTY.		
	1000年 1000年 1000年	



Kirkpatrick Dam Assessment S OF OF DATE 106/2021
S DATE 107/2021
R JOB NO. 466/8500-211187.01

JOB SHEET NO. CALCULATED BY: CHECKED BY: SCALE

od gringeël		Total Upliff (U) = Moment tor Uplift (M,) =	
fVn n n	Upliff Moment (Nip-ft)		(po)
	Moment Arm (feet)	id β	Mp-ft (about toe)
mt (G) = H / D _{me} = Neight of Woter = Base Length = Analysis Width =	Uplifit Force (kips)		
Hydrauffic Gradient (G) = H / D _{oc} = Unit Weight of Worker Base Length = Analysis Width =	Uplift Pressure	Total Upliff (U) =	Moment for Uplift (ML) =
Мубгаг	Total Head at Point Uplift Pressure		Moment
	H _{Pri}		
Weighted Creep Ratio (C.,) = Weighted Creep Distance (D.,.) = Headwelor Elevation = Teilweter Elevation = Net Yead (H) =	Creep Distance D = [D, J + D,*		
	Weighted Hortz, Dist, Creep Distance D ₁ = (1/3)*D ₂ D = [D ₁] + D ₂ .		
	Horizontal Distance D _h		
culation.	Elevation Change D,		
Joliff Cal	Distance rom Toe		
Weighted Creep Uplift Calculation Structure: Kringsinick Den Load Case: Gase I	Point Elevation Distance Change Change		
Weight	Point	@ D O D @ ← D C ← × ← E C	

kips kip-ft (about toe)

lipping point @:

Moment Upliff
Arm Moment
(feet) (kip-t)



2 OF DEPT ASSESSMENT S

2 OF DEPT S

3MS DATE 108/2021

GAR JOHN ASSESSMENT S

6AR JOHN ASSESSMENT S

MA JOB NO. 4866900-211187.01

JOB SMEET NO. CALCULATED BY. CHECKED BY. SCALE

iod Bujedin	Mor	Total uplift (u) =	
lva kei n	Upliff Noment (kip-ft)		ur toe)
	Moment Arm (feet)	S	Kipert (Boout toe)
rrt (G) = H / D _{sc} = Neight of Water = Base Length = Analysis Width =	Uplift Force (kips)		
Hydrauße Gradiert (6) = H / D _{me} = Unit Weight of Weter = Base Length = Analyais Wicth =	Uplift Pressure ksf	Total upith (U) =	Moment for Upitit (ML) =
Mydra	Total Head at Point Uplift Pressure H.** H _{0.11} = O _x = G*O ksf		Momen
	î		
Weighted Creep Ratio (C_s) = ghted Creep Distance (C_s,) = Headwater Elevation = Tailwater Elevation = Net Head (H) =	i 1		
Weighted Creep Ratio (C _w) = Weighted Creep Distance (O _w t) = Handwater Elevation = Tellwater Elevation = Net Head (H) =	Horizonial Weightad Horiz, Dist, Creep Distance Distance D _k = {1/3}*D _k D = [D _k + D _k ,		
	Horizontal Distance D.		
culation Jam	Elevation Change D.		
Weighted Creep Uplift Calculation Structure: Kitkpeirick Dem Load Gase: Case II			
ted Creep Uplift. Structure: Kirkpair Load Gase: Case II	Point Elevation Prom Toe		
Weights	Point	abone-er	


kip-ft (about toe)

Upping point (2):

Moment Upliff
Arm Moment
(feet) (Nip-ft)



sessment 5 10/6/2021 10/7/2021 4606900-211187.01	NA kcf a	Uplift Moment (Non-et)	
Kripatrick Dem Assessment OF DATE 1018 DATE 1058 JOB NO. 4606900.		Moment Arm (feet)	
DATE DATE DATE JOB NO.	Sradient (G) = H / D _{ec} = Unit Weight of Water = Base Length = Analysis Width =	Uplift Force (klps)	
S JMS GAR N/A	hydraullic Gradient (G) = H J D _{oc} = Unit Weight of Weter = Base Length = Analysis Width =	Uplift Pressure	
JOB SHEET NO. CALCULATED BY: CHECKED BY: SCALE	Hydr An	Total Head at Point	
		H _{bet})	
	Weighted Creep Ratio (C _w) = Weighted Creep Distance (D _{wc}) = Headwater Elevation = Tellwater Elevation = Net Head (H) =	Creep Distance	
	Weighted C Weighted Creep Head	Waighted Horiz, Dist. Greep Distance D ₁ = (1/3)*D ₂ O = [D ₁] + D ₁ .	
		Horizontal Distance D _a	
	Culation Dam	Elevation Change O.	
/ead -lunt	Weighted Creen Uplift Calculation Structure: Kintpatrick Dem Leed Cees: Case III	Point Elevation From Toe	
		Elevation	
2,8	Weigh	Point	8 D V D 0 - 05 E



kips kip-ft (about toe)

Total Uplitt (U) = Moment for Uplift (M.) =



JOB SHEET NO. CALCULATED BY. CHECKED BY: SCALE

niod Buddig	Arr Arr	Total upliff (U) = Moment for upliff (M _b) =
kef n	Upliff Moment (hip-ft)	(104)
	Moment Arm (feet)	kięs kięnt (about tos)
wrt (G) = N / D _{mc} = Neight of Water = Base Length = Analysis Width =	Upliff Force (kips)	Section 1
Hydraulle Gredient (G) = H / D.e. = Unit Weight of Weter = Base Length = Analysis Witth =	Uplift Pressure ksf	Total Upfit (U) = (Monent for Upfit (M.) =
	Total Head at Point H.= Harts • D. • G*D	Monten
	ĭ	
Weighted Creep Ratio (C.,) = Weighted Creep Distance (D.,) = Headwater Elevation = Tailwater Elevation = Net Head (H) =	Creep Distance 0 = [0,1 + 0,*	
	Weighted Hortz, Dist, Creep Distance D ₁ ' = (1/3)*D ₂ , D = [D ₁ + D ₂ '	
	Horizontal Distance D _h	
sulation am	Elevetion Change D.	
Joliff Cal		
Welshied Creep Uplift Calculation Structure: Kidpelrick Dam Loed Case: V	Elevation Distance From Toe	
Welahte S	Point	abobe- ac * = £c

kip-ft (about toe)

tispung point @. Moment Upliff
Arm Noment (test)



	od Bujedo)	¥ ¥	Total Uplift (U) = Moment for Uplift (M ₆) =	
Sessment 5 10/6/2021 10/7/2021 4608900_211187.01	th's	Moment Uplift Arm Moment (teet) (kip-ft)		kips kip-ft (about toe)
Kripatrick Dam Assessment OF DATE 10/8 DATE 10/8 DATE 10/8	Gradient (G) = H / D.c. = Unit Weight of Water = Base Length = Analysis Wicth =	Upliff Force (kips)		
JOB SHEET NO. 5 SH	Hydraulic Gradient (G) = H / D Unit Weight of Water = Base Length = Analysis Width =	Total Head at Point Uplift Pressure		Total Uplift (U) = Moment for Uplift (M _a) =
೪ ಹ ಶ ಶ ಜ	11111	ž.		
	Weighted Creep Ratio (C_,) = Weighted Creep Distance (O_x,) = Headwater Elevation = Tallwater Elevation = Tallwater Elevation =	Total Weighted Mortz, Dist, Creep Distance Distance Distance D. Ch. = (1/3)*D, D = [D.] + D.'.		
Mead Stiunt	Weighted Creen Unlift Calculation Structure: Kirkpairick Dem Load Case: Case V	Point Elevation Distance Change Distance Change Distance D. D. D.	a b o o o o o o o o o o o o o o o o o o	

tipping point @:
| Noment Upliff
Arm Moment
(feet) (kip-ty

kips kip-ft (about toe)